

2-47 ad

WRIGHT *Whirlwind* ENGINES

SERVICE BULLETINS

JANUARY, 1947



CONTENTS

Foreword

Numerical List of Active Service Bulletins

Alphabetical Index of Active Service Bulletins

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

WOOD-RIDGE, NEW JERSEY, U. S. A.

FOREWORD

The Service Bulletins contained in this set are prepared by the Wright Aeronautical Corporation for the use of operators of Wright Whirlwind engines. They supplement other publications by providing the most recent information necessary to keep these publications up to date. They also provide recent information necessary for engine modernization and table of limit values, the observance of which will assist in prolonging the serviceability of the engines and improve operation.

Among the many publications issued to the operator by the Wright Aeronautical Corporation are Overhaul Manuals, Service Manuals (Instruction Books), Parts Catalogs, and Tool Catalogs.

A numerical index and an alphabetical index of the active Whirlwind service bulletins are submitted herein for convenient reference. The numerical index will be revised every two months as scheduled below, through a supplement indicating new, revised, or cancelled bulletins. Both the numerical index and the alphabetical index will be reissued as changes warrant.

| | | | |
|---------|---|-----------|---|
| January | 1 | July | 1 |
| March | 1 | September | 1 |
| May | 1 | November | 1 |

NUMBERING SYSTEM

Bulletins are now numbered from No. 1 upward. Thus, the bulletins intended for this set are numbered "W-1," "W-2," etc. Prior to 1944, bulletins covering all Wright engines were published as one set and numbered in consecutive order of issuance up to No. 611. A complete set for Whirlwind engines consists, therefore, of bulletins under two numbering systems, as may be seen in the numerical index.

REVISIONS

Bulletins numbered under the former system will be reissued under the new system as revisions are published.

As bulletins of this new series are revised, they will be designated by a letter following the number of the bulletin, as "W-1A" ("A" indicating the first revision). Information of a later date supersedes and cancels all similar information that was released at a prior date.

NUMERICAL INDEX OF ACTIVE SERVICE BULLETINS

SERIES WHIRLWIND

This index indicates all the changes made in the set of Whirlwind Service Bulletins since the publication of the basic index dated January, 1947. A revised numerical index will be issued periodically, as indicated in the Foreword in the basic index, and should be used in conjunction with the alphabetical section of the Whirlwind Service Bulletin Index dated January, 1947.

January, 1947

Revised September 1, 1947

| No. | Title | No. | Title |
|---------------------|--|---------|---|
| W-1 | Pre-Oiling when Starting Engines | W-35A | Elastic Stop Nuts |
| W-2 | Profiling Cracked Cylinder Head Fins | W-36 | Ignition Manifold Drain Holes, Provision of |
| W-3A | Engine Starting Procedure | W-37 | Cleaning of Engine Parts |
| W-4A | Cold Weather Starting | W-38 | Carburetor Manufacturers' Bulletins |
| W-5 | Cylinder Hold-Down Studs, Location of | W-39 | Stamping Pistons for Identification |
| W-6 | Identification and Inspection of Steel Parts Treated to Eliminate Chafing | W-40 | Changes in Installation of Valve Guides |
| W-7 | Top Dead Center Indicator, Tool No. 80932 | W-41 | Testing of Spark Plugs |
| W-8B | Modification of Piston and Ring Assembly | W-42 | Reconditioning and Inspection of Valve Tappet and Guide |
| W-9 | Indicator Extension Arm for Measuring Propeller Shaft Run-Out | W-43 | Inspection of Intake Valves |
| W-10 | Cleaning Spark Plug Insert Threads | W-44 | Deviation in Carburetor Flow Bench Limit |
| W-11 | Cylinder Hold-Down Studs, Replacement of | W-45 | Identification and Matching of Valve Tappet Guide and Rollers |
| W-12E | Tables of Limits | W-46A | Procedure in Determining the Acceptability of Newly Developed and Improved Oils for Wright Aeronautical Corporation Engines |
| # W-13D | Approved Spark Plugs | W-47 | Salvaging of Service Assemblies |
| W-14 | Chrome Plating for Salvage | W-48 | Preparation of Engine for Operation after Storage |
| W-15A | Instructions for Acid Etching Parts | W-49 | Installation of Miscellaneous Clips and Brackets under Cylinder Hold-Down Nuts and Cap Screws, Avoidance of |
| # W-16A | Preparation of Engines for Storage or Shipment | W-50 | Replacement of Starter Shaft Oil Seal and Retainer |
| W-17A | Installation of Split Type Inner Race Thrust Bearing | W-51 | Installation of Eight-Ring Type Crankshaft Oil Seal |
| W-18 | Timing Serrations, Increased Diameter of | W-52 | Slot-Headed Plugs, Removal of |
| W-19 | Engine Driven Rocker Box Lubricator, Operation of | W-53 | Transfer of Engines from Surplus Stock to Licensed Operation |
| W-20 | Block Testing of Overhauled Engines | W-54 | Method of Selecting Oversize Wedge-Type Piston Rings |
| W-21 | Starter Drive Gear Bushing, Removal and Installation of | W-55 | Pre-Flight Ignition Check |
| W-22A | Excessive Engine Vibration, Prevention of | # W-56A | Anti-Friction Bearings, Service Limits for |
| W-23 | Propeller Shaft Thrust Bearing Nut, Limits for Reworking | W-57 | Spark Plugs, Installation Recommendations |
| W-24A | Replacement of Ignition Wire Ferrules with Washers | W-58 | Fuel, Use of Correct Octane |
| W-25A | Counterweight Stop, Rework to Permit Installation of Larger Counterweight Pins | W-59 | Valve Tappet Guide, Rework of Slot |
| W-26 | Prevention of Excessive Wear of the Accessory Drive Shaft Splines | W-60 | Reconditioning of Piston Ring Grooves |
| W-27 | Unauthorized Changes in Carburetor Settings | W-61 | Idle Mixture Setting, Adjustment of |
| W-28 | Cleaning of Master Rods | W-62 | Cylinders, Testing for Cracks or Leaks in |
| W-29A | Tapered Head Lock Screw For Valve Clearance Adjusting Screw | W-63 | Spacer, Crankshaft Front Main Bearing, Tin Plating of |
| W-30 | Piston Rings and Cylinder Barrels, Pre-Lubrication | W-64 | Crankshaft, Undercutting Threaded Section on Deflectors, Cylinder Head Alt, Cushioned Mounting For |
| W-31 | Protection of Cylinder Identification Numbers | W-65 | |
| W-32 | Inspection of Piston Pins | | |
| W-34 | Ordering of Tools | | |
| # Revised Bulletins | | | |

NUMERICAL INDEX—WHIRLWIND

The following bulletins have been dropped from the Numerical Index:

| No. | Title | Reason |
|-----|---|----------|
| 472 | Timken Rocker Arm Bearings, Mis-Matching of Rollers and Races | Obsolete |
| 482 | Oil Leakage, Standard Tachometer Drive Gear Housing | Obsolete |
| 497 | Carburetor Settings | Obsolete |
| 499 | Replacement of Whirlwind Cylinder Hold-Down Studs | Obsolete |
| 501 | Interference Between Valve Tapper Ball Socket and Guide | Obsolete |
| 503 | Reduction of Propeller Vibration and Stress | Obsolete |
| 519 | Change of Oil Pressure Marrings on Crankcase Front Section | Obsolete |
| 529 | Provision for Increased Hydro Oil Pressure | Obsolete |
| 539 | Installation of Crankcase Front Cover Spacer | Obsolete |
| 577 | Plug Type Piston Pin Retainers | Obsolete |
| 592 | Re-Design of Diffuser Section Oil Seal Ring | Obsolete |

40
2
3/16

NUMERICAL INDEX OF ACTIVE SERVICE BULLETINS

SERIES WHIRLWIND

This index indicates all the changes made in the set of Whirlwind Service Bulletins since the publication of the basic index dated January, 1947. A revised numerical index will be issued periodically, as indicated in the Foreword in the basic index, and should be used in conjunction with the alphabetical section of the Whirlwind Service Bulletin Index dated January, 1947.

January, 1947

Revised May, 1947

Revised Sept. 1, 1947

| No. | Title | No. | Title |
|---------------------|--|-------|---|
| 472 | Timken Rocker Arm Bearings, Mis-Matching of Rollers and Races | W-28 | Cleaning of Master Rods |
| 482 | Oil Leakage, Standard Tachometer Drive Gear Housing | W-29A | Tapered Head Lock Screw For Valve Clearance Adjusting Screw |
| 497 | Carburetor Settings | W-30 | Piston Rings and Cylinder Barrels, Pre-Lubrication of |
| 499 | Replacement of Whirlwind Cylinder Hold-Down Studs | W-31 | Protection of Cylinder Identification Numbers |
| 501 | Interference Between Valve Tappet Ball Socket and Guide | W-32 | Inspection of Piston Pins |
| 503 | Reduction of Propeller Vibration and Stress | W-34 | Ordering of Tools |
| 519 | Change of Oil Pressure Markings on Crankcase Front Section | W-35A | Elastic Stop Nuts |
| 529 | Provision for Increased Hydro-Oil Pressure | W-36 | Ignition Manifold Drain Holes, Provision of |
| 539 | Installation of Crankcase Front Cover Spacer | W-37 | Cleaning of Engine Parts |
| 577 | Plug Type Piston Pin Retainers | W-38 | Carburetor Manufacturers' Bulletins |
| 592 | Redesign of Diffuser Section Oil Seal Ring | W-39 | Stamping Pistons for Identification |
| W-1 | Pre-Oiling when Starting Engines | W-40 | Changes in Installation of Valve Guides |
| W-2 | Profiling Cracked Cylinder Head Fins | W-41 | Testing of Spark Plugs |
| W-3A | Engine Starting Procedure | W-42 | Reconditioning and Inspection of Valve Tappet and Guide |
| W-4A | Cold Weather Starting | W-43 | Inspection of Intake Valves |
| W-5 | Cylinder Hold-Down Studs, Location of | W-44 | Deviation in Carburetor Flow Bench Limit |
| W-6 | Identification and Inspection of Steel Parts Treated to Eliminate Chafing | W-45 | Identification and Matching of Valve Tappet Guide and Rollers |
| W-7 | Top Dead Center Indicator, Tool No. 80932 | W-46A | Procedure in Determining the Acceptability of Newly Developed and Improved Oils for Wright Aeronautical Corporation Engines |
| W-8B | Modification of Piston and Ring Assembly | W-47 | Salvaging of Service Assemblies |
| W-9 | Indicator Extension Arm for Measuring Propeller Shaft Run-Out | W-48 | Preparation of Engine for Operation after Storage |
| W-10 | Cleaning Spark Plug Insert Threads | W-49 | Installation of Miscellaneous Clips and Brackets under Cylinder Hold-Down Nuts and Cap Screws, Avoidance of |
| W-11 | Cylinder Hold-Down Studs, Replacement of | W-50 | Replacement of Starter Shaft Oil Seal and Retainer |
| W-12E | Table of Limits | W-51 | Installation of Eight-Ring Type Crankshaft Oil Seal |
| ≠ W-13D | Approved Spark Plugs | W-52 | Slot-Headed Plugs, Removal of |
| W-14 | Chrome Plating for Salvage | W-53 | Transfer of Engines from Surplus Stock to Licensed Operation |
| W-15A | Instructions for Acid Etching Parts | W-54 | Method of Selecting Oversize Wedge-Type Piston Rings |
| ≠ W-16A | Preparation of Engines for Storage or Shipment | W-55 | Pre-Flight Ignition Check |
| W-17A | Installation of Split Type Inner Race Thrust Bearing | W-56A | Anti-Friction Bearings, Service Limits for <i>5/20/47</i> |
| W-18 | Timing Serrations, Increased Diameter of | W-57 | Spark Plugs, Installation Recommendations |
| W-19 | Engine Driven Rocker Box Lubricator, Operation of | W-58 | Fuel, Use of Correct Octane |
| W-20 | Block Testing of Overhauled Engines | W-59 | Valve Tappet Guide, Rework of Slot |
| W-21 | Starter Drive Gear Bushing, Removal and Installation of | W-60 | Reconditioning of Piston Ring Grooves |
| W-22A | Excessive Engine Vibration, Prevention of | W-61 | Idle Mixture Setting, Adjustment of |
| W-23 | Propeller Shaft Thrust Bearing Nut, Limits for Reworking | W-62 | Cylinders, Testing for Cracks or Leaks in |
| W-24A | Replacement of Ignition Wire Ferrules with Washers | W-63 | Spacer, Crankshaft Front Main Bearing, Tin Plating of |
| W-25A | Counterweight Stop, Rework to Permit Installation of Larger Counterweight Pins | W-64 | Crankshaft, Undercutting Threaded Section on |
| W-26 | Prevention of Excessive Wear of the Accessory Drive Shaft Splines | W-65 | Deflectors, Cylinder Head Air, Cushioned Mounting For |
| W-27 | Unauthorized Changes in Carburetor Settings | W-66 | <i>Spark Plug Approval Procedure 6/15/43</i> |
| ≠ Revised Bulletins | | | |

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

WOOD-RIDGE, NEW JERSEY, U.S.A.

PRINTED
U.S.A.

NUMERICAL INDEX OF ACTIVE SERVICE BULLETINS

JANUARY, 1947

| No. | Title | No. | Title |
|-------|--|-------|---|
| 472 | Timken Rocker Arm Bearings, Mis-Matching of Rollers and Races | W-27 | Unauthorized Changes in Carburetor Settings |
| 482 | Oil Leakage, Standard Tachometer Drive Gear Housing | W-28 | Cleaning of Master Rods |
| 497 | Carburetor Settings | W-29A | Tapered Head Lock Screw For Valve Clearance Adjusting Screw |
| 499 | Replacement of Whirlwind Cylinder Hold-Down Studs | W-30 | Piston Rings and Cylinder Barrels, Pre-Lubrication of |
| 501 | Interference Between Valve Tappet Ball Socket and Guide | W-31 | Protection of Cylinder Identification Numbers |
| 503 | Reduction of Propeller Vibration and Stress | W-32 | Inspection of Piston Pins |
| 519 | Change of Oil Pressure Markings on Crankcase Front Section | W-34 | Ordering of Tools |
| 529 | Provision for Increased Hydro-Oil Pressure | W-35A | Elastic Stop Nuts |
| 539 | Installation of Crankcase Front Cover Spacer | W-36 | Ignition Manifold Drain Holes, Provision of |
| 577 | Plug Type Piston Pin Retainers | W-37 | Cleaning of Engine Parts |
| 592 | Redesign of Diffuser Section Oil Seal Ring | W-38 | Carburetor Manufacturers' Bulletins |
| W-1 | Pre-Oiling when Starting Engines | W-39 | Stamping Pistons for Identification |
| W-2 | Profiling Cracked Cylinder Head Fins | W-40 | Changes in Installation of Valve Guides |
| W-3A | Engine Starting Procedure | W-41 | Testing of Spark Plugs |
| W-4A | Cold Weather Starting | W-42 | Reconditioning and Inspection of Valve Tappet and Guide |
| W-5 | Cylinder Hold-Down Studs, Location of | W-43 | Inspection of Intake Valves |
| W-6 | Identification and Inspection of Steel Parts Treated to Eliminate Chafing | W-44 | Deviation in Carburetor Flow Bench Limit |
| W-7 | Top Dead Center Indicator, Tool No. 80932 | W-45 | Identification and Marking of Valve Tappet Guide and Rollers |
| W-8B | Modification of Piston and Ring Assembly | W-46A | Procedure in Determining the Acceptability of Newly Developed and Improved Oils for Wright Aeronautical Corporation Engines |
| W-9 | Indicator Extension Arm for Measuring Propeller Shaft Run-Out | W-47 | Salvaging of Service Assemblies |
| W-10 | Cleaning Spark Plug Insert Threads | W-48 | Preparation of Engine for Operation after Storage |
| W-11 | Cylinder Hold-Down Studs, Replacement of | W-49 | Installation of Miscellaneous Clips and Brackets under Cylinder Hold-Down Nuts and Cap Screws, Avoidance of |
| W-12E | Table of Limits | W-50 | Replacement of Starter Shaft Oil Seal and Retainer |
| W-13C | Approved Spark Plugs | W-51 | Installation of Eight-Ring Type Crankshaft Oil Seal |
| W-14 | Chrome Plating for Salvage | W-52 | Slot-Headed Plugs, Removal of |
| W-15A | Instructions for Acid Etching Parts | W-53 | Transfer of Engines from Surplus Stock to Licensed Operation |
| W-16 | Preparation of Engines for Storage or Shipment | W-54 | Method of Selecting Oversize Wedge-Type Piston Rings |
| W-17A | Installation of Split Type Inner Race Thrust Bearing | W-55 | Pre-Flight Ignition Check |
| W-18 | Timing Serrations, Increased Diameter of | W-56 | Anti-Friction Bearings, Service Limits for |
| W-19 | Engine Driven Rocker Box Lubricator, Operation of | W-57 | Spark Plugs, Installation Recommendations |
| W-20 | Block Testing of Overhauled Engines | W-58 | Fuel, Use of Correct Octane |
| W-21 | Starter Drive Gear Bushing, Removal and Installation of | W-59 | Valve Tappet Guide, Rework of Slot |
| W-22A | Excessive Engine Vibration, Prevention of | W-60 | Reconditioning of Piston Ring Grooves |
| W-23 | Propeller Shaft Thrust Bearing Nut, Limits for Reworking | W-61 | Idle Mixture Setting, Adjustment of |
| W-24A | Replacement of Ignition Wire Ferrules with Washers | W-62 | Cylinders, Testing for Cracks or Leaks in |
| W-25A | Counterweight Stop, Rework to Permit Installation of Larger Counterweight Pins | W-63 | Spacer, Crankshaft Front Main Bearing, Tin Plating of |
| W-26 | Prevention of Excessive Wear of the Accessory Drive Shaft Splines | W-64 | Crankshaft, Undercutting Threaded Section on Deflectors, Cylinder Head Air, Cushioned Mounting For |
| | | W-65 | |

This index supersedes the one issued in November, 1946, and is corrected to include the changes listed below:

The following bulletin was superseded as indicated:

Old No. W-13B

New No. W-13C

ALPHABETICAL INDEX OF ACTIVE SERVICE BULLETINS

JANUARY, 1947

A

Accessory Drive Shaft Splines, Prevention of Excessive
Wear of W-26
Acid Etching Parts, Instructions for W-15A
Adjusting Screw, Valve Clearance, Tapered Head Lock
Screw for W-29A
Adjustment of Idle Mixture Setting W-61
Air Deflectors, Cylinder Head, Cushioned Mounting
for W-65
Anti-Friction Bearings, Service Limits for W-56
Approved Spark Plugs W-13C
Arm, Indicator Extension, for Measuring Propeller
Shaft Run-Out W-9
Assemblies, Service, Salvaging of W-47
Assembly, Crankshaft Breather Plug, Changes in 459
Assembly, Piston and Ring, Modification of W-8B
Assembly, Radio-Shielded Standard Ignition Manifold,
Replacement of Ignition Cable in 399
Avoidance of Installation of Miscellaneous Clips and
Brackets under Cylinder Hold-Down Nuts and
Cap Screws W-49

B

Barrels, Cylinder, and Piston Rings, Pre-Lubrication of W-30
Bearing Nut, Propeller Shaft Thrust, Limits for Re-
working W-23
Bearing Spacer, Crankshaft Front Main, Tin Plating of W-63
Bearings, Anti-Friction, Service Limits for W-56
Bearings, Timken Rocker Arm, Mis-Matching of Roll-
ers and Noses 472
Bearing, Thrust, Split Type Inner Race, Installation of W-17A
Block Testing of Overhauled Engines W-20
Brackets and Clips, Miscellaneous, Installation of under
Cylinder Hold-Down Nuts and Cap Screws,
Avoidance of W-49
Bushing, Starter Drive Gear, Removal and Installation
of W-21

C

Carburetor Flow Bench Limit, Deviation in W-44
Carburetor Manufacturers' Bulletins W-38
Carburetor Settings 497
Carburetor Settings, Unauthorized Changes in W-27
Chafing, Steel Parts Treated to Eliminate, Identification
and Inspection of W-6
Change of Oil Pressure Markings on Crankcase Front
Section 519
Changes in Carburetor Settings, Unauthorized W-27
Changes in Installation of Valve Guides W-40
Chrome Plating for Salvage W-14
Cleaning of Engine Parts W-37
Cleaning of Master Rods W-28
Cleaning Spark Plug Insert Threads W-10
Clips and Brackets, Miscellaneous, Installation of under
Cylinder Hold-Down Nuts and Cap Screws,
Avoidance of W-49
Cold Weather Starting W-4A

Counterweight Stop, Rework to Permit Installation of
Larger Counterweight Pins W-25
Cracked Cylinder Head Fins, Profiling of W-2
Cracks or Leaks in Cylinders, Testing for W-62
Crankcase Front Cover, Spacer, Installation of 539
Crankcase Front Section, Change of Oil Pressure Mark-
ings on 519
Crankshaft Front Main Bearing Spacer, Tin Plating of W-63
Crankshaft Oil Seal, Eight-Ring Type, Installation of W-51
Crankshafts, Undercutting Threaded Section on W-64
Cushioned Mounting for Cylinder Head Air Deflectors W-65
Cylinder Barrels and Piston Rings, Pre-Lubrication of W-30
Cylinder Head Air Deflectors, Cushioned Mounting for W-65
Cylinder Head Fins, Cracked, Profiling of W-2
Cylinder Hold-Down Studs, Location of W-5
Cylinder Hold-Down Studs, Replacement of W-11
Cylinder Hold-Down Studs, Whirlwind, Replacement
of 499
Cylinder Identification Numbers, Protection of W-31
Cylinders, Testing for Cracks or Leaks in W-62

D

Deflectors, Cylinder Head Air, Cushioned Mounting
for W-65
Deviation in Carburetor Flow Bench Limit W-44
Diffuser Section Oil Seal Ring, Redesign of 592
Drain Hole, Ignition Manifold, Provision of W-36

E

Eight-Ring Type Crankshaft Oil Seal, Installation of W-51
Elastic Stop Nuts W-35A
Engines for Operation after Storage, Preparation of W-48
Engines from Surplus Stock to Licensed Operation,
Transfer of W-53
Engines, Overhauled, Block Testing of W-20
Engines, Pre-Oiling when Starting W-1
Engines, Preparation of for Storage or Shipment W-16
Engine Driven Rocker Box Lubricator, Operation of W-19
Engine Parts, Cleaning of W-37
Engine Starting Procedure W-3A
Engines, Wright Aeronautical Corporation, Procedure
in Determining the Acceptability of Newly Devel-
oped and Improved Oils for W-46A
Etching, Acid, of Parts, Instructions for W-15A
Excessive Engine Vibration, Prevention of W-22A
Excessive Wear of the Accessory Drive Shaft Splines,
Prevention of W-26
Extension Arm, Indicator, for Measuring Propeller Shaft
Run-Out W-9

F

Ferrules, Ignition Wire, Replacement of with Washers W-24
Fins, Cylinder Head, Cracked, Profiling of W-2
Flow Bench Limit, Carburetor, Deviation in W-44
Front Cover Spacer, Crankcase, Installation of 539
Front Section, Crankcase, Change of Oil Pressure
Markings on 519
Fuel, Use of Correct Octane W-58

- O**
- Grooves, Piston Ring, Reconditioning of.....W-60
 Guide, Valve, and Tappet Ball Socket, Interference
 Between 501
 Guide, Valve, Tappet and Rollers, Identification and
 Matching of.....W-45
 Guide, Valve Tappet, Rework of Slot.....W-59
- H**
- Hold-Down Studs, Cylinder, Location of..... W-5
 Hold-Down Studs, Cylinder, Replacement of.....W-11
 Hold-Down Studs, Whirlwind Cylinder, Replacement
 of 499
 Housing, Standard Tachometer Drive Gear, Oil Leak-
 age 482
 Hydro-Oil Pressure, Increased, Provision for..... 529
- I**
- Identification and Inspection of Steel Parts Treated to
 Eliminate Chafing W-6
 Identification and Matching of Valve Tappet, Guide,
 and Rollers.....W-45
 Identification Numbers, Cylinder, Protection of.....W-31
 Identification, Stamping Pistons for..... W-39
 Idle Mixture Setting, Adjustment of.....W-61
 Ignition Check, Pre-Flight.....W-55
 Ignition Manifold Drain Hole, Provision of.....W-36
 Ignition Wire Ferrules, Replacement of with Washers..W-24
 Impeller Recommendations, Supercharger..... 413
 Improved and Newly Developed Oils for Wright
 Aeronautical Corporation Engines, Procedure in
 Determining the Acceptability of.....W-46A
 Increased Diameter of Timing Serrations.....W-18
 Increased Hydro-Oil Pressure, Provision for..... 529
 Indicator Extension Arm for Measuring Propeller Shaft
 Run-Out W-9
 Indicator, Top Dead Center, Tool No. 80932..... W-7
 Insert Threads, Spark Plug, Cleaning.....W-10
 Inspection and Identification of Steel Parts Treated to
 Eliminate Chafing W-6
 Inspection of Intake Valves W-43
 Inspection of Piston Pins.....W-32
 Inspection and Reconditioning of Valve Tappet and
 Guide.....W-42
 Installation of Crankcase Front Cover Spacer..... 539
 Installation of Eight-Ring Type Crankshaft Oil Seal...W-51
 Installation of Larger Counterweight Pins, Rework of
 Counterweight Stop to Permit.....W-25
 Installation of Miscellaneous Clips and Brackets under
 Cylinder Hold-Down Nuts and Cap Screws,
 Avoidance of.....W-49
 Installation Recommendations, Spark Plugs.....W-57
 Installation and Removal of Starter Drive Gear Bush-
 ing W-21
 Installation of Split Type Inner Race Thrust Bearing W-17A
 Installation of Valve Guides, Changes in..... W-40
 Instructions for Acid Etching Parts..... W-15A
 Intake Valves, Inspection of.....W-43
 Interference Between Valve Tappet Ball Socket and
 Guide 501
- L**
- Leakage, Oil, Standard Tachometer Drive Gear Hous-
 ing 432
 Leaks or Cracks in Cylinders, Testing for.....W-62
 Limits for Reworking Propeller Shaft Thrust Bearing
 NutW-23
 Location of Cylinder Hold-Down Studs..... W-5
 Lock Screw, Tapered Head for Valve Clearance Ad-
 justing ScrewW-29A
 Lubricator, Rocker Box, Engine Driven, Operation of..W-19
- M**
- Markings on Crankcase Front Section, Change of Oil
 Pressure 519
 Master Rods, Cleaning of.....W-23
 Measuring Propeller Shaft Run-Out, Indicator Exten-
 sion Arm for..... W-9
 Method of Selecting Oversize Wedge-Type Piston
 RingsW-54
 Mis-Matching of Rollers and Races, Timken Rocker
 Arm Bearings 472
 Mixture Setting, Idle, Adjustment of.....W-61
 Modification of Piston and Ring Assembly.....W-8B
- N**
- Newly Developed and Improved Oils for Wright
 Aeronautical Corporation Engines, Procedure in
 Determining the Acceptability of.....W-46A
 Numbers, Cylinder Identification, Protection of.....W-31
- O**
- Octane Fuel, Use of Correct.....W-58
 Oil Leakage, Standard Tachometer Drive Gear Housing 482
 Oil Pressure, Increased Hydro, Provision for 529
 Oil Seal, Crankshaft, Eight-Ring Type, Installation of..W-51
 Oil Seal Ring, Diffuser Section, Redesign of..... 592
 Oil Seal, Starter Shaft, and Retainer, Replacement of..W-50
 Oils, Newly Developed and Improved for Wright
 Aeronautical Corporation Engines, Procedure in
 Determining the Acceptability of.....W-46A
 Operation after Storage, Preparation of Engines for...W-48
 Operation of Engine Driven Rocker Box Lubricator.....W-19
 Ordering of Tools.....W-34
 Overhauled Engines, Block Testing ofW-20
 Oversize Wedge-Type Piston Rings, Method of Select-
 ing W-54
- P**
- Parts, Acid Etching, Instructions for.....W-15A
 Parts, Steel, Treated to Eliminate Chafing, Identifica-
 tion and Inspection of..... W-6
 Pins, Counterweight, Installation of Larger, Rework of
 Counterweight Stops to Permit.....W-25
 Piston Pins, Inspection of.....W-32
 Piston Pin Retainers, Plug Type..... 577
 Piston and Ring Assembly, Modification of.....W-8B
 Piston Ring Grooves, Reconditioning of.....W-60
 Piston Rings and Cylinder Barrels, Pre-Lubrication of..W-30
 Piston Rings, Oversize Wedge-Type, Method of Select-
 ing W-54
 Pistons, Stamping for Identification..... W-39
 Plating, Chrome, for SalvageW-14
 Plating, Tin, of Crankshaft Front Main Bearing Spacer..W-63
 Plug, Spark, Insert Threads, CleaningW-10
 Plugs, Slot-Headed, Removal of.....W-52

Plugs, Spark, Approved.....W-13B
 Plug Type Piston Pin Retainers..... 577
 Pre-Flight Ignition Check.....W-55
 Pre-Lubrication of Piston Rings and Cylinder Barrels.....W-30
 Pre-Oiling when Starting Engines.....W-1
 Preparation of Engines for Operation after Storage.....W-48
 Preparation of Engines for Storage or Shipment.....W-16
 Pressure, Increased Hydro-Oil, Provision for..... 529
 Prevention of Excessive Engine Vibration.....W-22A
 Prevention of Excessive Wear of the Accessory Drive
 Shaft Splines.....W-26
 Procedure, Engine Starting.....W-3A
 Procedure in Determining the Acceptability of Newly
 Developed and Improved Oils for Wright Aero-
 nautical Corporation Engines.....W-46A
 Profiling Cracked Cylinder Head Fins.....W-2
 Propeller Shaft Run-Out, Indicator Extension Arm for
 Measuring.....W-9
 Propeller Shaft Thrust Bearing Nut, Limits for Re-
 working.....W-23
 Propeller Vibration and Stress, Reduction of..... 503
 Protection of Cylinder Identification Numbers.....W-31
 Provision of Ignition Manifold Drain Hole.....W-36
 Provision for Increased Hydro-Oil Pressure..... 529

R

Reconditioning and Inspection of Valve Tappet and
 Guide.....W-42
 Reconditioning of Piston Ring Grooves.....W-60
 Redesign of Diffuser Section Oil Seal Ring..... 592
 Reduction of Propeller Vibration and Stress..... 503
 Removal and Installation of the Starter Drive Gear
 Bushing.....W-21
 Removal of Slot-Headed Plugs.....W-52
 Replacement of Cylinder Hold-Down Studs.....W-11
 Replacement of Ignition Wire Ferrules with Washers.....W-24
 Replacement of Starter Shaft Oil Seal and Retainer.....W-50
 Replacement of Whirlwind Cylinder Hold-Down
 Studs..... 499
 Retainers, Piston Pin, Plug Type..... 577
 Retainer, and Starter Shaft Oil Seal, Replacement of.....W-50
 Rework of Counterweight Stop to Permit Installation
 of Larger Counterweight Pins.....W-25
 Rework of Valve Tappet Guide Slot.....W-59
 Reworking Propeller Shaft Thrust Bearing Nut, Limits
 for.....W-23
 Ring, Diffuser Section Oil Seal, Redesign of..... 592
 Ring and Piston Assembly, Modification of.....W-8B
 Rings, Piston, and Cylinder Barrels, Pre-Lubrication of.....W-30
 Rings, Piston, Oversize Wedge-Type, Method of Se-
 lecting.....W-54
 Rocker Arm Bearings, Timken, Mis-Matching of Roll-
 ers and Races..... 472
 Rocker Box Lubricator, Engine Driven, Operation of.....W-19
 Rollers, Valve, Tappet and Guide, Identification and
 Matching of.....W-45
 Run-Out, Propeller Shaft, Indicator Extension Arm
 for Measuring.....W-9

S

Salvage, Chrome Plating for.....W-14
 Salvaging of Service Assemblies.....W-47A

Seal, Starter Shaft Oil, and Retainer, Replacement of.....W-50
 Section, Crankcase Front, Change of Oil Pressure
 Markings on..... 519
 Selecting Oversize Wedge-Type Piston Rings, Method
 of.....W-54
 Serrations, Timing, Increased Diameter of.....W-13
 Service Assemblies, Salvaging of.....W-47
 Service Limits for Anti-Friction Bearings.....W-56
 Setting, Idle Mixture, Adjustment of.....W-61
 Settings, Carburetor..... 497
 Settings, Carburetor, Unauthorized Changes in..... 449
 Shaft, Propeller, Indicator Extension Arm for Measur-
 ing Run-Out.....W-9
 Shipment or Storage, Preparation of Engines for.....W-16
 Slot-Headed Plugs, Removal of.....W-52
 Socket, Valve, Tappet Ball, and Guide, Interference
 Between..... 501
 Spacer, Crankcase Front Cover, Installation of..... 539
 Spacer, Crankshaft Front Main Bearing, Tin Plating of.....W-63
 Spark Plug Insert Threads, Cleaning.....W-10
 Spark Plugs, Approved.....W-13B
 Spark Plugs, Installation Recommendations.....W-57
 Spark Plugs, Testing of.....W-41
 Splines, Accessory Drive Shaft, Prevention of Excessive
 Wear of.....W-26
 Split Type Inner Race Thrust Bearing, Installation of.....W-17A
 Stamping Pistons for Identification.....W-39
 Standard Tachometer Drive Gear Housing, Oil Leak-
 age..... 482
 Starter Drive Gear Bushing, Removal and Installation
 of.....W-21
 Starter Shaft Oil Seal and Retainer, Replacement of.....W-50
 Starting, Cold Weather.....W-4A
 Starting Engines, Pre-Oiling when.....W-1
 Starting Procedure, Engine.....W-3A
 Steel Parts Treated to Eliminate Chafing, Identification
 and Inspection of.....W-5
 Stop Nut, Elastic.....W-33A
 Storage or Shipment, Preparation of Engines for.....W-16
 Storage, Preparation of Engines for Operation after.....W-48
 Stress and Vibration, Propeller, Reduction of..... 503
 Studs, Cylinder Hold-Down, Location of.....W-5
 Studs, Cylinder Hold-Down, Replacement of.....W-11
 Studs, Whirlwind Cylinder Hold-Down Replacement
 of..... 499

T

Tables of Limits.....W-12E
 Tachometer Drive Gear Housing, Standard, Oil Leak-
 age..... 482
 Tapered Head Lock Screw for Valve Clearance Adjust-
 ing Screw.....W-29A
 Tappet Guide, Valve, Rework of Slot.....W-59
 Tappets, Valve, Guides and Rollers, Identification and
 Matching of.....W-45
 Tappet, Valve, Ball Socket and Guide, Interference
 Between..... 501
 Testing for Cracks or Leaks in Cylinders.....W-62
 Testing of Spark Plugs.....W-41
 Threaded Section on Crankshafts, Undercutting.....W-64
 Threads, Spark Plug Insert, Cleaning.....W-10
 Thrust Bearing Nut, Propeller Shaft, Limits for Re-
 working.....W-23
 Thrust Bearing, Split Type Inner Race, Installation of.....W-17A

Timing Serrations, Increased Diameter of.....W-18
 Timken Rocker Arm Bearings, Mis-Matching of Roll-
 ers and Races 472
 Tin Plating of Crankshaft Front Main Bearing Spacer..W-63
 Tools, Ordering ofW-34
 Top Dead Center Indicator, Tool No. 80932..... W-7
 Transfer of Engines from Surplus Stock to Licensed
 OperationW-53

U

Unauthorized Changes in Carburetor Settings.....W-27
 Undercutting Threaded Section on Crankshafts..... W-64

V

Valve Clearance Adjusting Screw, Tapered Head Lock
 Screw forW-29A
 Valve Guides, Changes in Installation of..... W-40

Valves, Intake, Inspection of..... W-43
 Valve Tappet Ball Socket and Guide, Interference Be-
 tween 501
 Valve Tappet and Guide, Inspection and Recondition-
 ing of W-42
 Valve Tappet Guide, Rework of Slot.....W-59
 Valve Tappets, Guides, and Rollers, Identification and
 Matching of W-45
 Vibration, Engine, Excessive, Prevention of.....W-22A
 Vibration and Stress, Propeller, Reduction of..... 503

W

Wear of the Accessory Drive Shaft Splines, Excessive,
 Prevention ofW-26
 Wedge-Type Piston Rings, Oversize, Method of Select-
 ingW-54
 Wire Ferrules, Ignition, Replacement of with Washers..W-24

SERVICE BULLETIN NO. 482

SUBJECT: Oil Leakage, Standard Tachometer Drive Gear Housing

MODELS: Whirlwind 7 and 9 Series Engines

An investigation of reported oil leakage at the tachometer drive gear housing location of the above Whirlwinds has disclosed the following:

Oil leakage at this location is apparently caused by improper assembly of the dual tachometer drive gear and shaft assemblies. The tachometer drive gear and shaft assemblies, Part Nos. 411947 and 411948, incorporate sleeves in which are milled spiral oil grooves. During normal operation and when properly assembled, the tachometer drive gears rotate in opposite directions to each other and the spiral oil grooves are milled in such a direction that during rotation the oil is forced into the interior of the tachometer drive gear housing. However, interchanging the drive gears reverses the direction of the spiral oil grooves and tends to force the oil out of the tachometer drive gear shaft housing and results in oil leakage.

To facilitate proper assembly of the tachometer drive gears, the upper tachometer drive gear of current production Whirlwinds is marked with an ellipse. The ellipse is acid-etched on the 9/16 inch diameter shoulder near the gear end of the assembly.

It is recommended that all operators of Whirlwinds incorporating the standard tachometer drive gear assembly acid etch an ellipse on the upper drive gear to prevent improper assembly and resultant oil leakage. Etching should be done in accordance with existing instructions.

To determine the proper drive gear assembly for installation in the upper location, make the following check:

Select one of the drive gears and while facing the gear end rotate it in a counter-clockwise direction. The spiral oil groove milled in the shaft of the drive gear assembly, Part No. 411947, that should be located in the upper position, will run in toward the gear end of the assembly. If this condition is not encountered, select the remaining drive gear and repeat the check.

Etch mark and install the drive gear with the spiral oil groove running in toward the gear end in the upper position. The assembly, Part No. 411948, with the oil groove running out from the gear end, as determined from the above check, is installed in the lower position.

Service Division
Wright Aeronautical Corporation
September 11, 1941

SERVICE BULLETIN NO. 472

SUBJECT: Timken Rocker Arm Bearings, Mis-matching of Rollers and Races

MODELS: All

This bulletin applies to all engines incorporating a roller type rocker arm bearing.

Some cases of bearing rejection have been traced to mis-matched rollers and races during reassembly of rocker arm roller bearings after disassembly for inspection and cleaning.

Since the rollers and races are assembled with selective fits, it is recommended that the rollers and outer races of each side of the bearing be placed in separate cloth bags or other suitable separate containers at disassembly. These selective fits require that extreme care be taken to reassemble the sets of rollers with the same races from which they were removed.

Wright Aeronautical Corporation
(A Division of Curtiss-Wright Corporation)
Paterson, New Jersey, U.S.A.
June 30, 1941

Printed in U.S.A.

Model NA-R9 carburetors having setting number 27225, for pressure feed, or 29041, for gravity feed, used on Whirlwind R-975 E and R-975 E-1 engines should have the economizer timing adjusted to 28° throttle opening. Instructions relative to adjusting the economizer timing are given in the last paragraph of this bulletin. Stamp change letter "K" next to the setting number on the flange of carburetors having setting number 27225 and change letter "B" on carburetors having setting number 29041. Some of the early carburetors with setting number 27225 will not have this number stamped on the flange. However, they may be identified by the setting stamped on the data plate which is as follows:

| | | | |
|----------|-------|-------------|------------|
| Model | NA-R9 | Float Level | 3/4 B.P.S. |
| Main | #25 | Econom. | #55 |
| Idle Jet | #50 | Venturi | 2 7/16" |
| I.A.B. | #48 | M.A.B. | #55 |

Model NA-R9A carburetors having setting number 63444 used on Whirlwind R975 E-2 and R975 E-3 engines should be modified as follows: Change the #25 main metering jet to a #26 jet. Change the #48 economizer metering jet to a #43 jet. Change the idle air bleed from a #50 to a #60 bleed and change the idle discharge orifice from a #44 to a #60-70-60-56. This will also require replacing the throttle valves with the 18° mill type. Adjust the economizer timing to 33° throttle opening. Instructions relative to adjusting the economizer timing are given in the last paragraph of this bulletin. Stamp change letter "H" next to the setting number on the flange, and change the setting on the data plate to agree with the modifications made in the economizer and main metering systems.

Model NA-R9A carburetors having setting number 64498 used on Whirlwind R975 E-2 and R975 E-3 engines should have the economizer timing adjusted to 28° throttle opening. The idle air bleed should be changed from a #50 to a #60 bleed. The idle discharge orifice should be changed from a #44 to a #60-70-60-56 and the throttle valves replaced with the 18° mill type. Instructions relative to adjusting the economizer timing are given in the last paragraph of this bulletin. Stamp change letter "D" next to the setting number on the flange.

Model NA-R9A carburetors having setting number 112166 used on Whirlwind R975 E-3 engines should have the following modifications incorporated. Change the #25 main metering jet to a #26 jet. Change the #48 economizer metering jet to a #43 jet. Adjust the economizer timing to 33° throttle opening. Instructions relative to adjusting the economizer timing are given in the last paragraph of this bulletin. Stamp change letter "A" next to the setting number on the flange and change the setting on the data plate to agree with the modifications made in the economizer and main metering systems.

It should be noted that operating fuel pressure for gravity feed carburetor settings is 1/2 lbs. per square inch plus 1.0 lbs., minus 0 lbs. When checking the fuel level of gravity feed carburetors 1 1/2 lbs. fuel pressure should be maintained and the fuel level held at 3/4 inch below parting surface.

To adjust the economizer timing proceed as follows: Check the tapered pins which locate the economizer valve actuating lever on the left end of the throttle shaft and the throttle stop lever on the right end to see that they are tight in the levers and the shaft. Back off the throttle adjusting stop screw so that the throttle valve may be completely closed. Assemble a protractor graduated in one degree units on the throttle shaft at the throttle control lever. A suitable protractor may be procured commercially and an extension should be either riveted or soldered at the axis to permit drilling a 5/16 inch diameter hole at the axis. A protractor designed for this purpose may be procured from the Bendix Products Corporation. Attach a pointer to the carburetor body. With the throttle fully closed, set the pointer to indicate zero on the protractor. The upper end of the economizer valve needle is threaded and protrudes through the cover of the carburetor body on the left of the throttle body. The threaded end of the economizer needle is provided with an adjusting nut. On Model NA-R7 and NA-R9 carburetors this nut is knurled and is locked with a cotter pin. On Model NA-R7A and NA-R9A carburetors the adjusting nut is a hex nut and is locked with a hex lock nut. Loosen the economizer valve needle adjusting nut lock nut, or remove the cotter pin if a Model NA-R7 or NA-R9 carburetor. Open the throttle until the protractor indicates the degree of throttle opening for which it is desired to set the economizer timing. Screw the economizer valve needle adjusting nut down until it contacts the valve needle actuating lever. Do not turn the nut hard enough to lift the valve needle or move the throttle, but make sure that it contacts the actuating lever. Secure the adjusting nut in position with the lock nut or cotter pin, as provided. Close the throttle and check the economizer timing. Reset if it is not correct.

SERVICE BULLETIN NO. 499

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

MODELS: Whirlwind R 760 E and R 975 E Series Engines Employing Cylinder Hold-Down Studs of 7/16 Inch Diameter on the Crankcase End

This bulletin applies to all Whirlwinds using cylinder hold-down studs of 7/16 inch diameter on the crankcase end. Early Whirlwinds using cylinder hold-down studs of 3/8 inch diameter at the crankcase end are not affected by this bulletin.

Several types of cylinder hold-down studs have been supplied on the above Whirlwind models, and different methods and tools are employed for their removal and installation. Cylinder hold-down studs used in all Whirlwinds of current manufacture have ground threads and a .043 inch taper per inch on the crankcase end threads.

Whirlwind models of current manufacture employ cylinder hold-down studs having a 7/16-12 thread on the crankcase end. Part numbers and descriptions of these studs are given in Table 1 at the end of this bulletin. Instructions for replacement of these studs may be found in Section "A" of this bulletin. These studs are driven into the crankcase to obtain a stud height of .640 to .700 inches. Stud height is defined as the distance from the cylinder mounting pad to the top of the stud when driven. Extended type nuts, Part No. 124-D-116, which are drilled for lockwiring, are used with these studs. Stud holes 1 and 8 in crankcases used in Whirlwinds of current manufacture are counterbored.

The cylinder hold-down studs are numbered consecutively in a clockwise direction around the cylinder mounting pad, beginning with No. 1 as the first stud to the left of the center line of the cylinder at the front of the engine, viewed from the propeller end and looking down on the pad.

The remaining Whirlwinds affected by this bulletin formerly employed cylinder hold-down studs having a 7/16-14 straight or .0025 inch taper per inch thread on the crankcase end. Straight studs are no longer supplied for replacement. Studs having .0025 inch taper per inch may be used for replacement of straight or .0025 inch tapered studs where only a very limited number of studs require replacement and the crankcase threads are in perfect condition. However, it is recommended that the crankcases used in these engines be reworked to incorporate the new 7/16-14, .043 inch taper per inch studs. Part numbers and description of these studs are given in Table 1 at the end of this bulletin. Instructions for reworking of the crankcase and installation of the new studs may be found in Section "B" of this bulletin. These studs are driven into the crankcase to obtain a stud height of .810 to .870 inches. Plain hexagonal nuts, locked by palnuts, are used with these studs. All stud holes in crankcases used in these engines are counterbored.

In cases where the stud hole threads have become mutilated in engines using 7/16-14 studs, replacement may be possible with 7/16-14, .043 inch taper, .003 inch oversize studs. However, when necessary, 9/16-10, .043 inch taper studs or 9/16-10, .043 inch taper, .003 inch oversize studs may be procured for replacement. Part numbers and descriptions of these studs are given in

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

Table I at the end of this bulletin. Instructions for installation are given in Section "C" of this bulletin.

Table I of this bulletin lists the only studs currently supplied and gives the part numbers, description, stud height, stud length, location of the various studs in the cylinder pad, in cases where certain studs should be driven in specific hole locations, and part numbers of hold-down nuts to be used with each stud. Note that only one oversize stud is supplied for each of the studs listed. These studs are .003 inch oversize and are marked with a +3 on the nut end.

Careful segregation of all studs is important when these parts are stocked, since the proper selection of a stud to be used in an engine is essential. An attempt to drive into a crankcase a stud not specifically intended for use in that crankcase may cause damage to the stud hole threads which will render the crankcase unsatisfactory for use. Discard all straight studs that may be in stock, since further replacement of those studs will be made with either the .0025 or the .043 inch taper ground thread studs. The difference in amount of taper is discernible to the experienced eye but further identification can be made by the number of threads per inch.

A careful inspection of all taps must be made before using to tap stud holes, since rough edges or burrs on the tap may cause the tap to cut oversize. All taps must be tried in a test block made of the same material as the material to be cut. The tap being tested should not free itself enough to shake in the tapped hole. If such shaking is possible, that is an indication that the tap is not free of burrs. Remove burrs if necessary.

Use a torque wrench in every case in driving a new stud. Torque limits for driving cylinder hold-down studs having 3/8 inch diameter threads and 24 threads per inch on the nut end have been established in the Table of Limits, TL-45. These torque limits should under no circumstances be disregarded in obtaining the proper stud height.

Section "A" - Replacement of 7/16-12, .043 Inch Taper Studs.

Remove the old studs using stud remover, Tool No. 801490. If the stud is broken in the crankcase, drill it out using successively 1/8, 1/4, and 9/32 inch drills, Tool Nos. 84276, 84277, and 84904, and drill jig, Tool No. 84907-1, and bushings, Tool Nos. 84907-4, 84907-3, and 84907-2. Note that if the stud is broken off in a counterbored hole, it will first be necessary to drill off the entire neck of the stud using drill, Tool No. 801155, and bushing, Tool No. 84907-5. Extreme caution must be exercised while drilling through studs in blind holes, as any misalignment might result in mutilation of the threads and drilling too deep might damage the crankcase.

Most of the studs installed in holes drilled completely through the crankcase can be removed during the drilling operation. Insure that all remaining particles are removed. However, with studs in blind holes, three drilling operations are needed to leave only the threads and the tip of the stud. Some

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

of the threads can be picked out with long-nose pliers, while others require removing Tool No. 802150 and wrench, Tool No. 83759. The end of the stud is in the shape of a washer and can be broken by striking with a cold chisel and removed.

Tap the threads to clean up to a depth of 1-1/16 to 1-5/16 inches for stud holes 2, 3, 4, 5, 6, and 7 with finish tap, Tool No. 84893, tap holder, Tool No. 84909, and tap fixture, Tool No. 84908. Use tap, Tool No. 84899 for .003 inch oversize studs. Tap holes 1 and 8 completely through the crankcase.

Drive in the stud to the correct stud height and to the proper torque limits using stud driver, Tool No. 84432, adapter, Tool No. 84435, and torque wrench, Tool No. 84922. Check the stud height and if not within limits, remove stud. If the stud projection is too great, try another stud of the same size or retap the hole slightly deeper and drive again. If the stud projection is too small, try another stud of the same size or retap the hole for an oversize stud.

All the necessary tools for the foregoing operations are listed in Table II at the end of this bulletin.

Tool Nos. 84907-1, 84907-2, 84907-3, 84907-4, and 84907-5 are supplied in a single set under Tool No. 84907. Tool Assembly No. 802149 includes the following standard and special tools: Tool Nos. 83759, 84276, 84277, 84432, 84435, 84904, 84907, 84908, 84909, 84922, 801155, 801490, and 802150. When a complete set of tools is desired, it should be ordered under Tool No. 802149. However, when only certain special tools of this set are required, they should be ordered under their respective tool numbers. **Blueprint No. 802149 is furnished with each set of tools. Tool Nos. 84898 and 84899 are furnished separately.**

Section "B" - Replacement of 7/16-14, Straight or .0025 Inch Taper Per Inch Studs With 7/16-14, .043 Inch Taper Per Inch Studs.

Removal of the old studs is accomplished by the same procedure outlined in Section "A" using the same tools. These tools are listed in Table III at the end of this bulletin. For replacement with the .043 inch taper studs, employ fixture, Tool No. 84908, clamp, Tool No. 801012, and centering plug, Tool No. 801537-1. Locate the centering plug in the present counterbore and lock the clamp.

In counterboring, adjust stop collar, Tool No. 801815 on counterbore, Tool No. 801519, to give the desired depth, as specified on Blueprint No. 801523. Install bushing, Tool No. 801539, in the fixture and counterbore holes No. 1 and 8 on all crankcases to a depth of .875 inches. On crankcases using .0025 inch taper studs, a counterbore of .375 inches is incorporated in holes 2, 3, 4, 5, 6, and 7. Crankcases using straight studs have these six holes counterbored to a depth of .188 inches. Counterbore these six holes on all crankcases to .375 inches.

Install bushing, Tool No. 801537-2, in the fixture and ream one of holes 2, 3, 4, 5, 6, or 7, using reamer, Tool No. 801520. Check with gauge, Tool No.

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

801521. Install stop collar, Tool No. 801537-3 on the reamer and set stop collar with reamer seated in reamed hole. Ream all remaining holes except 1 and 8 controlling the depth with the stop collar. Remove the stop collar and ream holes 1 and 8 and check with gauge, Tool No. 801522.

Loosen fixture clamp, Tool No. 801012. For rough tapping insure to start the tap in the old threads. Use rough tap, Tool No. 801540. Adjust stop collar on tap holder, Tool No. 84909 to the following dimensions, measured from the top of the stop collar to the end of the tap in order to tap to the desired depth: 5.540 inches for holes 2, 3, 4, 5, 6, and 7, and with the wedge in the lower slot of the holder, and 6.350 inches for holes 1 and 8 with the wedge in the upper slot. Hand tap to the indicated depth. Note that the stop collar is not used for finish tapping. Install finish tap, Tool No. 801517, for standard holes or Tool No. 801518 for .003 inch oversize holes. Hand tap these holes deep enough to obtain a stud height of .31 to .87 inches when the proper torque is applied in driving the stud.

Drive in the stud to the required depth and to the correct torque limits using stud driver, Tool No. 84432, adapter, Tool No. 84435, and torque wrench, Tool No. 84922. Check the stud height and if the stud is not within the limits, remove the stud. If the stud projection is too great, try another stud of the same size or retap the hole slightly deeper. If the stud projection is too small, try another stud of the same size or retap the hole for an oversize stud.

Replacing tools for the foregoing operations are listed under Table III at the end of this bulletin.

Tool Nos. 801537-1, 801537-2, and 801537-3 are supplied in a single set under Tool No. 801537 and should be ordered as such. Tool Assembly No. 802149 includes the following standard and special tools: Tool Nos. 83759, 84276, 84904, 84277, 84432, 84435, 84907, 84908, 84909, 84922, 801155, 801490, and 802150. When a complete set of tools is desired, it should be ordered under Tool No. 802149. However, when only certain special tools of this set are required, they should be ordered under their respective tool numbers. Blueprint No. 802149 is furnished with each set of tools. All other tools are furnished separately.

Section "C" - Replacement of 7/16-14 Inch Studs With 9/16-10, .043 Inch Taper Studs.

The same procedure for removal and replacement described in Section "B" of this bulletin should be followed when installing these studs. The tools necessary for removal and replacement of these studs are listed in Table IV at the end of this bulletin. Note that drill, Tool No. 801030, stop collar, Tool No. 80153 -4 and bushing, Tool No. 801538-1 are used in an additional operation prior to counterboring. Refer to Blueprint No. 801028 for specific rework instructions.

Tool Nos. 801538-1, 801538-2, 801538-3, and 801538-4 are furnished as a single set under Tool No. 801538 and should be ordered as such. Tool Assembly

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

No. 801028 includes the following tools: Tool Nos. 801030, 801031, 801032, 801033, 801034, 801035, and 801036. Tool Assembly No. 802149 includes the following standard and special tools: Tool Nos. S3759, 84276, 84277, 84432, 84435, 84904, 84907, 84908, 84909, 84922, 801155, 801490, and 802150. When a complete set of tools is desired, it should be ordered under Tool No. 802149. However, when only certain special tools of this set are required, they should be ordered under their respective tool numbers. Blueprint 802149 is furnished with each set of tools. All other tools are furnished separately.

Wright Aeronautical Corporation
(A Division of Curtiss-Wright Corporation)
January 28, 1942

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

TABLE I
CYLINDER HOLD-DOWN STUDS USED IN
WHIRLWIND ENGINES

| Engine Model | Stud Part Number | Stud Length (In.) | Stud Thread Description (Crankcase End Threads) | | | Stud Height (Inches) | | Location of Stud on Mounting Pad (Hole Nos.) | Hold-Down Nut & Method of Locking | Part Numbers of Studs Cancelled |
|--|------------------|-------------------|---|-------------------------|--------------------------|----------------------|------|--|-----------------------------------|---------------------------------|
| | | | Diameter (Inches) | Taper (Inches per Inch) | Diameter Over-size (In.) | Min. | Max. | | | |
| R 975 E R 760 E (of current manufacture) | 2118-D-1 | 1.719 | 7/16-12 | .043 | STD. | .640 | .700 | 2,3,4,5,6,7 | Lockwire | 126-D-139 |
| | 2118-H-1 | 1.719 | 7/16-12 | .043 | .003 | .640 | .700 | 2,3,4,5,6,7 | 85-D-14 | 126-H-139 |
| | 2118-D-2 | 2.563 | 7/16-12 | .043 | STD. | .640 | .700 | 1,8 | Nut | 126-D-140 |
| | 2118-H-2 | 2.563 | 7/16-12 | .043 | .003 | .640 | .700 | 1,8 | 124-D-116 | 126-H-140 |
| R 975 E R 760 E | 126-D-141 | 2.00 | 7/16-14 | .043 | STD. | .810 | .870 | 2,3,4,5,6,7 | Nut | 126-D-139 |
| | 126-H-141 | 2.00 | 7/16-14 | .043 | .003 | .810 | .870 | 2,3,4,5,6,7 | 124-D-54 | 126-H-139 |
| | 126-D-142 | 2.75 | 7/16-14 | .043 | STD. | .810 | .870 | 1,8 | Palnut | 126-D-140 |
| | 126-H-142 | 2.75 | 7/16-14 | .043 | .003 | .810 | .870 | 1,8 | 2000-D-3 | 126-H-140 |
| R 975 E R 760 E | 126-D-191 | 2.00 | 9/16-10 | .043 | STD. | .810 | .870 | 2,3,4,5,6,7 | Nut | 126-D-139 |
| | 126-H-191 | 2.00 | 9/16-10 | .043 | .003 | .810 | .870 | 2,3,4,5,6,7 | 124-D-54 | 126-H-139 |
| | 126-D-192 | 2.75 | 9/16-10 | .043 | STD. | .810 | .870 | 1,8 | Palnut | 126-D-140 |
| | 126-H-192 | 2.75 | 9/16-10 | .043 | .003 | .810 | .870 | 1,8 | 2000-D-3 | 126-H-140 |

SERVICE BULLETIN NO. 499

SUBJECT: Replacement of Whirlwind Cylinder Hold-Down Studs

| TABLE II | TABLE III | TABLE IV |
|--|--|--|
| <p><u>Removing Tools</u></p> <ul style="list-style-type: none"> 801,490 - Whole Stud Remover 84,276 - 1/8 Inch Drill 84,277 - 1/4 Inch Drill 84,904 - 9/32 Inch Drill 801,155 - 5/16 Inch Drill 84,907 - Drill Jig, Bushings 802,150 - Removing Tool 83,759 - Wrench <p><u>Replacing Tools</u></p> <ul style="list-style-type: none"> 84,898 - Finish Tap 84,899 - Tap (.003 inch oversize) 84,909 - Tap Holder 84,908 - Fixture 84,432 - Stud Driver 84,435 - Stud Driver Adapter 84,922 - Torque Wrench | <p><u>Removing Tools</u></p> <ul style="list-style-type: none"> 801,490 - Whole Stud Remover 84,276 - 1/8 Inch Drill 84,277 - 1/4 Inch Drill 84,904 - 9/32 Inch Drill 801,155 - 5/16 Inch Drill 84,907 - Drill Jig, Bushings 802,150 - Removing Tool 83,759 - Wrench <p><u>Replacing Tools</u></p> <ul style="list-style-type: none"> 84,908 - Fixture 801,012 - Fixture Clamp 801,537 - Centering Plug, Bushings, Stop Collars 801,815 - Stop Collar 801,519 - Counterbore 801,539 - Bushing 801,520 - Reamer 801,521 - Gauge 801,522 - Gauge 801,540 - Rough Tap 84,909 - Tap Holder 801,517 - Finish Tap 801,518 - Finish Tap (.003 inch oversize) 84,432 - Stud Driver 84,435 - Stud Driver Adapter 84,922 - Torque Wrench | <p><u>Removing Tools</u></p> <ul style="list-style-type: none"> 801,490 - Whole Stud Remover 84,276 - 1/8 Inch Drill 84,277 - 1/4 Inch Drill 84,904 - 9/32 Inch Drill 801,155 - 5/16 Inch Drill 84,907 - Drill Jig, Bushings 802,150 - Removing Tool 83,759 - Wrench <p><u>Replacing Tools</u></p> <ul style="list-style-type: none"> 84,908 - Fixture 801,012 - Fixture Clamp 801,537 - Centering Plug, Stop Collars, Bushings 801,538 - Stc. Collars, Bushings 801,030 - Counterbore Drill 801,031 - Counterbore 801,032 - Reamer 801,033 - Gauge 801,034 - Gauge 801,035 - Rough Tap 801,036 - Finish Tap 84,909 - Tap Holder 84,432 - Stud Driver 84,435 - Stud Driver Adapter 84,922 - Torque Wrench |

SERVICE BULLETIN NO. 501

SUBJECT: Interference Between Valve Tappet Ball Socket and Guide

MODELS: Whirlwind R760E and R975E Series Engines


Several instances of interference between the shoulder on the valve tappet ball socket, Part No. 62728, and the tappet guide have been reported. Investigation has revealed that this condition is caused by bottoming of the valve tappet guide approximately .018 inch above the blueprint requirements, in crank-cases that have been machined to the high limit of production tolerances on the outside diameter. The interference may cause mutilation of the outer ends of the tappet guides.

To overcome interference at this point, a new valve tappet ball socket, Part No. 115176, has been designed with a .10 inch wide step in the shoulder to allow sufficient clearance between this part and the tappet guide.

It is recommended that all the above model engines which have not been overhauled be inspected at once or as soon as possible for signs of this trouble. Routine overhaul inspection of older engines should have revealed previously any interference which existed between these parts. To perform this check, remove the push rod, push rod housing, and tappet guide retaining nut. The condition of the end of the tappet guide may then be checked. Whenever this trouble is experienced, it is recommended that the new socket be installed or the old socket be reworked to incorporate the change.

The rework must be accomplished by grinding because of case hardening of the socket. Chuck the socket shoulder in the grinder and check the socket body for true running. Grind the shoulder to the dimensions specified in the sketch at the end of this bulletin. Extreme care should be exercised to prevent overheating and grinding checks. Upon completion of the rework, it is recommended that a magnetic type inspection be made.

Service Division
Wright Aeronautical Corporation
(A Division of Curtiss-Wright Corporation)
January 28, 1942



REWORK OF WHIRLWIND VALVE TAPPET BALL SOCKET PART NO. 2728 TO PREVENT INTERFERENCE WITH TAPPET GUIDE.

S.S. NO. 501

SERVICE BULLETIN NO. 503

SUBJECT: Reduction of Propeller Vibration and Stress

MODELS: Whirlwind R760E Series Engines with No. 20 Spline Crankshafts
Whirlwind R975E Series Engines

THIS BULLETIN SUPERSEDES SERVICE BULLETIN NO. 503 DATED APRIL 30, 1942, DUE TO THE INCLUSION OF R975E MODEL ENGINES.

It is sometimes necessary to change the angular relation of the propeller to the crank throw to overcome excessive propeller vibration and stress. To permit the installation of the propeller at a particular angle, the blind spline must be removed from the crankshaft.

REMOVAL OF BLIND SPLINE

Install a flat head set screw, Part No. 2075-D-23, between two crankshaft splines in place of the fillister head set screw originally used. After removal of the original screw, countersink the screw hole to a .38" diameter with a 90 deg. countersink to permit proper seating of the flat head screw. Clean the shaft of all drill shavings.

CHANGING PROPELLER ANGLE

To facilitate the installation of the propeller at the desired angle on engines having the blind spline eliminated, it is recommended that the crankshaft be numbered according to the following standard reference system: Etch an "0" on the angular front face of the spline groove in which the set screw is located. Number "1" spline is adjacent to the groove marked "0" in the direction of propeller rotation. Continuing in this direction, the succeeding splines are numbered consecutively to 16.

In the following table find the angle which is closest to the angle recommended by the propeller manufacturer to give the desired timing for that installation. Note the propeller shaft splines listed after that angle in the table. Install the propeller on the shaft so that these splines are enclosed by the wide spline groove in the propeller hub.

| <u>Required Angle</u> | <u>Spline Numbers</u> |
|-----------------------|-----------------------|
| 0° | 16 and 1 |
| 22.5° | 1 and 2 |
| 45° | 2 and 3 |
| 67.5° | 3 and 4 |
| 90° | 4 and 5 |
| 112.5° | 5 and 6 |
| 135° | 6 and 7 |
| 157.5° | 7 and 8 |

Angles are measured from the centerline of No. 1 cylinder in the direction of propeller rotation when the piston in No. 1 cylinder is at top dead center.

R760E ENGINES

This bulletin is particularly applicable to R760E engines with solid

SUBJECT: Reduction of Propeller Vibration and Stress

counterweights and an S.A.E. No. 20 spline crankshaft. A No. 20 spline crankshaft measures 2-3/8" across the splines. When the Hamilton Standard 2B20 propellers having 6109A or 6135A blade design are installed on these engines, it is necessary to reindex the propeller so that the blades form an angle of 90° with the crank throw, and to make certain adjustments to the propeller as specified by the propeller manufacturer's Service Bulletin No. 66, Reference 230.

When this particular propeller is used on engines with dynamic damped crankshafts, excessive vibration may be entirely corrected by reworking the propeller as specified in the Hamilton Standard bulletin.

SERVICE BULLETIN NO. 519

SUBJECT: Change of Oil Pressure Markings on Crankcase Front Section

MODELS: Whirlwind R975E Series Engines

Some Whirlwind crankcase front sections were cast with reversed markings on the two tapped holes provided for measuring the hydro high and hydro low oil pressures. These oil pressure connections are found only on crankcase front sections which incorporate a propeller governor mounting pad.

The hydro high connection, marked "H", is located slightly to the right of the vertical center line of the engine and adjacent to the governor mounting pad. The hydro low connection, marked "L", is located several inches to the left of the vertical center line of the engine and is the connection away from the governor mounting pad. Where the markings "L" and "H" have been reversed, the "L" has been located at the hydro high connection and the "H" at the hydro low connection.

All operators of Whirlwind engines incorporating propeller governors should check to see that the hydro oil pressure connections are marked properly. If the connections have been marked incorrectly, the letters, which are of the raised type, should be removed by filing. The exposed surface should be protected by a coating of paint.

Using 1/8 inch type, stamp the proper letter directly in front of each connection boss. Although the crankcase is comparatively heavy at this point, extreme care must be exercised when stamping the letters to avoid cracking the case.

Engines on which the hydro oil connections are not identified should also be stamped in this manner.

Service Division
Wright Aeronautical Corporation
(A Division of Curtiss-Wright Corporation)
March 26, 1942

SERVICE BULLETIN NO. 529

SUBJECT: Provision for Increased Hydro Oil Pressure

MODELS: Whirlwind R760E and R975E Series Engines

Difficulty has been experienced in changing the propeller pitch on R760E and R975E engine installations which incorporate a two-position hydro oil control valve, due to insufficient hydro oil pressure. Sluggish pitch changes of the propeller when the two-position control valve is operated is evidence of insufficient hydro oil pressure.

In some engines, an external hydro oil tube has been installed. In these engines, insufficient hydro oil pressure is due to the high oil pressure backing into the normal engine oil system instead of supplying the hydro oil control valve.

In earlier engines, no external hydro oil tube was used. In these engines, insufficient pressure resulted from the drop of pressure during the passage of the oil through the engine.

In the case of engines which employ the external hydro oil tube, increased oil pressure may be obtained by plugging the oil passage between the two-position hydro valve and the propeller shaft hydro line. If the engines do not employ the external hydro oil tube, sufficient pressure may be obtained by installing the external line and plugging the oil passage.

If low pressure is evident, the rework should be done immediately. If not, the change should be made at the next overhaul.

To install this plug proceed as follows: Heat the crankcase front section to a temperature between 300°F. and 350°F. for approximately twenty minutes either in hot oil or in an oven. It is essential that the temperature of the crankcase front section does not exceed 350°F. since the strength of the metal in the crankcase may be seriously affected. Heating the front section in this manner will allow the crankcase front section sleeve to be removed easily from the propeller shaft bore. Care should be exercised in removing and in handling the sleeve since at high temperatures the metal becomes somewhat brittle. Remove the locking pin which will probably remain with the sleeve.

The oil passage to be plugged is the one towards the rear of the propeller shaft bore. Bore this passage to a diameter of .2955 - .2965 inch and to a depth of .88 inch as shown on Figure 1, using piloted reamer, Tool No. 602710. Reheat the crankcase as before and insert plug, Part No. 2634-D-21, in the hole so that all edges just clear the crankshaft bore. Peen a little metal into the hole to keep the plug in place. Install the sleeve in position, aligning it with a suitable rod inserted in the locking pin holes in the sleeve and crankcase. Install a new locking pin, Part No. 13-D-31.

To install the external hydro oil line, it will be necessary to rework the inter-cylinder air deflector between cylinders, Nos. 8 and 9, in accordance with Figure 2. Insert the grommet, Part No. 2109-D-6, in the opening drilled in the air deflector. Install the deflector on the engine and insert the hydro oil tube in position through the grommet.

SUBJECT: Provision for Increased Hydro Oil Pressure


Remove the pipe plug from the hydro oil pressure gauge connection on the crankcase front section, and the plug from the tapped hole adjacent to No. 9 cylinder intake pipe boss on the crankcase rear section. After coating the threads with Glyptal, install an elbow, Part No. 175-D-10, in each of these locations, and align the elbow outlets with the ends of the tube, Part No. 415834. Place a piece of hose, Part No. 2058-D-43, and two hose clamps, Part No. 5040-D-1, over each end of the tube. Insert a liner, Part No. 2015-D-3, in each of the elbows and place the end of the tube over the other end of the liner. Center the hose over the tube to elbow connection and secure the hose at each end with a hose clamp. Repeat this process at the front end of the hydro oil tube.

The parts necessary for incorporating the external hydro oil line are as follows:

| <u>Part No.</u> | <u>Part Name</u> | <u>Quantity</u> |
|-----------------|------------------|-----------------|
| 2109-D-6 | Grommet | 1 |
| 175-D-10 | Elbow | 2 |
| 415834 | Tube | 1 |
| 2058-D-43 | Hose | 2 |
| 5040-D-1 | Clamp | 4 |
| 2015-D-3 | Liner | 2 |

Wright Aeronautical Corporation
 (A Division of Curtiss-Wright Corporation)
 Paterson, New Jersey, U.S.A.
 June 17, 1942


Printed in U.S.A.



■REAK ALL SHARP CORNERS

FIG. 2

REWORK OF INTER-CYLINDER AIR DEFLECTOR
TO PROVIDE FOR EXTERNAL HYDRO OIL LINE



REMOVE SLEEVE NO. 62104
BEFORE PRESSING IN PLUG

REAM .2955-.2965
TO DEPTH SHOWN

2094-D-21

PEEN METAL OVER
AFTER INSERTING PIN

.88

BREAK ALL SHARP CORNERS

SECTION E-E

FIG.1

REWORK OF CRANKCASE FRONT SECTION ASSEMBLY

SERVICE BULLETIN NO. 539

SUBJECT: Installation of Crankcase Front Cover Spacer

MODELS: Whirlwind R760E and R975E Series Engines

Whirlwind engines of current production have been provided with a steel crankcase front cover spacer, Part No. 114162, to eliminate galling between the front cover and the outer race of the thrust bearing.

A new front cover, Part No. 416337, is installed with the spacer in place of cover, Part No. 47170. The new cover and spacer together are approximately the same size and shape as the former cover alone. The .005-.007 inch tight fit between the bearing and front cover has been changed to a .002-.004 inch loose fit when the spacer is used.


It is recommended that Whirlwind operators incorporate this spacer on engines in which galling of the front cover or thrust bearing is experienced. The crankcase front cover, Part No. 47170, may be replaced or may be reworked for use with the spacer.

Rework of the front cover, which is made of aluminum, may be accomplished with an ordinary lathe operation. Reduce the width of the cover to .519-.523 inch as shown in the sketch at the end of this bulletin, removing the metal from the rear face. Reduce the outer diameter of the cover pilot flange to 4.699-4.700 inch. Provide a .040 inch radius in the corner between the two reworked surfaces. Shorten the pilot flange to .256-.258 inch and provide a .040 inch 45 degree chamfer on the outer diameter at the end of the flange. Break all sharp edges to a .003-.015 inch radius.

To measure the side clearance, the thrust bearing may be reached from the interior of the front section sub-assembly with a feeler gauge.

Wright Aeronautical Corporation
(A Division of Curtiss-Wright Corporation)
Paterson, New Jersey, U.S.A.
August 5, 1942

Printed in U.S.A.



REWORK OF CRANKCASE FRONT COVER, PART NO. 47170

FOR USE WITH STEEL CRANKCASE FRONT COVER SPACER

PART NO. 114162


SB. NO. 539

SERVICE BULLETIN NO. 577
 SUBJECT: Plug Type Piston Pin Retainers
 SERIES: Whirlwind R760E and R975E

THIS BULLETIN SUPERSEDES SERVICE BULLETIN NO. 577 DATED JUNE 19, 1943, TO PERMIT REWORKING STANDARD SIZE RETAINERS TO UNDERSIZES.

Plug type piston pin retainers have been provided for Whirlwinds to replace the spring type retainer. It is recommended that the new retainers be installed at next overhaul. They may be used with all pistons.

A .002 -.004 in. loose fit is required between the retainer and the piston pin inner diameter. Two different retainers are provided to permit the installation of this type part with both the piston pin currently used and the early thin-walled pin. Measure each piston pin separately and install retainers of the proper size as noted in the following tables.



It is recommended that undersize retainers be ordered as required. Standard sizes, however, can be reworked to appropriate undersizes by turning down the "D" diameter in a lathe. The reworked surface and the inner face of the flange must be square within .002 in. full indicator reading. Stamp the retainer with the proper undersize designation as shown in the sketch.

RETAINER 117741

Use this retainer with the present piston pin No. 26823. As a .010 in. tolerance (.940 -.950 in.) had been permitted until recently on the inner diameter of this pin, undersize retainers have been provided to permit a selective fit with all pins.

| <u>Piston Pin Inner Diameter</u> | <u>Retainer Size</u> | <u>Retainer "D" Diameter</u> | <u>Retainer Part No.</u> |
|----------------------------------|----------------------|------------------------------|--------------------------|
| .949 -.950 in. | Standard | .946 -.947 in. | 117741 |
| .947 -.948 in. | -.002 | .944 -.945 in. | 117741Y1 |
| .945 -.946 in. | -.004 | .942 -.943 in. | 117741Y2 |
| .943 -.944 in. | -.006 | .940 -.941 in. | 117741Y3 |
| .941 -.942 in. | -.008 | .938 -.939 in. | 117741Y4 |
| .940 in. | -.010 | .936 -.937 in. | 117741Y5 |

It may be necessary to break the edges at the inner diameter of the pin to a larger radius to avoid interference with the retainers. Before installation check fit of the piston pins and retainers at this point. Piston pins are now made with a 1/32 in. x 45° chamfer at these edges.

RETAINER 126060

Use this retainer with the early thin-walled pin No. 22037. A .006 in. tolerance (1.028 -1.034 in.) was permitted on the inner diameter of this pin. Undersize

SUBJECT: Plug Type Piston Pin Retainers

retainers are provided for a selective fit.

| <u>Piston Pin Inner Diameter</u> | <u>Retainer Size</u> | <u>Retainer "D" Diameter</u> | <u>Retainer Part No.</u> |
|--------------------------------------|----------------------|----------------------------------|------------------------------|
| 1.033 -1.034 in. | Standard | 1.030 -1.031 in. | 126060 |
| 1.031 -1.032 in. | -.002 | 1.028 -1.029 in. | 126060Y1 |
| 1.029 -1.030 in. | -.004 | 1.026 -1.027 in. | 126060Y2 |
| 1.028 in. | -.006 | 1.024 -1.025 in. | 126060Y3 |

OVERHAUL

The retainers, which are made of aluminum, must be handled very carefully. Use puller, Tool No. 803390, to remove the retainers at overhaul if they do not come out readily. Avoid scratching or marring the end that bears against the cylinder wall. Lightly polish the other surfaces to remove carbon, but do not touch this dome.

Retainers must be replaced when the worn spot on the dome exceeds $3/8$ in. in diameter. Service limits on the fit with the piston pin inner diameter are .002 -.006 in.

Undersize retainers are stamped with their size for identification. To avoid measuring the piston pins at each overhaul, the size of the mating retainer may be acid etched on the ends of each pin. Pins must not be stamped or electrically etched.

Wright Aeronautical Corporation
 (A Division of Curtiss-Wright Corporation)
 Paterson, New Jersey, U.S.A.
 August 26, 1943

SERVICE BULLETIN NO. 592


SUBJECT: Re-design of Diffuser Section Oil Seal Ring

SERIES: Whirlwind R760E and R975E

A change has been made in the design of the oil seal packing, Part No. 2083-D-25, located at the diffuser section parting surfaces on the main pressure oil passage.

A groove has been cut in the ring to provide room for displacement of the ring material when the engine sections are assembled. With an ungrooved ring if the material more than fills the space provided for it, the excess may become wedged between the parting surfaces and may possibly crack the crankcase when the attaching bolts are tightened.

Grooved, neoprene oil seal rings, Part No. 2083-D-25, should be installed at next overhaul. Ungrooved neoprene rings carried in stock may be reworked to the dimensions in the sketch. Set the ring on a mandrel and cut the groove with a properly trimmed grinding wheel.



Cork packing rings are no longer recommended at this location.

Wright Aeronautical Corporation
(A Division of Curtiss-Wright Corporation)
April 23, 1943

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PRE-OILING WHEN STARTING
ENGINES

Bulletin No. W-1
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 24, 1943

Improved performance and extended service life of engine parts, particularly master rod bearings, may be obtained by insuring that all engines receive a sufficient quantity of oil upon starting.

To be sure that oil is immediately available, new engines, overhauled engines, or engines that have been in storage must be pre-oiled just prior to being operated. If the oil system of an aircraft has been drained, the engine must be pre-oiled before being operated. Pre-oiling, as outlined below, will provide the required supply of oil across the bearings during starting.

PRE-OILING ENGINES 1. Fill the oil tank normal full.

2. Remove the oil inlet line connection at the oil pump and drain one gallon or more of oil to insure that no air remains in the line.

3. Reinstall the oil inlet line to the oil pump.

4. Remove the oil pressure relief valve.

5. With the ignition switch off turn the crankshaft by hand or starter until sufficient oil is

expelled through the oil holes to indicate that no air remains in the oil pump. Reinstall the valve.

GENERAL INSTRUCTIONS The engine should be operated as soon as possible after pre-oiling. Start the engine in the normal manner, observing the engine oil pressure gage for indicated oil pressure. Stop the engine if the pressure does not begin to rise within five seconds and does not reach 40 pounds per square inch within ten seconds after starting.

It is recommended that an SAE 10 W oil of good quality, having a viscosity of approximately 40 at 210 deg F (99 deg C), be used in the oil pressure gage lines at all times. Keep all connections tight after the lines are filled to prevent the oil from running out. If the lines are allowed to fill up with engine oil, the oil will thicken in cold weather and give slow and incorrect pressure readings. Refill the lines whenever sluggish readings are noted.

SERVICE DEPARTMENT
WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PROFILING CRACKED CYLINDER
HEAD FINS

Bulletin No. W-2
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 24, 1943

Cracking of the cylinder head fins may be a result of vibration or differences in temperature. It is recommended that fins so affected be profiled to prevent the further extension of these cracks along the fins and into the dome of the cylinder. Cylinders with cracked domes must be discarded.

FIN REMOVAL LIMITS The maximum amount of metal which may be safely removed from cylinder head fins is approximately 1 per cent of the total fin cooling area of the head, or 2 square inches, measured on one side only of the fins. Fin metal may be removed from a single fin or from several fins, provided that the total amount of metal removed does not exceed 2 square inches. This limitation is necessary because the removal of a larger amount would adversely affect the cooling of the cylinder.

PROFILING Profiling consists of removing the cracked portion of the fin to the full depth of the fin, using for this purpose a thin burring tool or a grinding wheel that is operated on a flexible shaft. In profiling a fin, care must be exercised to prevent cutting into the dome of the head, to prevent scratching adjacent fins, and finally, to remove all sharp corners on the reworked fins. If these corners are not re-

moved or if scratches remain in the reworked areas, other cracks may develop. Therefore, profile and blend all such areas with a minimum radius of .250 inch.

DOMES INSPECTION 1. If it is necessary to profile a fin down to the outside surface of the cylinder head dome, inspect the location to insure that the crack does not extend into the dome. This inspection is accomplished by etching the outside surface of the dome adjacent to the reworked fins by swabbing or rubbing with a 10 to 20 per cent caustic soda solution for seven to ten minutes. Swabbing or rubbing is necessary to accomplish the removal of the aluminum oxides as they are formed and to work the caustic soda into any crack that may be present.

2. After this operation is completed, swab the same area with a 35 to 65 per cent solution of nitric acid. This treatment will brighten the surface and reveal any crack that may be present. The crack will appear as a black line.

3. The presence of a crack in the surface of a dome is cause for discarding the cylinder. If no cracks are found, wash the head thoroughly with hot water to remove the etching solutions, and if the cylinder is otherwise satisfactory, it may be installed on the engine for further use.

SERVICE DEPARTMENT
WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: ENGINE STARTING PROCEDURE

Bulletin No. W-3A
Page 1 of 2

MODELS AFFECTED: Whirlwind 7 and 9

Date: October 14, 1946

This bulletin cancels Service Bulletin No. W-3 dated January 15, 1944, to provide an improved procedure.

The procedure given below should be followed in starting all the above model engines, irrespective of the type of carburetor installed.

1. Head the aircraft into the wind whenever possible.

2. Set the controls in the following positions:

| | |
|----------------|-----------------------------|
| Cowl Flaps | "OPEN" |
| Oil Cooler | "CLOSED" or "AUTOMATIC" |
| Carburetor Air | "COLD" |
| Ignition | "OFF" |
| Mixture | "CUT-OFF" |
| Propeller | "LOW PITCH" ("HIGH RPM") |

3. Check for hydraulic lock by turning the propeller at least four blades. Always use the engine starter for this purpose except on installations incorporating cartridge or "shot gun" starters, in which case the propeller must be pulled through by hand in the normal direction of engine rotation. Exercise caution since two or three men exerting force on the tips of large propeller blades may cause serious damage to the engine if hydraulic lock is present. To prevent damage when using electric starters, make sure that the starter clutch setting does not exceed the recommended torque of 375 ± 50 foot-pounds.

Never turn the propeller opposite to the engine rotation when performing this operation, as such action forces liquid into the intake pipe, whence it is apt to be drawn back into the cylinder when the engine is started. If there is any apparent high compression, remove the spark plugs from the lower cylinders and allow any liquid that has collected in the combustion chambers to drain.

The presence of any quantity of liquid in the combustion chamber is likely to cause serious damage. The Wright Aeronautical Corporation will not be responsible for damage to an engine caused by liquid or any other obstruction in the cylinders.

4. Immediately before starting, adjust the following controls as noted:

| | |
|------------------|---|
| Throttle | Set for a maximum of 1200 engine rpm |
| Fuel Supply Cock | "ON" |

5. Build up the fuel pressure with the boost pump to the normal operating limits.

6. Energize the starter for approximately 10 seconds.

7. Engage the starter and operate the primer simultaneously.

8. After the propeller has turned two revolutions, turn the ignition switch to the "BOTH" position.

9. Operate the booster ignition. If the characteristics of the engine installation make it difficult or impossible to perform the starting operation in this manner, it will be satisfactory to switch the ignition on immediately before engaging the starter.

If the engine is equipped with a cartridge type or plain inertia type starter, the procedure must be altered for starting engines in cold weather. This is necessary because of the inherent inability of such starters to provide more than several engine revolutions even in warm weather. If the weather is extremely cold or if the oil has not been diluted, it may be impossible for the starter to rotate the crankshaft more than one-half revolution. Under these conditions it is permissible to prime the engine before the crankshaft starts rotating.

Prime for two or three seconds only, then switch the ignition to the "ON" position and immediately engage the starter or fire the cartridge.

10. As the engine starts to fire, regulate the charge to obtain smooth engine operation. This may be accomplished by varying the length or frequency of the strokes on a hand priming pump, or by operating the primer switch intermittently if the airplane is equipped with a solenoid type priming system. Success in starting depends on the manner in which the primer is operated. The priming operation is affected by the primer system, the temperature, and the ability of the operator. In airplanes equipped with a solenoid, smooth starting at temperatures below 4°C (40°F) will be best obtained by engaging the starter and the primer simultaneously and holding the solenoid "ON" until the engine has been running for several seconds on the primer charge alone. These procedures will be dictated by experience to compensate for the variables mentioned above.

11. With the engine operating smoothly on the priming charge, move the mixture control to the "RICH" position. As the carburetor starts to function, it will be necessary to decrease the priming until the engine is running smoothly on the carburetor.

12. Stop the engine if the oil pressure gage does not register within ten seconds or reach 40 pounds per square inch at 1200 rpm within twenty seconds after starting.

Should the engine refuse to start within 30 seconds, let the starter cool. Move the ignition switch to "OFF" and rotate the propeller through at least four blades to insure that overpriming has not caused liquid to collect in the cylinder. Repeat the starting procedure.

Do not prime by pouring raw gasoline into the cylinders through the exhaust ports or the spark plug bushings.

Be positive that the primer shut-off valve is operating properly and that it is closed except when the pump is being operated. Depending upon the type of priming system, fuel leaking through the primer pump into the intake passages may cause liquid to collect in the lower cylinders.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: COLD WEATHER STARTING

Bulletin No. W-4A

Page 1 of 3

MODELS AFFECTED: Whirlwind—All

Date: March 8, 1945

This bulletin supersedes Service Bulletin No. W-4, in order to bring the information up to date.

The major problem of cold weather operation is starting. Two basic conditions, the difficulty of vaporizing fuel and the tremendously increased lubricant viscosity at low temperatures, are fundamentally responsible for most starting troubles. Other factors, however, such as moisture or ice accumulation on the spark plug electrodes, battery power loss, and ice locking of engine accessories, will vary with location and conditions, but weigh heavily in the choice of any particular starting aid.

Regardless of the starting aids employed, standard starting procedures are recommended at all times. Moreover, experience has shown that a normal start may usually be made at temperatures above -12°C (10°F) without resorting to additional equipment and provided that careful engine handling techniques are used to prevent spark plug icing in humid areas. This temperature will be found at variance with other temperatures listed below for each contributing piece of equipment but has been found valid for the engine as a whole when all equipment is in good condition. The following paragraphs discuss those aids generally used in starting.

EXTERNAL HEAT

Many cold weather starting aids have been developed and tested, but none are so satisfactory, from the standpoint of the engine and its accessories, as applying heat externally. The use of external heat makes starting easier, eliminates need for special fuels, and precludes innumerable minor problems, because all parts of the engine and installation, not just the lubrication system, fuel system, or ignition system, operate normally from the first crank of the starter. Equipment should be available that will deliver heat continuously to the front and rear of the cylinders, rear section, battery, oil tank (unless self-sealing) and other accessories. The oil temperature must not be allowed to drop below -7°C (20°F) unless oil dilution is to supplement heating. If an oil tank of the self-sealing type is used, heat will not penetrate to the oil and oil dilution must be used. A shroud of quilted kapok, or other material, incorporating heater pipe inlets and designed to keep circulation at a minimum, is placed over the propeller

dome and back, over, and around the engine cowling. The engine accessory section and carburetor are also warmed since heat aids in vaporization of fuel during and after starting.

Heating should continue until the cylinder head temperatures reach 20°C (68°F); this allows for a certain amount of cooling while preparing to start. Spark plug icing may result if the engine cools off to 0°C (32°F) before starting.

OIL DILUTION

Oil can be diluted with gasoline prior to stopping the engine, thereby reducing subsequent starting friction and preventing the oil from congealing in engine passages, lines, or tank. Dilution is recommended for use if air temperatures are 0°C (32°F) or lower providing the oil tank cannot be heated.

The values given in the following table should be used only in the absence of authenticated information, generally supplied by the airplane manufacturer and placarded in the cockpit.

1. Operate the engine at 1000 rpm maximum.
2. Maintain oil temperature below 50°C (122°F) and oil pressure within recommended limits.
3. Hold the oil dilution valve open for the time specified at each temperature condition. The conditions are:

| | |
|---|-------------|
| 0° to -12°C (32° to 10°F) | —3 minutes |
| -12° to -29°C (10° to -20°F) | —6 minutes |
| -29° to -46°C (-20° to -51°F) | —10 minutes |

Add one minute dilution for each additional 5°C (9°F) below -46°C (-51°F).

4. During the last two minutes of the oil dilution operation, the following should be performed: On turbosupercharged engines with the regulators actuated by engine oil, dilute the oil in the regulators by moving the individual cockpit regulator control levers at least 14 complete movements from low to high boost and return.

For airplanes having hydromatic propellers, advance the propeller control until a drop of 400 rpm is observed, and return to its original position. Repeat three times. Do not depress the feathering switch.

5. Return the dilution switch to the "OFF" position and stop the engine. Diluting enables the starter to rotate the engine at a fairly high rate of speed without the necessity of preheating the oil. The gasoline evaporates gradually once the engine has started and oil temperature begins to rise.

After starting, if a highly viscous oil is indicated by an oil pressure that is too high or that fluctuates or falls off when engine rpm is increased, the dilution valve may be operated intermittently to correct this condition. Should the oil pressure drop too low, stop the engine, apply external heat and drain the system; replenish the oil supply with warm undiluted oil before attempting to start again.

AUXILIARY PRIMING SYSTEMS

If using external heat is not practicable, as in the case of water based aircraft, special priming fuels are resorted to; their use however does not eliminate the need for oil dilution. Regular aviation fuels do not sufficiently vaporize below -18°C (0°F) to provide satisfactory priming and consistent starting. If a high humidity condition is present, vaporization may be insufficient at -7°C (20°F). Numerous paraffin base, pure hydrocarbon fuels of higher volatility are available, some of which vaporize sufficiently at temperatures as low as -57°C (-70°F). Winter automotive gasoline having a Reid vapor pressure of 15 lb per sq in. (1.05 kg per sq cm) permits good starting down to approximately -29°C (-20°F). Ether, although not preferred as a priming fuel, because of toxic and low anti-knock qualities, permits successful starting to -29°C (-20°F), while pentane has been used at -34°C (-30°F).

The use of various priming systems, nozzles, and pressures has very little effect on the relative amount of fuel vaporization for starting. Any benefits derived by increasing priming pressures are probably due to the improvement of nozzle spray characteristics; even so, fuel vaporization may be reduced if fuel is injected in such quantities that it strikes the cold walls of the induction system before vaporizing.

Standard priming nozzles are satisfactory in cold weather starting when either regular fuel or special highly volatile fuels are used. When improper flow and spray characteristics are suspected, the nozzle should be tested by using gasoline or water at 5 lb per sq in. (42 kg per sq cm) pressure. A satisfactory cone spray should be obtained with no "dribbling" at a flow rate of 40 to 55 lb per hour.

To prevent spark plug electrode icing, the engine must be provided with the correct amount of priming, consequently insuring a successful start on the first

attempt. The two-point priming system with discharge nozzles located in the carburetor adapter has proved most satisfactory from this standpoint and it also reduces liquid lock possibilities by introducing fuel at a location other than one where lack of vaporization or subsequent condensation would tend to fill the lower intake pipes.

A portable priming unit can be constructed with a small tank of one or two gallons capacity equipped with an electric pump. The pump outlet can be connected to the regular two-point priming system by a quick sealing coupling. Power for the electric pump is obtained by installing a cannon plug connection and a primer solenoid line. No additional controls or circuits are required on the airplane.

For temperatures from freezing to -18°C (0°F), a mixture of equal amounts of special priming fuels and standard aviation gasoline is suggested for use with minimum possibilities of vapor lock; below this temperature, a quantity of the selected priming fuel alone may be used.

Normally, the standard fuel pressure of the auxiliary priming pump will be high enough to ensure proper nozzle spray.

OIL DRAINAGE

If forced to land where cold weather starting facilities are not available, keep the engine warm by occasional run-ups or else drain the oil system immediately after shutting down and then heat the oil so that the engine may be refilled with warm oil just prior to starting. Once oil congeals within the engine, extreme difficulty will be experienced before circulation can again be obtained.

SPARK PLUG ICING

Icing inside the combustion chamber results when the temperature drops below 0°C (32°F) and any moisture, either condensed from the air or caused by combustion at an unsuccessful starting attempt, freezes. This condition effectively "shoots out" the spark plugs, preventing starting. The higher the atmospheric relative humidity, the more serious this condition becomes. It is further aggravated by the fact that the fuel mist deposited in the combustion chamber from the combustion of fuel tends to collect moisture readily.

It is essential that the first starting attempt be successful. "False starting" in which the engine fires a few times and then cuts out, can cause spark plug icing since the water products of combustion will freeze.

BATTERY HEATING

It has been proven that batteries which are kept warm at all times will more nearly approach their capacity output than batteries that are cold. Batteries are rated at an air temperature of 27°C (80°F), and the performance of a new fully charged battery decreases as the temperature decreases. This is not a straight line relationship as indicated by the table below which is calculated on a 300 ampere discharge.

| Temperature | Percent Output in Relation to Capacity at 27°C (80°F) |
|---------------|---|
| 5°C (40°F) | 93 |
| -18°C (0°F) | 76 |
| -29°C (-20°F) | 55 |
| -34°C (-30°F) | 30 |
| -37°C (-34°F) | 5 |

Batteries, when being charged, should be in an air temperature of 5° to 27°C (41° to 80°F) since this procedure is also affected by atmospheric conditions. Most battery manufacturers specify a maximum temperature of not more than 60°C (140°F).

When bringing a battery from an airplane or from storage for recharging, sudden changes in temperature should be avoided to minimize the possibility of splitting battery cases. A battery that is cold should be heated to at least 5°C (41°F) before charging to ensure maximum battery life and minimum charging time. This is applicable to a battery being charged on a bench, in a hangar, or by the generator on the engine while in flight.

ACCESSORY FREEZING

Trouble has been experienced below -18°C (0°F) with frozen engine mounted accessories resulting in sheared accessory shafts when the engine is started. The vacuum pump in particular has been subject to this condition since the moisture condensed from the air during operation freezes after the engine has been shut down. Other accessories experience a similar trouble from lack of lubrication at starting. Since this lubrication is provided by engine oil through metering passages, normal oil dilution does not appreciably relieve this condition.

WARM-UP

It may be necessary, after the engine has started, to use carburetor air heat to prevent subsequent engine cutting out. This will occur when the carburetor intake air is at a low enough temperature to reduce fuel vaporization below the amount needed to maintain engine operation. Heat should be used as necessary to maintain a carburetor air temperature of not less than -18°C (0°F).

The entire engine warm-up should be conducted according to existing recommendations. In the case of a diluted engine the airplane may be flown at once if the oil pressure remains constant and a temperature rise is indicated by the oil temperature gage. The length of time it takes to evaporate the fuel varies for each installation, therefore the warm-up period will depend solely on the operator's judgment. Cowling flaps must be full open during all ground operations.

WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTISS-WRIGHT CORPORATION
PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CYLINDER HOLD-DOWN STUDS—LOCATION OF

Bulletin No. W-5
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: February 23, 1944

This bulletin supersedes all previously published material on this subject.


It is the purpose of this bulletin to establish a uniform method for identifying stud locations on the cylinder mounting pads of subject engines.

Cylinder hold-down studs are numbered in a clockwise direction, facing the cylinder mounting pads, with the propeller shaft end of the engine facing up. Number one stud is the first at the top and to the right of the vertical center line of the

mounting pad when the propeller shaft is pointing up. Refer to the sketch.

The number of the pad is the same as the number of the cylinder mounted on it.

The number of each stud hole in the cylinder mounting flange will be the same as the number of the corresponding stud location on the cylinder mounting pad.



WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTISS-WRIGHT CORPORATION
WOOD-RIDGE, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: IDENTIFICATION AND INSPECTION OF STEEL PARTS
TREATED TO ELIMINATE CHAFING

Bulletin No. W-6
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: March 7, 1944

This bulletin supersedes Service Bulletin No. 596,
dated May 26, 1943.

To eliminate chafing at steel to steel contact locations in all engines, the affected parts are often given a metallic or chemical treatment. The two methods of treatment are:

1. Plating the part with either silver, copper, tin, chrome or lead. This treatment results in a surface discoloration that resembles the color of the metal used in the plating.

2. Treating the surface of the part with chemicals. This treatment results in the surface having a dull, black, satin-like appearance.

These changes in appearance have caused the treated pieces to be mistaken for used or unfinished parts, and attempts have been made to polish them. Do not polish these parts.

NOTE

Chemically treated parts that are magnetized by passing electrical current through them must be polished at the point of contact with the electrodes as this type of finish acts as a partial insulator to electric current.

PRECAUTIONS Certain precautions must be taken when subjecting treated parts to a magnetic type inspection. Due to the discolored surface of the parts, a black medium will not give the desired result. Use a red oxide powder as a medium to obtain clearly visible patterns. Parts that can be magnetized circularly on a bar must not be polished, regardless of the type of treatment they have received.

WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: TOP DEAD CENTER INDICATOR TOOL No. 80932

Bulletin No. W-7

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: March 8, 1944


This bulletin supersedes Service Bulletin No. 591,
dated April 26, 1943.

The top dead center indicator, Tool No. 80932, must be assembled correctly to prevent breakage of the arm and to permit correct readings to be obtained. It is recommended that this tool be checked for proper assembly.

Disassemble the tool by removing the arm, loosening the screw, and taking the body from the shell. Remove the spring and plunger from

the body. Install the spring in the plunger and reassemble the tool. Be careful that the plunger and spring assembly and the arm are installed exactly as shown in the sketch.

Adjust the angle setting of the arm to conform with the particular piston cylinder assembly being checked.



SERVICE DEPARTMENT
WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

SERVICE BULLETIN

WRIGHT AERONAUTICAL CORPORATION

PISTON AND RING ASSEMBLY— MODIFICATION OF

Bulletin No. W-8B
Page 1 of 4

MODELS AFFECTED: Whirlwind R-760E and R-975E

Date: August 7, 1945

This bulletin supersedes Service Bulletin No. W-8A dated June 3, 1944, to include the R-760E series engines and to specify a new piston ring for piston ring groove No. 1.

GENERAL

Piston, part No. 114333, is being installed in all R-760E and R-975E engines. This piston incorporates 12 oil drain holes in the No. 5 ring groove and employs a new chrome faced piston ring, part No. 130799, in the No. 1 ring groove. See figure 1. Rings, part No. 112213, 66239, 67159, and 67160, are used in ring grooves No. 2, 3, 4, and 5 respectively. This arrangement greatly improves oil control which in turn insures longer service from the piston and the piston rings.




Figure 1

Piston, part No. 112214, formerly installed in these engines, incorporated oil drain holes in ring groove No. 4 and in the land between grooves No. 3 and 4. Ring, part No. 112213, was installed in ring grooves No. 1 and 2 and ring, part No. 66239, was installed in grooves No. 3, 4, and 5.

Piston, part No. 112214, may be reworked in accordance with instructions contained herein and used satisfactorily with the ring set up shown in figure 1.

REWORK

1. Remove the piston rings from the piston, part No. 112214.

2. Ream and plug the drain holes located in groove No. 4 and in the land between grooves No. 3 and 4 as follows:

(a) Place the piston on a vee block on a drill press table as shown in figure 2. Insert a No. 00 taper pin reamer in the drill chuck and ream the first hole until the large end of pin, part No. 75D9, when inserted, will project approximately .050 inch above the bottom of the land, as shown in View "A." Set the stop of the drill spindle for the proper reaming fit. Ream the remaining holes on the land.




Figure 2

(b) Place the piston on a vee block as shown in figure 3, with the block shimmed to approximately 2 degrees. Insert a No. 0 taper pin reamer in the drill chuck and ream the first hole in groove No. 1 until the large end of pin, part No. 69105, when inserted, will project approximately .050 inch above the bot-




Figure 3

tom of the groove, as shown in View "B." Set the stop on the drill spindle for the proper reaming fit. Ream the remaining holes in groove No. 4.

(c) Drive the pins in the reamed holes in the land to the dimensions shown in View "C." Cut off the pins inside of the pistons, to the dimensions shown in View "D," using a dull edge chisel in order to peen one side of the pin for retaining the latter in the piston. Install the pins in groove No. 4 using the same procedure. See Views "E" and "F."

3. Drill the new vent holes in the No. 5 ring groove as follows:

(a) Insert plug, tool No. 804498-2, in the piston pin hole, and slip drill jig, tool No. 804498, over the lower end of the piston and locate the blind hole in the jig with the pin in the plug. Insert the shank of a No. 45 (.082 inch diameter) drill through one of the drill bushings and into the lower groove of the pistons. Engage the pilot end of the four screws in this groove using care so that the screws are not forced against the piston. Remove the drill. Place the jig on a vee block. Drill 12 holes through using a No. 45 (.082 inch diameter) drill. Remove the burrs. See figure 4.

4. Machine a relief on the skirt of the piston as follows:

(a) Clamp the fixture, tool No. 804497, to the lathe plate. Indicate at "A" to run true within .001 inch full indicator reading. Place the piston on the fixture and insert a dummy pin, tool No. 804497-4, through the piston and the draw rod and tighten the

nut on the draw rod lightly. Locate the piston radially on the fixture using pin, tool No. 804497-2, and locator, tool No. 804497-3, as shown in figure 5. Clamp the piston to the fixture securely by tightening the draw rod nut. Cut the relief to the dimensions shown. Repeat this operation on the opposite side of the pistons. Break all sharp corners. See figure 5.




Figure 4




Figure 5

5. Machine a chamfer on the bottom ring groove as follows:

(a) Clamp the fixture, tool No. 804497, to the lathe face plate, indicating surface "A" to run true within .001 inch full indicator reading. Clamp the piston to the fixture using the dummy piston pin and draw-in rod as shown. Cut chamfer to the dimensions shown. Break all sharp corners. See figure 6.

6. Restamp the piston part number.

(a) Deface the old part number, 112214, with a blunt end punch. Using a metal stamp with 1/8 inch numerals, stamp part No. 114333 on the dome, confining the stamping to the same section of the dome end between 3/8 and 1 inch from the edge of the piston.

(b) Polish the stamping lightly with crocus cloth to remove raised edges.

TOOLS REQUIRED

| Tool | Name |
|-----------------|------------------------------------|
| (Not Furnished) | Reamer, No. 0 |
| (Not Furnished) | Reamer, No. 00 |
| 804497 | Lathe, Fixture |
| 804498 | Drill, Jig |
| | Drill, No. 45 (.082 inch diameter) |
| (Not Furnished) | Vee Block |




Figure 6

PARTS REQUIRED

| <i>Part No.</i> | <i>Quantity Per Piston</i> | <i>Name</i> | <i>Part No.</i> | <i>Quantity Per Piston</i> | <i>Name</i> |
|-----------------|----------------------------|--------------------|-----------------|----------------------------|--|
| 150799 | 1 | Ring, Groove No. 1 | 67160 | 1 | Ring, Groove No. 5 |
| 112213 | 1 | Ring, Groove No. 2 | 69D5 | 14 | Pin, Special Taper, No. 0 by .250 inch |
| 66239 | 1 | Ring, Groove No. 3 | 75D9 | 16 | Pin, Special Taper, No. 00 by .375 inch |
| 67159 | 1 | Ring, Groove No. 4 | | | |

WRIGHT AERONAUTICAL CORPORATION
 A DIVISION OF CURTISS-WRIGHT CORPORATION
 PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

SERVICE BULLETIN

WRIGHT AERONAUTICAL CORPORATION

TITLE: INDICATOR EXTENSION ARM FOR MEASURING PROPELLER
SHAFT RUN-OUT

Bulletin No. W-9

Page 1 of 1

MODELS AFFECTED—Whirlwind—All


Date: May 2, 1944

This bulletin supersedes Service Bulletin No. 598, dated May 31, 1943.

Measurement of propeller shaft run-out on an engine installed in an aircraft may be done quite simply by the use of a dial indicator and an extension arm similar to that illustrated. The tool is constructed to a 9-inch length with internal threading at one end and a 3/8 inch shank. Attachment of the tool to the engine is

made by removing one of the crankcase front cover nuts and installing the arm on the stud threads.

An adapter, also illustrated, may be constructed to accommodate the tool when used on engines incorporating 5/16-inch studs at the crankcase front cover location.



WRIGHT AERONAUTICAL CORPORATION

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

SERVICE BULLETIN

WRIGHT AERONAUTICAL CORPORATION

TITLE: CLEANING SPARK PLUG INSERT THREADS

Bulletin No. W-10
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: May 24, 1944

The use of the tool described below will simplify the removal of hard-baked deposits which accumulate in the spark plug insert threads during normal engine operation. This procedure will not require the removal of the cylinder to clean the insert, as the danger of damage to the engine from metallic chips falling into the cylinder will be eliminated.

with current instructions, and apply a generous amount of heavy grease during the operation so that the amount of material which might fall into the cylinder is held to a minimum. After the operation is completed, carefully remove the grease.

CONSTRUCTION OF TOOL 1. Select a rejected spark plug which has good threads.

2. Mill four 1/16-inch slots in the threads as illustrated. Extend these slots up to the shell shoulder. See figure 1. Mill the slot deep enough to provide adequate clearance for any material which might accumulate when the plug is used as a tool.

3. With a fine three-cornered file, dress the threads next to the slots to remove any rough edges that might result from the milling operation.

USE OF TOOL Insert the plug, which is now similar to a tap, into the spark plug insert as far as it will go. One passage should remove any foreign material without increasing the depth of the insert threads. Do not use grease of any kind during this operation. Do not install a spark plug gasket.

Note

If spark plug insert distortion is experienced, it will be necessary to use a spark plug insert tap to true up the threads. Use this tap in accordance





Figure 1

TOOLS REQUIRED FOR TAPPING OPERATION

Tool No.
81355

Name
Tap

PARTS REQUIRED A rejected spark plug with good shell threads.

WRIGHT AERONAUTICAL CORPORATION

A Division of Curtiss Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U. S. A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CYLINDER HOLD-DOWN STUDS, REPLACEMENT OF

Bulletin No. W-11
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: June 17, 1944

When it is necessary to replace a cylinder hold-down stud because of failure during operation, it is recommended that the remainder of the studs on the cylinder pad be replaced at the

same time.

It has been found that the failure of one stud overstresses the remainder, thus making them unsafe for further use.

WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

WRIGHT
AERONAUTICAL
CORPORATION

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: TABLE OF LIMITS

Bulletin No. W-12E

Page 1 of 10

MODELS AFFECTED: Whirlwind—All

Date: July 5, 1944

Revised: September 1946

This bulletin supersedes Bulletin No. W-12D, dated May 20, 1946, to incorporate the latest changes in the Tables of Limits.

The Table of Limits, Numbers 13 and 79, contained in this bulletin provide the most recent, recommended maximum and minimum service clearances and shall be considered to supersede all previously issued instructions.

In order to determine a particular clearance, it is first advisable to find the exact location of the fit on the cross-sectional drawing of the Limits and Lubrication Chart. The arrow directed to the clearance will indicate the reference number to be used. The number of the Table of Limits in which both the reference number and the clearance figures appear is also clearly indicated on the chart. When consulting the Table of Limits, the letter "L" will indicate a loose fit, while the letter "T" will indicate those fits which are tight, or which are less than a line to line fit.

Revised pages to the Table of Limits will be issued periodically and, when received, they should be inserted in place of the pages which they supersede. Each revised page will be dated and the letter "R" will precede reference numbers for revised fits and the letter "N" will be used in the same location to advise of additional or new fits. Charts may be kept up to date by simply drawing an arrow on the chart to indicate each new reference number added to the Table of Limits. Reference numbers missing from the orderly sequence of reference numbers in the Table of Limits have been cancelled and should be so indicated by deleting the corresponding numbers on the charts.

The date of issuance of the most recent Limits and Lubrication Charts is shown below. Copies of these charts may be obtained upon request.

Whirlwind Limits and Lubrication Charts

| <i>Chart No.</i> | <i>T. L. No.</i> | <i>Chart Name</i> | <i>Part No.</i> | <i>Latest Revision</i> |
|------------------|------------------|---|-----------------|------------------------|
| 1 | 79 | Section Through Accessory Drives—R-760E, R-975E | 853560 | January, 1944 |
| 2 | 13 and 79 | Longitudinal Section—R-760E, R-975E | 853559 | January, 1944 |

Table of Limits No. 13
WHIRLWIND R-975E ENGINES
GUN SYNCHRONIZER

The reference numbers listed are found on Limits and Lubrication Chart No. 2.

| Reference No. | Chart No. | Description | Inches | |
|------------------|--------------|---|---------------|---------------|
| | | | Minimum | Maximum |
| 106 | 2 | Synchronizer Housing and PlungerDia. | .0005L | .005L |
| 107 | 2 | Synchronizer Cam and Roller with Plunger Locked in Position ... | .002L | .010L |
| 108 | 2 | Synchronizer Roller and PlungerSide Clearance | .002L | .012L |
| 109 | 2 | Synchronizer Roller and ShaftDia. | .001L | .004L |
| 110 | 2 | Synchronizer Shaft Bearing and HousingDia. | .000 | .003L |
| 111 | 2 | Synchronizer Shaft Bearing Cage and Housing Dia. | .000 | .003L |
| 112 | 2 | Synchronizer Shaft Bearing and CageDia. | .000 | .003L |
| 113 | 2 | Synchronizer Drive Gear Shaft and Synchronizer Drive Shaft Gear.....Backlash | .004 | .025 |
| 114 | 2 | Synchronizer Shaft and BearingDia. | .0006T | .002L |
| 115 | 2 | Synchronizer Shaft Bearing Cage and HousingDia. | .001T | .003L |
| 116 | 2 | Synchronizer Drive Gear and Accessory Drive Shaft Bevel Gear Backlash | .004 | .025 |
| 117 | 2 | Synchronizer Cam Shaft and HousingDia. | .001L | .008L |
| 500 | 2 | Ball Bearing Retainer Nut.....Tightening Torque Threads must be lubricated with oil. | 375 in.-lb | 400 in.-lb |

TABLE OF LIMITS No. 79

Table of Limits No. 79
WHIRLWIND R-760E AND R-975E ENGINE BASIC
LONGITUDINAL SECTION AND SECTION THROUGH ACCESSORY DRIVES

The reference numbers listed are found on Limits and Lubrication Charts No. 1 and 2

| Reference No. | Chart No. | Description | Inches | | |
|--------------------------|-----------|--|-------------------------|-------------------------|----------|
| | | | Minimum | Maximum | |
| 1 | 1 | Rocker Roller Hub and Pin Dia. | .001T | .002L | |
| 2 | 1 | Rocker Roller Hub and Roller Dia. | .0015L | .020L | |
| 3 | 1 | Rocker Roller Hub and Rocker Arm Side Clearance Select to obtain .000-.001 inch tight fit before riveting. | Rivet Tight | | |
| 4 | 1 | Rocker Roller and Rocker Arm Side Clearance | .0095L | .050L | |
| 5 | 1 | Rocker Box and Rocker Bearing Side Clearance Before clamping. | .004L | .020L | |
| 6 | 1 | Rocker Bearing Bore and Rocker Bolt Dia. | .000 | .004L | |
| 7 | 1 | Rocker Bearing Outside Diameter and Rocker Arm Dia. | .000 | .0017T | |
| 8 | 1 | Rocker Bolt and Cylinder Head Dia. | .0005L | .005L | |
| VALVE SPRING LOAD | | | | | |
| | | <i>Spring</i> | <i>Wire Dia.</i> in. | <i>At Height</i> in. | |
| 9 | 1 | Outer | .175 | 1.380 | 49.32 lb |
| 10 | 1 | Interm | .135 | 1.380 | 30.07 lb |
| 11 | 1 | Inner | .112 | 1.340 | 20.91 lb |
| 12 | 1 | Valve Guide and Intake Valve Center Dia. | | | .0025L |
| | | Large diameter valve stem. End Dia. | | | .0025L |
| 12A | 1 | Valve Guide and Intake Valve Center Dia. | | | .0025L |
| | | Small diameter valve stem. End Dia. | | | .010L |
| 13 | 1 | Valve Guide and Exhaust Valve Center Dia. | | | .005L |
| | | Large diameter valve stem. End Dia. | | | .013L |
| 13A | 1 | Valve Guide and Exhaust Valve Center Dia. | | | .005L |
| | | Small diameter valve stem. End Dia. | | | .015L |
| 14 | 1 | Intake Valve Guide and Cylinder Head Dia. Shrink fit. | | | .0008T |
| 15 | 1 | Exhaust Valve Guide and Cylinder Head Dia. Shrink fit. | | | .002T |
| 16 | 1 | Exhaust Valve Seat and Cylinder Head Dia. Shrink fit. | | | .011T |
| 17 | 1 | Intake Valve Seat and Cylinder Head Dia. Shrink fit. | | | .011T |
| 18 | 1 | Cam Hub Bearing Spacer Select spacer to align cam with valve tappet rollers. | | | |
| 19 | 1 | Valve Tappet Ball Socket Spring Wire Diameter .051 in. Load at 2.18 in. | | | 7.74 lb |
| 20 | 1 | Valve Tappet Guide and Valve Tappet Dia. Select tappet to obtain this fit. | | | .001L |
| 21 | 1 | Valve Tappet Guide and Crankcase Dia. | | | .0005T |
| 22 | 1 | Valve Tappet Roller and Roller Pin Dia. | | | .003L |
| 23 | 1 | Piston and Piston Pin Dia. | | | .0005T |
| 24 | 1 | Piston Groove No. 1 (Top) and Ring Side Clearance | .0075L | .010L | |
| 24A | 1 | Piston Groove No. 1 (Top) and Ring (Wedge) Side Clearance Side clearance of wedge rings must be measured in four equally spaced places and is obtained when wedge ring OD is flush with the piston thrust faces at the skirt diameter. | .002L | .006L | |

BULLETIN No. W-12E

| Reference No. | Chart No. | Description | Inches | |
|---------------|-----------|---|---------|---------|
| | | | Minimum | Maximum |
| 25 | 1 | Piston Groove No. 2 and Ring Side Clearance | .006L | .0035L |
| 25A | 1 | Piston Groove No. 2 and Ring (Wedge) Side Clearance | .002L | .006L |
| | | Side clearance of wedge rings must be measured in four equally spaced places and is obtained when wedge ring OD is flush with the piston thrust faces at the skirt diameter. | | |
| 26 | 1 | Piston Groove No. 3 and Ring Side Clearance | .0045L | .007L |
| 27 | 1 | Piston Groove No. 4 and Ring (Scraper Ring) Side Clearance | .0045L | .007L |
| 27A | 1 | Piston Groove No. 4 and Ring (Uniflow Piston) Side Clearance | .009L | .012L |
| | | (Oil Control Ring) Side Clearance | .0045L | .0075L |
| 28 | 1 | Piston Groove No. 5 and Ring Side Clearance | .0045L | .007L |
| 29 | 1 | Piston and Cylinder—Center of Skirt Dia. | .023L | .041L |
| 29A | 1 | Piston Wear—Center of Skirt Dia. | | .004 |
| 30 | 1 | Piston Pin Bushing and Master and Articulated Rods (Split Bushing) Dia. | .0045T | .0065T |
| 30A | 1 | Piston Pin Bushing and Master and Articulated Rods (Solid Bushing) Dia. | .001T | .005T |
| 31 | 1 | Piston Pin and Bushing Dia. | .0015L | .005L |
| | | Bushing bores in either end of connecting rod must be parallel in all planes within .015 inch in 6 inches when checked on standard fixture. | | |
| 32 | 1 | Master Rod End Clearance on Crankpin Dia. | .013L | .050L |
| 33 | 1 | Crankpin Bearing and Master Rod Dia. Shrink fit. | .001T | .003T |
| 34 | 1 | Crankpin Bearing and Crankpin Dia. Select at assembly. Bushing bores in either end of connecting rod must be parallel in all planes within .015 inch in 6 inches when checked on standard fixture. | .0025L | .006L |
| 34A | 1 | Crankpin Bearing and Crankpin Dia. Select at assembly. Bushing bores in either end of connecting rod must be parallel in all planes within .015 inch in 6 inches when checked on standard fixture. For R-760E series engines only. | .003L | .0065L |
| 34B | 1 | Crankpin Bearing and Crankpin Dia. Select at assembly. Bushing bores in either end of connecting rod must be parallel in all planes within .015 inch in 6 inches when checked on standard fixture. For R-975-7 engines only. | .0035L | .006L |
| 35 | 1 | Knuckle Pin and Master Rod Dia. | .000 | .0015T |
| 36 | 1 | Knuckle Pin Bushing and Master Rod Side Clearance | .006L | .030L |
| 37 | 1 | Knuckle Pin Bushing and Articulated Rod Dia. Split bushing. | .0045T | .0065T |
| 37A | 1 | Knuckle Pin Bushing and Articulated Rod Dia. Solid bushing. | 1T | .005T |
| 38 | 1 | Knuckle Pin Bushing and Knuckle Pin Dia. Bushing bores in either end of connecting rod must be parallel in all planes within .015 inch in 6 inches when checked on standard fixture. | .0015L | .005L |
| 39 | 1 | Main Bearing Support and Crankcase Front Section Dia. | .003T | .005L |
| 40 | 1 | Main Front Bearing Support and Bearing Ring Dia. | .003T | .006T |
| 41 | 1 | Main Front Bearing and Bearing Ring Dia. | .0002T | .006L |
| 42 | 1 | Main Front Bearing and Crankshaft Dia. | .0002T | .0013T |

TABLE OF LIMITS No. 79

| Reference No. | Chart No. | Description | Inches | |
|---------------|-----------|--|------------------------|---------|
| | | | Minimum | Maximum |
| 43 | 1 | Allowable Run-Out of Crankshaft at Center Bearing When Supported at Thrust and Rear Main Bearings | .004 Maximum | |
| | | | Full Indicator Reading | |
| 44 | 1 | Thrust Bearing and Front SectionDia. | .0002L | .004L |
| 45 | 1 | Thrust Bearing and CrankshaftDia. | .0002T | .0009L |
| 46 | 1 | Thrust Bearing and Front Cover Clamp Shim | .005T | .007T |
| 47 | 1 | Allowable Run-Out of Crankshaft at Thrust Bearing Journal When Supported at Front and Rear Main Bearings..... | .004 Maximum | |
| | | | Full Indicator Reading | |
| 48 | 1 | Crankcase Front Cover and Crankcase Front Cover Sleeve.....Dia. | .003T | .006T |
| 49 | 1 | Main Bearing Support and Crankcase Main SectionDia. | .002T | .006L |
| 50 | 1 | Propeller Shaft Thrust Bearing Nut and Oil Seal Ring Side Clearance | .002L | .028L |
| 51 | 1 | Thrust Bearing Play Between inner and outer races measured on an axis parallel to crankshaft. | | .020 |
| 52 | 1 | Crankshaft Front and Crankshaft Rear.....Dia. Before tightening screw. | .001T | .005L |
| 53 | 1 | Crankshaft Rear End Plug and Crankshaft.....Dia. | .000 | .002T |
| 54 | 1 | Crankshaft Rear Gear Hub and Crankshaft Gear.....Dia. | .001L | .005L |
| 55 | 1 | Crankshaft Rear Gear Hub and Crankshaft Gear Side Clearance | .001L | .008L |
| 56 | 1 | Crankshaft Rear Spring Wire Diameter .125 in. Load at .713 in. Height | 181 lb | |
| 57 | 1 | Crankshaft Rear Bearing and Rear Crankshaft Dia. | .002L | .0045L |
| 58 | 1 | Crankshaft Rear Bearing and Crankcase Main SectionDia. Shrink fit. | .002T | .004T |
| 59 | 1 | Rear Crankshaft and Counterweight Pin Bushing Dia. | .001T | .0025T |
| 60 | 1 | Rear Crankshaft and Counterweight Side Clearance | .006L | .015L |
| 61 | 1 | Rear Counterweight and Stop | .041L | .060L |
| 62 | 1 | Rear Counterweight and Bushing Dia. | .0015T | .003T |
| 63 | 1 | Starter Drive Gear Bushing and Diffuser Section.....Dia. | .001T | .003T |
| 64 | 1 | Starter Drive Gear and Bushing Dia. | .001L | .008L |
| 65 | 1 | Starter Shaft Bushing and Shaft Dia. | .001L | .008L |
| 66 | 1 | Starter Shaft Bushing and Rear Section Dia. | .001T | .003T |
| 67 | 1 | Starter Shaft End Clearance | .013L | .050L |
| 68 | 1 | Starter Drive and Crankshaft Gear..... Backlash | .008 | .025 |
| 69 | 2 | Oil Check Valve Spring Wire Dia. .036 in. Load at 1.440 in. Height | 1.575 lb | |
| 70 | 2 | Oil Suction Strainer Spring Wire Dia. .063 in. Load at 3.125 in. Height..... | 6 lb | |
| 71 | 2 | Vacuum Pump Drive Shaft and Vacuum Pump Drive Gear Backlash | .004 | .025 |
| 72 | 2 | Oil Pump Idler Shaft and Oil Pressure Pump Body.....Dia. | .001L | .0025L |
| 73 | 2 | Oil Pump Idler Shaft and Pump Spacer.....Dia. | .002L | .0035L |
| 74 | 2 | Reverse-Type Generator Idler Pinion and Bracket.....Dia. | .001L | .008L |
| 75 | 2 | Reverse-Type Generator Idler Gear and Pinion..... Backlash | .004 | .050 |
| 76 | 2 | Oil Pressure Relief Valve Body and Oil Pump Body.....Dia. | .000 | .005L |
| 77 | 2 | Oil Check Valve Body and Crankcase Rear Section.....Dia. | .001T | .001L |

BULLETIN No. W-12E

| Reference No. | Chart No. | Description | Inches | |
|---------------|-----------|--|---|---------|
| | | | Minimum | Maximum |
| 78 | 2 | Oil Pressure Relief Valve Spring Wire Dia. .048 in. Load at 1.250 in. Height | 4.95 lb | |
| 79 | 2 | Oil Pump Drive Shaft and Oil Pump Idler Shaft Backlash | .004 | .025 |
| 80 | 2 | Oil Pressure Pump Body and Oil Pump Idler Shaft End Clearance | .002L | .005L |
| 81 | 2 | Oil Pump Body and Oil Pump Idler Shaft Dia. | .001L | .0025L |
| 82 | 2 | Oil Pump Body and Pump Gear Dia. | .005L | .009L |
| 83 | 2 | Oil Pressure Pump Body and Oil Pump Idler Shaft Dia. | .004L | .010L |
| 84 | 2 | Oil Pump Body and Oil Pump Idler Gear Dia. | .004L | .010L |
| 85 | 2 | Oil Pump Body and Oil Pump Drive Shaft Dia. | .001L | .0025L |
| 86 | 2 | Oil Pump Body and Vacuum Pump Drive Shaft Bushing . Dia. | .001T | .003T |
| 87 | 2 | Oil Pump Idler Gear and Body End Clearance | .002L | .005L |
| 88 | 2 | Oil Pump Drive Shaft and Oil Pressure Pump Body Dia. | .001L | .0025L |
| 89 | 2 | Oil Pump Drive Gear and Oil Pressure Pump Body Dia. | .001L | .008L |
| 90 | 2 | Oil Pump Drive Shaft and Oil Pump Gear Spacer Dia. | .002L | .0035L |
| 91 | 2 | Oil Pump Shaft Gear and Oil Pressure Pump Body Dia. | .004L | .010L |
| 92 | 2 | Oil Pump Gear and Oil Pump Idler Gear Backlash Total permissible backlash in finished pump. | | .025 |
| 93 | 2 | Oil Pump Bushing and Vacuum Pump Drive Shaft Dia. | .001L | .008L |
| 94 | 1 | Impeller Shaft Rear Ball Bearing Side Clearance Do not use to set impeller shaft. | .005L | |
| 95 | 1 | Impeller Shaft Ball Bearing and Impeller Shaft Dia. | .0001L | |
| 96 | 1 | Impeller Shaft Bearing Support and Bearing Dia. | .0005L | .0013L |
| 97 | 1 | Impeller Shaft Rear Bearing and Cage Dia. | .0005L | .0013L |
| 98 | 1 | Impeller Oil Seal Ring Side Clearance | .006L | .011L |
| 99 | 1 | Impeller Oil Seal Ring Gap | .003 | .010 |
| 100 | 1 | Impeller and Shaft | Impeller must be a tight fit on splines | |
| 101 | 1 | Impeller Shaft Nut Lock and Nut Side Clearance | .003L | .006L |
| 102 | 1 | Impeller Shaft Nut Lock and Nut End Clearance | .000 | .004L |
| 103 | 1 | Impeller and Supercharger Housing (Front) Side Clearance | .022L | .027L |
| 104 | 1 | Impeller and Supercharger Housing (Rear) Side Clearance | .018L | .072L |
| 105 | 1 | Impeller Drive Gear Bearing and Support | Clamp Tight | |
| 106 | 1 | Impeller Drive Gear Pinion and Bearing Side Clearance | .008L | .025L |
| 107 | 1 | Supercharger Intermediate Gear and Bushing Dia. | .001T | .003T |
| 108 | 1 | Impeller Drive Gear Hub Bearing and Impeller Drive Gear Bushing Dia. | .003L | .006L |
| 109 | 1 | Impeller Shaft Gear and Drive Gear Backlash | .002 | .010 |
| 110 | 1 | Impeller Drive Pinion and Crankshaft Gear Backlash | .010 | .025 |
| 111 | 1 | Cam Drive Pinion Spring Wire Dia. .062 in. Load at 1.375 in. Height | 8 lb | |
| 112 | 1 | Cam, Cam Hub and Attaching Screw Dia. | .000 | .002T |
| 113 | 1 | Cam Hub and Cam Bearing Dia. | .0015T | .0045T |
| 114 | 1 | Cam Hub Support and Cam Bearing Dia. | .003L | .008L |
| 115 | 1 | Cam Hub Side Clearance | .007L | .025L |
| 116 | 1 | Cam and Cam Drive Pinion Backlash | .006 | .025 |
| 117 | 2 | Accessory Drive Shaft and Bushing Dia. | .001L | .008L |
| 118 | 1 | Hydro-Control Valve Adapter and Crankcase Dia. | .002L | .006L |
| 119 | 2 | Accessory Drive Idler and Starter and Accessory Drive Gears Backlash | .004 | .025 |
| 120 | 1 | Accessory Drive Idler Gear Side Clearance | .011L | .050L |

TABLE OF LIMITS No. 79

| Reference No. | Chart No. | Description | Inches | |
|---------------|-----------|--|---------|---------|
| | | | Minimum | Maximum |
| 121 | 1 | Accessory Drive Idler Gear Bushing and Diffuser Section Dia. | .001T | .003T |
| 122 | 1 | Accessory Drive Idler Gear and Bushing Dia. | .001L | .008L |
| 123 | 2 | Accessory Drive Shaft Bushing and Crankcase Rear Section Dia. | .000 | .002L |
| 124 | 2 | Accessory Drive Shaft and Rear Bushing Dia. | .001L | .008L |
| 125 | 2 | Accessory Drive Shaft Rear Bushing and Crankcase Rear Section Dia. | .001T | .003T |
| 126 | 2 | Accessory Drive Shaft and Bushings Side Clearance | .012L | .050L |
| 127 | 2 | Accessory Drive Shaft Bevel Gear and Tachometer and Fuel Pump Drive Shaft Backlash | .004 | .025 |
| 128 | 2 | Tachometer Drive Gear and Sleeve and Tachometer Shaft Bushing Dia. | .001L | .008L |
| 129 | 2 | Tachometer and Fuel Pump Drive Shaft and Fuel Pump Drive Gear Dia. | .000 | .002L |
| 130 | 2 | Tachometer and Fuel Pump Drive Shaft and Tachometer and Fuel Pump Drive Shaft Adapter Dia. | .001L | .008L |
| 131 | 2 | Tachometer and Fuel Pump Drive Shaft Adapter Side Clearance | .006L | .029L |
| 132 | 2 | Tachometer Driving Gear and Drive Shaft Gear Backlash | .004 | .025 |
| 133 | 2 | Tachometer Driving Gear and Sleeve Dia. | .0035T | .0015L |
| 134 | 2 | Tachometer Drive Gear and Housing Side Clearance | .003L | .050L |
| 135 | 2 | Rear Crankcase and Tachometer and Fuel Pump Drive Shaft Adapter Large Dia. | .001L | .005L |
| 136 | 2 | Fuel Pump Adapter Bushing and Fuel Pump Gear Dia. | .001L | .005L |
| 137 | 2 | Rear Crankcase and Tachometer and Fuel Pump Drive Shaft Adapter Small Dia. | .000 | .002L |
| 138 | 2 | Crankcase Rear Section and Packing Retainer Ring Dia. | .001T | .005T |
| 139 | 2 | Fuel Pump Drive Gear and Tachometer and Fuel Pump Drive Shaft Backlash | .004 | .025 |
| 140 | 2 | Fuel Pump Adapter and Bushing Dia. | .001T | .003T |
| 141 | 2 | Drive Shaft Bushing and Diffuser Section Dia. | .001T | .003T |
| 142 | 1 | Governor Drive Adapter and Crankcase Dia. | .000 | .004L |
| 143 | 1 | Governor Drive Bevel Gear Bushing and Adapter Dia. | .0015T | .0035T |
| 144 | 1 | Governor Drive Bevel Gear and Bushing Dia. | .001L | .005L |
| 145 | 1 | Governor Drive Intermediate Bevel Gear and Governor Drive Bevel Gear Backlash | .004 | .025 |
| 146 | 2 | Reverse-Type Generator Gear and Support Dia. | .006L | .010L |
| 147 | 2 | Reverse-Type Generator Gear and Bracket Dia. | .002L | .008L |
| 148 | 1 | Crankshaft (Front) Gear Oil Seal Ring Gap | .008 | .013 |
| 149 | 1 | Crankshaft (Front) Gear and Governor Drive Intermediate Spur Gear Backlash | .004 | .025 |
| 150 | 1 | Governor Drive Intermediate Bevel Gear and Bushing Dia. | .001L | .005L |
| 151 | 1 | Governor Drive Intermediate Bevel Gear and Bushing and Bracket Dia. | .0015T | .0035T |
| 152 | 2 | Tachometer Driving and Drive Shaft Gear Backlash | .004 | .025 |
| 153 | 2 | Tachometer Drive Shaft and Bushing Dia. | .0025L | .008L |
| 154 | 2 | Tachometer Housing and Bushing Dia. | .0005T | .0025T |
| 155 | 2 | Tachometer Drive Shaft Side Clearance | .008L | .040L |
| 156 | 2 | Tachometer Drive Shaft and Bushing Dia. | .001L | .008L |
| 157 | 2 | Tachometer Drive Shaft Cover and Bushing Dia. | .0035T | .0055T |
| 158 | 2 | Tachometer Drive Packing Gland Spring Wire Dia. .095 in. Load at .591 in. Height | 16 lb | |

BULLETIN No. W-12E

| Reference No. | Chart No. | Description | Inches | |
|---------------|-----------|--|---------|---------|
| | | | Minimum | Maximum |
| 159 | 2 | Tachometer Drive Shaft and Gland Dia. | .009L | .020L |
| 160 | 2 | Generator Idler Gear and Starter Gear Backlash | .004 | .020 |
| 161 | 2 | Generator Idler Gear Bushings and Shaft Dia. | .001L | .008L |
| 162 | 2 | Generator Idler Gear and Bushings Dia. | .0005T | .0035T |
| 163 | 2 | Generator Idler Gear Side Clearance | .003L | .050L |
| 164 | 2 | Generator Drive Gear Support and Bushing Dia. | .0015T | .0035T |
| 165 | 2 | Generator Drive Gear and Generator Drive Support Bushing Dia. | .0025L | .008L |
| 166 | 2 | Generator Drive Gear and Generator Drive Support Side Clearance | .006L | .020L |
| 167 | 2 | Tachometer Drive Shaft and Housing Dia. | .006L | .016L |
| 168 | 2 | Tachometer Drive Shaft Side Clearance | .005L | .035L |
| 169 | 2 | Tachometer Shaft Spiral Gear Backlash | .004 | .025 |
| 170 | 2 | Tachometer Drive Sleeve and Bushing Dia. | .0005T | .0025T |
| 171 | 2 | Tachometer Drive Shaft and Bushing Dia. | .001L | .0065L |
| 172 | 2 | Generator Drive Gear Support and Rear Crankcase Dia. | .001T | .003L |
| 173 | 2 | Generator Idler Gear Shaft Bushing and Rear Crankcase Dia. | .001T | .003T |
| 174 | 2 | Generator Idler Gear Shaft and Rear Crankcase Dia. | .000 | .003L |
| 175 | 2 | Generator Idler Gear Shaft and Bushing Dia. | .000 | .003L |
| 176 | 2 | Generator Idler Gear and Starter Shaft Gear Backlash | .004 | .025 |
| 177 | 1 | Crankshaft Constant Speed Governor Drive Gear and Oil Seal Ring Side Clearance | .001L | .006L |
| 178 | 1 | Hydro-Control Propeller Operating Valve and Hydro-Control Valve Adapter Dia. | .0005L | .0037L |
| 179 | 1 | Crankcase Sleeve and Crankcase Front Section Dia. | .001T | .0035T |
| 180 | 1 | Crankshaft Constant Speed Governor Drive Gear and Crankcase Front Section Sleeve Dia. | .017L | .034L |
| 181 | 1 | Crankshaft Constant Speed Governor Drive Gear and Crankshaft Dia. | .0005L | .003L |
| 182 | 2 | Generator Idler Gear and Bushing Dia. | .0005T | .0035T |
| 183 | 1 | Spline Side Clearance | | .040 |
| | | Movement of propeller hub on crankshaft measured at 15 inch radius from center of crankshaft. | | |
| 184 | 1 | Propeller Thrust Bearing Nut Oil Seal Ring Gap | .000 | .002 |
| 185 | 1 | Allowable Run-Out of Crankshaft between Threads and Splines at Forward End When Supported at Front and Rear Main Bearings Full Indicator Reading | .012 | Maximum |
| 186 | 1 | Oil Sump Strainer Spring Wire Dia. .091 in. Load at 1 in. Height 1.45 lb | | |
| 187 | 2 | Gear and Accessory Drive Shaft Spline Dia. | .001L | .008L |
| 188 | 2 | Gear and Accessory Drive Shaft Dia. | .001L | .005L |
| 189 | 2 | Gear and Tachometer and Fuel Pump Drive Adapter Dia. | .0015L | .008L |
| 190 | 2 | Gear and Accessory Drive Shaft Adapter and Bushing Dia. | .0005L | .008L |
| 191 | 2 | Tachometer and Fuel Pump Drive Cover and Bushing Dia. | .0005L | .0025L |
| 192 | 2 | Accessory Drive Shaft and Vacuum Drive Bevel Gear Backlash | .004 | .025 |
| 193 | 2 | Gear and Vacuum Pump Drive Shaft Spline | .001L | .012L |
| 194 | 2 | Vacuum Pump Drive Shaft and Fuel Pump Drive Gear Backlash | .004 | .025 |
| 195 | 2 | Fuel Pump Adapter and Bushing Dia. | .0025T | .0045T |

TABLE OF LIMITS No. 79

| Reference No. | Chart No. | Description | Inches | |
|---------------|-----------|--|---------|---------|
| | | | Minimum | Maximum |
| 196 | 1 | Piston Rings Gap | .032 | |
| 197 | 2 | Fuel Pump Drive Gear and Bushing Dia. | .062L | .006L |
| 198 | 2 | Vacuum Pump Adapter and Bushing Dia. | .0035T | .0055T |
| 199 | 2 | Vacuum Pump Drive Shaft and Bushing Dia. | .001L | .005L |
| 200 | 2 | Gear and Vacuum Pump Drive Shaft Dia. | .061L | .006L |
| 201 | 2 | Accessory Drive Housing and Bushing Dia. | .0015T | .0035T |
| 202 | 2 | Vacuum Pump Drive Shaft Gear and Bushing Dia. | .001L | .008L |
| 203 | 2 | Vacuum Pump Drive Shaft Side Clearance | .063L | .040L |
| 204 | 2 | Governor Drive Gear and Vacuum Pump Drive Shaft ... Backlash | .004 | .025 |
| 205 | 2 | Governor Drive Gear and Bushing Dia. | .002L | .008L |
| 206 | 2 | Governor Adapter and Bushing Dia. | .0015T | .0035T |
| 207 | 1 | Crank Cheek Cap Screw Stretch | .004 | .005 |
| | | Use .625 inch diameter ball at head end when measuring. | | |
| 208 | 1 | Knuckle Pin Locks—Select to Obtain a Light Tapping Fit When Assembled between Knuckle Pins | | |
| 209 | 1 | Thrust Bearing and Crankcase Front Cover Spacer Side Clearance | .001L | .004L |
| 210 | 1 | Cylinder Barrel Bore Taper | | .010 |
| 211 | 1 | Cylinder Barrel Bore Out-of-Round | | .005 |
| 212 | 1 | Crankshaft Adapter and Oil Seal Ring Side Clearance | .001L | .015L |
| | | Apply to 7 ring adapters. | | |
| 213 | 1 | Crankshaft Adapter Oil Seal Ring Gap | .008 | .013 |
| 214 | 1 | Hydro-Control Propeller Operating Valve and Crankcase Front Section Dia. | .0005L | .004L |
| 215 | 2 | Valve Tappet Guide and Valve Tappet (External Lubrication) Dia. | .0002L | .003L |
| 216 | 1 | Impeller Drive Gear Pinion and Bushing Dia. | .001T | .003T |
| 217 | 1 | Impeller Drive Pinion Bearing Ring and Pinion Dia. | .0025T | .0045T |
| 218 | 1 | Impeller Drive Pinion and Clutch Band and Dog (Slot) Side Clearance | .000 | .020L |
| 219 | 1 | Impeller Drive Ring Gear and Clutch Assembly Total Clearance | .000 | .020L |
| 220 | 1 | Starter Drive Gear Bushing and Rear Section Dia. | .000 | .002L |
| 221 | 1 | Governor Drive Bracket and Crankcase Dia. | .000 | .004L |
| 222 | 1 | Starter Shaft (With Riveted Starter Drive Gear) End Clearance | .009L | .050L |
| 223 | 1 | Crankshaft Adapter and Oil Seal Ring Side Clearance | .0085L | .036L |
| | | Apply to 3 ring adapters. | | |
| 224 | 1 | Crankshaft Adapter and Crankcase Front Section Sleeve Dia. | .035L | .050L |
| 225 | 1 | Crankshaft Adapter and Crankshaft Dia. | .0025L | .005L |
| 226 | 1 | Crankshaft Adapter Oil Seal Ring Gap | .000 | .015 |
| 227 | 1 | Propeller Thrust Bearing Nut and Front Cover Sleeve Dia. | .0215L | .0485L |
| 228 | 2 | Tachometer Drive Shaft and Gland Dia. | .010L | .020L |
| 229 | 2 | Tachometer Drive Shaft and Housing Dia. | .006L | .016L |
| 230 | 1 | Crankshaft Length | 6.49S | 6.502 |
| | | Front crank cheek front face to shoulder on rear crank cheek. | | |
| 231 | 1 | Piston Pin Plug and Piston Pin Dia. | .002L | .006L |
| 232 | 1 | Valve Clearance If this clearance aligns oil hole in adjusting screw with split in rocker arm, turn screw in direction to increase valve clearance until hole is closed off .09 inch or until .017 inch valve clearance is obtained, whichever occurs first. In no case must .017 inch clearance be exceeded. | .010 | |
| 233 | 1 | Piston Pin Plug and Cylinder Bore Total Side Clearance | .034L | .064L |

| Reference No. | Chart No. | Description | Inches | |
|------------------|--------------|---|---------------|---------------|
| | | | Minimum | Maximum |
| 500 | 1 | Intake Pipe Flange to Cylinder Head Attaching Bolt Tightening Torque | 125 in.-lb | 150 in.-lb |
| 501 | 1 | Valve Clearance Adjusting Screw Lockscrew (Tapered Head) Tightening Torque | 135 in.-lb | 150 in.-lb |

Table of Limits No. 45

ALL MODELS

TIGHTENING TORQUE VALUES

Note: Special cases and exceptions to TL-45 are listed in other Tables of Limits.







STANDARD STUDS, BOLTS, SCREWS AND CAP SCREWS

| NAME | Size of Thread | Minimum Diameter of Thread Root or Neck (Inches) | Minimum Rockwell Hardness | Tightening Nut, Screw, or Cap Screw TORQUE VALUES | |
|--|----------------|--|---------------------------|---|-----------------|
| | | | | Minimum In.-Lb. | Maximum In.-Lb. |
| Button Head Screws | 10-32 | .1467 | B-50 | 20 | 25 |
| | 12-24 | .1585 | B-50 | 25 | 30 |
| Bolts, Screws, Cap Screws | 10-32 | .1467 | C-19 | 35 | 40 |
| | 12-24 | .1585 | C-19 | 45 | 50 |
| Standard Plain and Elastic Stop Nuts and Undrilled Cap Screw Heads | 1/4-28 | .180 | C-26 | 80 | 85 |
| | 5/16-24 | .229 | C-26 | 160 | 175 |
| | 3/8-24 | .285 | C-26 | 225 | 250 |
| | 7/16-20 | .331 | C-26 | 350 | 375 |
| | 1/2-20 | .387 | C-26 | 550 | 600 |
| | 9/16-18 | .436 | C-26 | 825 | 875 |
| Standard Slotted Nuts and Drilled Cap Screw Heads | 1/4-28 | .180 | C-26 | 70 | 95 |
| | 5/16-24 | .229 | C-26 | 145 | 200 |
| | 3/8-24 | .285 | C-26 | 200 | 285 |
| | 7/16-20 | .331 | C-26 | 315 | 425 |
| | 1/2-20 | .387 | C-26 | 500 | 700 |
| | 9/16-18 | .436 | C-26 | 750 | 1000 |
| | 5/8-18 | .493 | C-26 | 1000 | 1375 |

STANDARD PRACTICES FOR SPECIAL APPLICATIONS

| | | | | | |
|---|----------|------|------|------|------|
| Cylinder Hold-Down Stud | 3/8-24 | .313 | C-32 | 325 | 450 |
| Cylinder Hold-Down Stud Nut | | | | 350 | 375 |
| Cylinder Hold-Down Stud | 7/16-20 | .331 | C-32 | 400 | 550 |
| Cylinder Hold-Down Stud Nut | | | | 425 | 450 |
| Cylinder Hold-Down Cap Screw | 7/16-20 | .330 | C-26 | 500 | 525 |
| Rocker Hub Bolt | 7/16-20 | .371 | C-32 | 250 | 325 |
| | 15/32-20 | .400 | C-19 | 250 | 325 |
| | 9/16-18 | .488 | C-26 | 300 | 375 |
| Spark Plug | 18mm | | | 300 | 360 |
| Water Injection Discharge Valve | 9/16-18 | | | 200 | 210 |
| Water Injection Discharge Valve | 3/4-16 | | | 130 | 170 |
| Water Injection Tube Gland Nut | 7/16-20 | | | 105 | 145 |
| Water Injection Tube Gland Nut | 5/8-18 | | | 160 | 200 |
| Spark Plug Insert | 1.000-14 | | | 1200 | 1400 |
| Fuel Injection Nozzle Insert | 5/8-18 | | | 400 | 450 |
| Exhaust Flange Lock Nut | 5/16-24 | | | 90 | 100 |
| Fuel Injection Nozzle | 7/16-20 | | | 275 | 300 |
| Fuel Injection Nozzle Substituting Plug | 7/16-20 | | | 275 | 300 |

TORQUE VALUES FOR DRIVING STUDS

| STUD SIZE | | | TORQUE VALUE | TORQUE VALUE | TORQUE VALUE | |
|---|----------------|---------|---|---|---|----------|
| | | | In.-Lb | In.-Lb | In.-Lb | |
| <p>STEPPED STUDS</p> <p>TYPES X AND Y ARE DRIVEN FROM NUT END</p> <p>TYPE Z IS DRIVEN FROM FLAT ON STUD END</p> | | |  |  |  | |
| | | | TYPE X | TYPE Y | TYPE Z | |
| | Hand Driven | Nut End | Stud End | | | |
| | | .250-28 | .313-18 | 50-100 | 50-70 | 50-110 |
| | | .313-24 | .375-16 | 100-210 | 100-150 | 100-240 |
| | | .375-24 | .438-14 | 175-390 | 175-275 | 175-435 |
| | | .438-20 | .500-13 | 250-600 | 250-425 | 250-670 |
| | | .500-20 | .563-12 | 400-980 | 400-700 | 400-1110 |
| | | .563-18 | .625-11 | 600-1360 | 600-975 | 600-1570 |
| | | .625-18 | .688-11 | 900-1950 | 900-1400 | 900-2130 |
| | Machine Driven | .250-28 | .313-18 | 50-100 | 50-80 | 50-125 |
| | | .313-24 | .375-16 | 100-235 | 100-170 | 100-330 |
| | | .375-24 | .438-14 | 175-460 | 175-325 | 175-510 |
| | | .438-20 | .500-13 | 250-730 | 250-520 | 250-320 |
| .500-20 | | .563-12 | 400-1130 | 400-810 | 400-1290 | |
| .563-18 | | .625-11 | 600-1620 | 600-1150 | 600-1790 | |
| .625-18 | | .688-11 | 900-2320 | 900-1670 | 900-2540 | |
| | | | | | | |
| <p>STRAIGHT STUDS</p> <p>TYPES X AND Y ARE DRIVEN FROM NUT END</p> <p>TYPE Z IS DRIVEN FROM FLAT ON STUD END</p> | | |  |  |  | |
| | | | TYPE X | TYPE Y | TYPE Z | |
| | Hand Driven | Nut End | Stud End | | | |
| | | .250-28 | .250-20 | 50-70 | 50-60 | 50-70 |
| | | .313-24 | .313-18 | 100-150 | 100-130 | 100-150 |
| | | .375-24 | .375-16 | 175-275 | 175-230 | 175-255 |
| | | .438-20 | .438-14 | 250-425 | 250-370 | 250-425 |
| | | .500-20 | .500-13 | 400-700 | 400-500 | 400-700 |
| | | .563-18 | .563-12 | 600-975 | 500-690 | 600-975 |
| | | .625-18 | .625-11 | 900-1400 | 700-1010 | 900-1400 |
| | Machine Driven | .250-28 | .250-20 | 50-90 | 50-65 | 50-90 |
| | | .313-24 | .313-18 | 100-200 | 100-135 | 100-200 |
| | | .375-24 | .375-16 | 175-350 | 175-250 | 175-350 |
| | | .438-20 | .438-14 | 250-560 | 250-400 | 250-560 |
| .500-20 | | .500-13 | 400-580 | 400-630 | 400-580 | |
| .563-18 | | .563-12 | 600-1290 | 500-920 | 600-1290 | |
| .625-18 | | .625-11 | 900-1790 | 700-1290 | 900-1790 | |
| | | | | | | |

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: APPROVED SPARK PLUGS

Bulletin No. W-13D

Page 1 of 1

MODELS AFFECTED: Whirlwind—R760E and R975E

Date: February 17, 1947

This bulletin supersedes Service Bulletin No. W-13C, dated December 2, 1946 in recognition of changes in the list of approved spark plugs.

The procedure outlined below is currently being followed in determining the acceptability of new or improved spark plugs for use in Whirlwind engines.

1. The vendor must submit spark plugs to the Wright Aeronautical Corporation who will apply to the Civil Aeronautics Administration for approval of the plugs after sufficient engine test stand experience has shown that approval is warranted.

2. Upon receiving Civil Aeronautics Administration approval and upon request by the spark plug manufacturer, the Wright Aeronautical Corporation will notify all domestic operators that the new plug has been approved for limited use to accumulate service operating experience. The Wright Aeronautical Corporation will then notify the spark plug manufacturer that these plugs may be released to domestic operators for this purpose.

3. Service experience operation must be conducted with a total of between 1,000 and 2,000 plugs of which no more than 500 plugs may be used by any one airline.

4. All spark plugs to be service tested must be

routed through the Service Division of the Wright Aeronautical Corporation for inspection, after which they will be forwarded to the operator.

5. A report of operation experience must be forwarded to the Wright Aeronautical Corporation on forms which will be provided, together with a sufficient quantity of parts to permit accurate analysis. Subsequent to the accumulation of operating experience and the analysis of the results as obtained by operators participating in the project, the Wright Aeronautical Corporation will grant or deny final approval of the plugs for general use.

All spark plugs currently approved for use in these engines are included in the following list. The order of listing is not intended to represent a recommendation for any particular spark plug mentioned.

The approval of any of these spark plugs for use in a particular engine is limited only by installation requirements—the necessary reach of the plug and the size and type of ignition wiring harness attachment.

| Part No. | Wrench Size | Spark Plug | Reach | Type | Terminal Connection Thread Size |
|----------|-------------|----------------|-------|------------|---------------------------------|
| 28044 | 11/16 | B.G. 3B2 | Short | Unshielded | Clamp Fastened |
| 27818 | 11/16 | B.G. 4B2 | Short | Unshielded | Clamp Fastened |
| 29624 | 11/16 | B.G. 3B2S | Short | Shielded | 9/16-27 |
| 29263 | 11/16 | B.G. 4B2S | Short | Shielded | 9/16-27 |
| 63185 | 1 | B.G. 314GS | Short | Shielded | 9/16-27 |
| 64174 | 1 | B.G. 298GS | Long | Shielded | 9/16-27 |
| 111556 | 1 | B.G. 1S 298 | Long | Shielded | 5/8-24 |
| 117597 | 1 | B.G. 1S 298A | Long | Shielded | 5/8-24 |
| 112895 | 7/8 | B.G. 1S 465 | Long | Shielded | 5/8-24 |
| 117596 | 7/8 | B.G. 1S 465A | Long | Shielded | 5/8-24 |
| 118602 | 7/8 | Champion C35S | Long | Shielded | 5/8-24 |
| 130170 | 7/8 | Champion RC35S | Long | Shielded | 5/8-24 |
| 132278 | 7/8 | Champion C26S | Short | Shielded | 5/8-24 |
| 133108 | 7/8 | Champion R37S | Long | Shielded | 5/8-24 |
| 132630 | 7/8 | B.G. RB19R | Long | Shielded | 5/8-24 |

- * Use short reach where inserts in cylinder have 1/2 inch thread depth.
- Use long reach where thread depth is 13/16 inch.

REFERENCE INFORMATION:

R 760E, R 975E may require either long or short reach, shielded or unshielded plugs.

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

WOOD-RIDGE, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CHROME PLATING FOR SALVAGE

Bulletin No. W-14

Page 1 of 2

MODELS AFFECTED: Whirlwind—All

Date: September 8, 1944

Wear on engine steel parts often causes rejection of the part due to the fact that established clearances cannot be met although the part is otherwise in satisfactory condition. Some of these parts may be reconditioned for further use by chrome plating. This procedure is only necessary where oversize and undersize mating parts are not available.

The sketches included in this bulletin are intended to designate the location and amount of chrome plating permissible to salvage worn parts. The heavy lines and the number adjacent indicate the surface to which chrome plate may be applied and the maximum permissible finished thickness of the chrome plating on that surface. This information applies only to those parts which bear the part number listed. Parts

which are chrome plated on a carburized surface shall be required to pass magnetic inspection for cracks after chrome plating and finishing.

NOTE

Most chrome plating processes are patented and permission to use them must be obtained from the licensor. As the work must be conducted under carefully controlled expert supervision, it is recommended by the Civil Aeronautics Administration that the plating operations be accomplished by the Wright Aeronautical Corporation or a Certified Repair Station in accordance with Wright Aeronautical Corporation specifications.




Figure 1
Crankshaft Machining and Balancing Assembly
Parts No. 47773, 48171, 49344, 411235, 411236, 411895,
413107, 413747, 414502, 414585, 415381, 417422




Figure 2
Crankshaft Machining and Balancing Assembly
Parts No. 40222, 44064, 44336, 44510, 44529, 44768, 44867,
44939, 45883, 46208, 46466, 47747, 48188, 48939, 415523




Figure 3
Crankshaft Machining and Balancing Assembly
Parts No. 414547, 414586, 414588, 414711, 414824





Figure 4
Crankshaft Machining and Balancing Assembly
 Parts No. 47221, 48084, 48814, 48908



**Crankshaft
 Gear Hub**
 Parts No.
 28504, 67900

Figure 6





Figure 5
Master Connecting Rod
 Parts No. 22134, 67357



Master Connecting Rod
 Parts No.
 21942, 67358, 117911

Figure 8




Figure 7
Crankshaft Rear Bearing
 Parts No. 25088, 64836




Figure 9
Crankshaft Gear Hub
 Parts No. 28008, 28013, 68047




Figure 10
Crankshaft Rear Bearing
 Parts No. 25088, 64836

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: ACID ETCHING PARTS—INSTRUCTIONS FOR
MODELS AFFECTED: Whirlwind—All

Bulletin No. W-15A
Page 1 of 1

Date: April 21, 1945

This bulletin supersedes Service Bulletin No. W-15, dated
September 9, 1944, in order to include additional information.

GENERAL PRECAUTIONS

This information will establish a procedure for acid etching parts for identification purposes. If the etching is accomplished in a careless manner there is the possibility of a corrosive action being set up where the part has been stamped. Before attempting to etch or to stamp good usable parts, it is recommended that some rejected parts be stamped for practice purposes.

Acid etching equipment must be handled and stored carefully as acid fumes easily contaminate parts in their vicinity. When in use, keep the acid and rubber stamp as far from the neutralizer and swabs as possible. When the equipment is not in use, keep the acid well covered and isolated from any parts.

To prevent possible corrosive action, do not touch the area being etched. To prevent injury, keep the hands from direct contact with the acid.

PROCEDURE

1. Clean the part at the location to be etched.

Parts coated with engine oil or low viscosity slushing compound require only that the area to be stamped be wiped clean, as the remaining film of oil protects the surface of the work from rust and corrosion, also the film of oil is thin enough to permit the etching acid on the rubber stamp to penetrate.

Make certain that the correct acid is used for etching. Use etching fluid corresponding to Wright Aeronautical Corporation Specification No. 300 (Part No. 87940) when etching steel parts. Use etching fluid corresponding to Wright Aeronautical Corporation Specification No. 301 (Part No. 850335) when etching bronze or nitralloy parts.

2. Press the rubber stamp to the acid pad. To assure that more acid than necessary does not remain on the part, blot the stamp on a clean white blotter or cloth before applying it to part.

3. Apply the stamp firmly to the surface to be etched.

4. Remove the stamp. Let the acid remain on the part for at least 30 seconds.

5. Apply a cotton swab containing a neutralizing agent to the area. Press down with a blotting motion and then lift the swab carefully from the surface. Do not smear or rub with the swab.

Make certain that all acid is positively neutralized.

As the neutralizing agent consists of water and oil, it is not necessary that it be removed because the water will evaporate and leave a film of oil as a protective covering.

6. After the etching is completed, coat each part with a suitable corrosion preventive.

Replace the stamp when necessary.

SPECIAL EQUIPMENT REQUIRED

1. Blue acid conforming to Wright Aeronautical Corporation Specification 300 (Part No. 87940, supplied in one pint bottles) to be used when etching all steel parts.

2. Green acid conforming to Wright Aeronautical Corporation Specification 301 (Part No. 850335, supplied in one pint bottles) to be used when etching all bronze and nitralloy parts.

The colors are an additional safeguard against an incorrect choice of acids.

3. Neutralizer conforming to Wright Aeronautical Corporation Specification 62.

A neutralizer may be made by mixing one part of any soluble cutting oil or grinding oil to three parts of water. The volume of neutralizer mixed should be about three times the amount needed. This will assure enough excess solution to neutralize any acid carried into the container by the swab.

Make certain that the neutralizer is always alkaline. Use red litmus paper to test the solution. If the paper turns blue when it is placed in the neutralizer, the solution is alkaline. If the paper remains red under the same conditions the solution must be discarded.

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF COLUMBIA-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PREPARATION OF ENGINES FOR
STORAGE OR SHIPMENT

Bulletin No. W-16A
Page 1 of 5

MODELS AFFECTED: Whirlwind R760E and R975E

Date: February 17, 1947

This bulletin supersedes Service Bulletin No. W-16 dated
September 14, 1944 in order to standardize procedures.

Protect all engines which are to remain idle, to be
stored, or to be shipped, in accordance with the in-
structions contained in specification AN-E-11 or spe-

cification AMS 2570A, which is included in this bul-
letin and reprinted with the permission of the copy-
right owner.

AERONAUTICAL MATERIAL SPECIFICATION

SOCIETY OF AUTOMOTIVE ENGINEERS, INC.

29 WEST 39TH STREET

NEW YORK CITY

Copyright 1945 by Society of Automotive Engineers, Inc.

AMS 2570A

Issued 6-1-42

Revised 11-1-45

PRESERVATION OF ENGINES

1. PURPOSE

To provide a procedure for preparing reciprocating aircraft engines to resist corrosion during shipment and storage.

2. MATERIAL AND EQUIPMENT

The latest revision of the following specifications and standards shall be applicable:

AMS 3070—Oil, Corrosion-Preventive (Carburetor Slushing)

AMS 3072—Compound, Corrosion Preventive (Aircraft Engine)

AMS 3075—Compound, Corrosion Preventive (Parts and Equipment)

AMS 3160—Solvent, Petroleum

AMS 3420—Agent, Dehydrating

AMS 3535—Moisture Vapor Resistant Sheet

AMS 3540—Wrapper—Greaseproof

AMS 3542—Wrapper—Greaseproof Paper (Laminated)

AMS 3610—Plastic Film—Transparent, Moisture-Resistant

AS 6—Enclosure, Storage and Shipping

AS 7—Plug, Cylinder Dehydrator

AS 8—Plug, Crankcase Dehydrator

AS 9—Protector and Cable Attachment

AS 10—Indicator, Humidity—Large

AS 11—Equipment, Spray

AS 160—Collar—Propeller Shaft, Shipping

AS 172—Nut, Propeller Shaft, Shipping

AS 173—Cap, Propeller Shaft, Shipping

AS 338—Shipping Containers, Aircraft Engines and Components

AS 347—Indicator, Humidity, Medium

ARP 197—Preservation and Packaging of Aircraft Engine Parts

3. SLUSHING PROCEDURE

It is recommended that the sequence of operations specified in this section be followed in all essential details and for best results should be accomplished within 48 hours, except as otherwise specified.

(a) **Crankcase Sections.** The engine shall be securely mounted in its normal running position. In this position the engine shall be driven from an external source of power or operated under its own power at a crankshaft speed of not less than 500 rpm. While running at this speed the engine lubricating system shall feed from a reservoir of preservative oil, AMS 3072. During this operation the oil shall be maintained within the temperature limits of 215-260°F. If because of peculiarities of individual installations it may not be practical to retain the temperature at or above the low limit without exceeding the high limit, then the high limit (260°F) shall be the controlling temperature. The engine shall be operated for a minimum 15 minutes under the above conditions.

(b) **Cylinder Bores.** The above procedure shall be supplemented by spraying the cylinder bores with preservative oil, AMS 3072, by one of the following methods:

(1) **Aspirating.** Within the last two minutes of the above specified slushing run, while the engine is turning over, the preservative oil, AMS 3072, under pressure, shall be aspirated through the induction system. The quantity of compound to be used to insure adequate coverage, and the procedure, should be determined for each individual engine model. The

engine shall be shut down immediately after this operation.

(2) **Gun Spraying.** As an alternate procedure the cylinder bores may be preserved by the following procedure. At the end of the engine run using the preservative oil as a lubricant, the fuel supply shall be cut off and the engine speed accelerated at the time the ignition is switched off. Within two hours from the shut down time each cylinder of the engine shall be sprayed with preservative oil, AMS 3072, through a spark plug hole with the piston at the bottom of stroke. This operation may be done on cylinders in firing order. Twenty-five milliliters of oil is considered adequate for each cylinder provided application is conducted in a manner to ensure complete coverage. (See AS 11 for recommended equipment.)

(c) **Oil and Coolant Drainage.** Preferably while the engine is still warm from the procedure specified in paragraph 3(a) excess oil shall be drained from the engine crankcase, filter or screen chambers, and/or sump(s). Screens or filters shall be removed, cleaned, slushed with preservative oil, AMS 3072, and replaced. The coolant shall be drained from liquid cooled engines and the coolant chambers dried. All drain plugs shall be replaced and safetied.

(d) **Cam and Rocker Boxes.** Within three hours after the procedure specified in paragraph 3(a), all valve mechanism such as cam shafts, rockers, springs, washers, valve stems and interior of housings and rocker boxes shall be thoroughly coated with preservative oil, AMS 3072. This preservative oil shall be applied preferably by spraying using pressure gun equipment. Covers which have been removed to accomplish this operation shall be cleaned and reinstalled.

(e) **Exhaust Ports.** The exhaust ports shall be sprayed directly with preservative oil, AMS 3072, so as to coat thoroughly the opened exhaust valves as well as the port walls. Seal the exhaust ports with oil and moisture-resistant covers or gasketed plates. Where an exhaust manifold is supplied on the engine prior to shipment see instructions contained in paragraph 4(d).

(f) **Accessory Drives.** The ends of accessory drives for which oil seals are provided shall be thoroughly coated with preservative oil, AMS 3072. Covers or cover plates with gaskets shall be installed over all accessory drives.

(g) **Cylinder Bore Preservation.** Before the engine has been prepared for final packing the cylinders shall be sprayed again in the manner described in paragraph 3(b)(2). The propeller shaft shall then

be turned at least six revolutions and the cylinders re-sprayed without moving the pistons. The cylinders shall then be thoroughly drained of excess compound through the spark plug holes. Sufficient time shall elapse for sufficient draining to ensure against the danger of subsequent hydraulic damage to cylinders and moving parts. The use of a suction gun to facilitate removal of this drained compound is recommended. After this operation a temporary tag shall be tied to the propeller shaft with the warning note "DO NOT TURN PROPELLER SHAFT."

(h) **Cleaning.** Where necessary the external surfaces of the engine may be cleaned with petroleum solvent, AMS 3160 or equivalent.

4. DEHYDRATING PROCEDURE

(a) **Cylinder Dehydrators.** Cylinder dehydrator plugs, conforming to AS 7, shall be installed in each spark plug opening and tightened to the torque recommended in AS 7 for the applicable plug size. The moisture seal shall not be removed from the end of the dehydrator plug until immediately before the plug is installed.

(b) **Crankcase Dehydrators.** All openings to the interior of the engine such as breathers and oil connectors shall be plugged or suitably sealed with oil and moisture resistant closures. The oil sump plug or closure(s) of other selected opening(s) shall be removed and replaced with a crankcase dehydrator plug of suitable size. The dehydrator plug shall be tightened to the torque specified for applicable plug size listed in AS 8. The removed plugs and or closures shall be attached to engine together with suitable instructions for removing dehydrator and reinstalling permanent plugs or covers. The quantity of crankcase dehydrators shall be installed according to the following schedule:

| Engine Weight Pounds | Weight of Desiccant Grams Minimum | Minimum No. of Plugs AS 8 |
|----------------------------|--------------------------------------|------------------------------|
| Up to 500 | 20 | 1 |
| 500 to 1000 | 40 | 1 or 2 |
| 1000 $\frac{1}{2}$ to 2000 | 40 | 2 |
| 2000 $\frac{1}{2}$ to 3000 | 60 | 2 |
| 3000 $\frac{1}{2}$ to 4000 | 80 | 3 |

The moisture seals shall not be removed from the ends of dehydrators until immediately before plugs are installed.

(c) **Induction Port Dehydrators.** Dehydrating agent, contained in a sift-proof bag, as specified by AMS 3120 shall be installed at the entrance to the air induction system to the engine according to the following schedule:

| Cylinder Displacement per Engine Cubic Inches | Desiccant Quantity, AMS 3420—Grade E Ounces Minimum |
|---|---|
| Up to 1000 | 4 oz. |
| 1000 $\frac{1}{2}$ to 2000 | 8 oz. |
| 2000 $\frac{1}{2}$ to 3000 | 12 oz. |
| 3000 $\frac{1}{2}$ to 4000 | 16 oz. |
| 4000 $\frac{1}{2}$ | 16 oz. $\frac{1}{2}$ oz./1000 cu. in. or fraction thereof. |

The above quantities may be interpolated to more exact amounts for actual "cylinder displacement." Where openings in small engines are not of sufficient size to accommodate the above specified amounts of desiccant a bag of dehydrating agent as large as practicable shall be used. Where the carburetor is shipped installed in its operating location the desiccant shall be placed at the induction entrance of the carburetor. A conspicuous warning tag or notice shall be provided to indicate presence of the dehydrating agent and need for removal prior to engine operation. Handling of the desiccant shall be held to a minimum and shall always be installed in the engine immediately after removal from its closed shipping container. The intake manifold or carburetor opening shall then be immediately sealed with a gasketed cover or plate securely fastened in place. It is desirable to have the bags containing dehydrating agent installed in such a manner that they will be removed with the cover or observed when cover is removed.

(d) Exhaust Manifold. When an exhaust manifold is shipped attached to the engine, a one-half pound bag of dehydrating agent, AMS 3420, Grade E, shall be installed in the opening(s) of the collector ring or rings and the opening(s) closed with an oil and moisture resistant diaphragm(s) or sealing cover(s). A conspicuous warning tag indicating the presence of the dehydrating material shall be fastened adjacent to the opening. The dehydrating agent shall be installed directly from its closed shipping container.

(e) Propeller Shaft Breather. Where a propeller shaft breather is provided with sufficient space a one-quarter pound bag of dehydrating agent, AMS 3420, Grade E, shall be located inside the propeller shaft thread protector cap with provision for its removal with the cap. The bag of dehydrating agent shall not be removed from its closed shipping container until immediately before installation.

5. PACKING PROCEDURE

All ends of locking wire shall be bent inward or covered with tape to prevent rupture of engine envelope. All loose ends of pipes, ignition leads, etc., shall be secured in place to prevent chafing of engine envelope. The spark plug leads may be supported in shipment by fastening the terminal protector, AS 9, to the end of each cylinder dehydrator plug. Remove warning tag from end of propeller shaft having warning note "DO NOT TURN PROPELLER SHAFT."

(a) Engine Envelope. An envelope incorporating, in general, the requirements of AS 6 shall be fitted to the shipping case saddle, anchor plate or to the engine, whichever is more convenient. Holes for the anchor belts shall be punched and the belts inserted to hold envelope in position. The shipping case saddle or anchor plate together with envelope shall then be fitted to the engine taking care not to tear the envelope. The engine and envelope with attaching components shall be then secured to the shipping container. This procedure may be varied at the discretion of the shipper, provided the anchor plate or saddle is removable with the engine.

(b) Shipping Container. The engine shipping container shall conform to the requirements of AS 338 where applicable.

(c) Dehydrating Agent. Bags of dehydrating agent, AMS 3420, Grade E, shall be uniformly distributed around the engine at the rate of one pound per cylinder for engines up to and including 14 cylinders. For engines with more than 14 cylinders the recommended minimum of 14 pounds shall be supplemented by the addition of dehydrating agent at the rate of at least one pound per each additional two cylinders. Not less than a half pound per pound weight of paper, etc., shall be added to provide for dehydration of the dunnage within the shipping envelope. The dehydrator bags shall not be removed from closed shipping container until immediately before attachment to the engine.

(d) Humidity Indicator. A humidity indicator, AS 10 or AS 347, shall be secured to the engine opposite the inspection port in the shipping container in a manner to be readily observed from outside the encased engine by lifting the inspection port cover.

(e) Creped paper, canvas, or other suitable covering shall be placed around the periphery of radial engines and other locations as required to prevent damage to the shipping envelope which might result from chafing on projections. For in-line engines the covering shall be placed so as to provide maximum protection.

(f) Propeller Shaft. Exterior surfaces of the propeller shaft shall be coated thoroughly with preservative oil, AMS 3072, or preservative compound, AMS 3075. A thread protector cap, AS 173, shall be installed, and the splines covered with greaseproof paper, AMS 3540 or AMS 3542. Any surface of the propeller shaft exterior to the engine envelope must be coated with preservative compound, AMS 3075.

(g) Propeller Shaft. (Alternate Method) When it is contemplated that the engine will be handled while in storage with the aid of a lifting eye applied to the end of the propeller shaft a hole shall be care-

fully cut to the inside diameter of the large gaskets provided near the open end of the shipping envelope. Shipping parts AS 160, AS 172, and AS 173 shall be applied in proper sequence as explained in AS 6. The propeller shaft splines shall be coated and wrapped as detailed in paragraph 5(f). With this arrangement for shipping an additional band of grease-proof paper, AMS 3540 or AMS 3542 shall be applied to the cone seat and shall be of sufficient width to extend to the top of the gasket area. This will provide insulation from contact corrosion between the envelope material and the propeller shaft. The threads, cone seat, and inside of the propeller shaft shall be thoroughly coated with corrosion-preventive compound, AMS 3075, before shipping parts are installed. A second application of corrosion-preventive compound to the threads after installation of nut and before installation of thread protector cap is recommended.

(h) **Envelope Sealing.** The engine shipping envelope shall be heat sealed (using a temperature within the range specified on the envelope identification panel) as soon as practicable after attaching dehydrator bags as specified in paragraph 5(c). In so doing, the envelope shall be unfolded and the open edges brought together and sealed under heat and pressure so as to provide a continuous moisture-proof seam. Excess air within the envelope shall be removed by the use of a suitable exhaust fan to assist in folding the envelope around the engine, but not to an extent which will cause damage to the envelope.

(i) After the sealing operation the excess material of the envelope shall be folded around the engine and secured with tape in a manner to provide a minimum size package. The envelope should be so arranged as to permit unobstructed visibility of the humidity indicator.

(j) **Closure of Shipping Container.** The engine container sides and/or cover shall be assembled over the envelope enclosed engine in such a manner as not to rupture the envelope. The humidity indicator contained within shall be carefully examined through inspection port in the side of the container for suitable alignment and visibility. The inspection port cover shall be closed and sealed and the container secured for shipment.

(k) **Marking.** In addition to dispatching information which may be special for each consignment the shipping container shall be marked as specified in AS 338.

6. ACCESSORIES

Preservative oil, AMS 3077, may be used for the preservation of accessories except carburetors, and other units which contain elements such as synthetic

rubber diaphragms which may be damaged by this compound. Unless the recommendations of the accessories manufacturers are otherwise, these "excepted" accessories shall be preserved with oil conforming to AMS 3070.

(a) **Carburetor Slushing.** The carburetor shall be emptied of all residual gasoline and shall be filled with oil, AMS 3070. Interior surfaces shall be thoroughly slushed in accordance with manufacturers' instructions. Care shall be exercised not to damage moving parts such as needle valves or float (where provided). When flushing a pressure-type carburetor the oil pressure applied to fuel chambers or passages shall not exceed eight pounds per square inch. Under no circumstances shall the regulator air chambers, air passages, and/or automatic mixture control be flushed with oil; these must be kept dry at all times. Drain excess oil from all fuel passages and replace plugs or cover plates. When the carburetor is shipped attached to the engine lock the throttle plates in the open position.

(b) **Carburetor Packing.** When the carburetor is shipped disassembled from the engine the throttle plates shall be locked in a position which will prevent damage during shipment. For this method of shipment the carburetor shall be sealed within a moisture-resistant enclosure fabricated of material conforming to either AMS 3610 or AMS 3535. The enclosure shall contain dehydrating agent, AMS 3420, Grade E, in quantity as calculated by the following formula:

$$\text{Pounds of dehydrating agent} = \frac{A + D}{10} \frac{1}{2}$$

A = Area in square feet of the moisture-resistant enclosure.

D = Weight of Hygroscopic dunnage in pounds.

The minimum quantity of dehydrating agent shall be one-half pound. The dehydrator bags shall not be removed from their closed shipping container until immediately before applying to the carburetor. A humidity indicator conforming to AS 347 shall be fastened to carburetor in a conspicuous location before enclosure is sealed.

(c) All accessories and auxiliaries to be shipped with the engine shall be packed in accordance with ARP 197.

7. MAINTENANCE

(Inspection and re-preservation will not be the responsibility of the engine manufacturer after engines have been shipped from the engine manufacturer's plant.)

(a) **Inspection of Engines in Storage.** Engines shall be inspected periodically, preferably monthly, to ascertain the relative humidity prevailing within the engine envelope. If the relative humidity is above 20% the atmosphere contains sufficient moisture to cause corrosion. The humidity indicator, secured to the engine opposite the inspection port of the shipping case, affords a convenient means of approximating the relative humidity. By matching the color of the indicator dehydrating agent with the color scale printed on the front of the Humidity Indicator, AS 10 or AS 347, an inspector may quickly determine if an engine must be re-preserved. The indicating agent used in the humidity indicator is deep blue in color when dry, but fades to a lighter shade of blue or pink, depending on the degree of moisture absorbed.

(b) **Re-preservation of Engines During Storage.** When moisture within the engine envelope has increased to an unsafe amount, as shown by the Humidity Indicator, AS 10 or AS 347, the engine envelope shall be opened by cutting off the seal and the engine re-preserved by replacing all old dehydrating agent with freshly activated dehydrating agent, and installing a new Humidity Indicator. Likewise,

the dehydrator plugs which have a color matching an unsafe shade on the color scale of the Humidity Indicator shall be replaced. As soon as this is accomplished, the engine envelope shall be re-sealed.

NOTE

The dehydrator bags shall not be removed from their moisture resistant containers, nor the moisture seals removed from dehydrator plugs until immediately before application to the engine.

(c) **Re-Sealing and Repairing Damaged Engine Envelopes.** An engine envelope shall be re-sealed, using an iron heated to the temperature recommended on the envelope identification panel. Ruptured envelopes may be repaired by heat-sealing a patch of the envelope material over the opening or by sealing the open edges of a straight tear.

NOTE

SIMILAR SPECIFICATION

Army-Navy Aeronautical AN-E-11 is listed for information only and shall not be construed as an acceptable alternate unless all requirements of this AMS are met.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: INSTALLATION OF SPLIT TYPE INNER RACE
THRUST BEARING

Bulletin No. W-17A

Page 1 of 1

MODELS AFFECTED: Whirlwind R760E and R975E

Date: August 19, 1946

This bulletin supersedes Service Bulletin No. W-17, dated October 2, 1944, to provide additional information.

Thrust bearing, part No. 21D101, currently supplied to replace the thrust bearing, part No. 21D68, in the above engine models except as indicated below, differs from the earlier type in that it has a smaller inside diameter, a puller flange on the propeller end, and a split inner race. Its tighter fit reduces movement of the inner race on the crankshaft and decreases end float of the crankshaft. The puller flange which acts as an oil slinger ring eliminates the need for an additional slinger and permits easier removal of the bearing. In addition, the bearing life is increased.


When replacing the thrust bearing in service engines, install bearing, part No. 21D101, except as noted below. If bearing, part No. 21D68, was used,

it will be necessary to discard the oil slinger and to either use a new thrust nut, part No. 120889 for number 20 spline crankshafts and part No. 117908 for No. 30 spline crankshafts, or rework the old nut as indicated by the illustration.

Exception—Thrust bearing, part No. 21D101, cannot be used on R760E and R975E engines incorporating a crankcase front section with a 6.313 inch diameter front cover bolt circle because of interference with the thin type crankcase front cover, part No. 21554. Bearing, part No. 21D68, must be retained in this assembly along with the oil slinger ring and thrust nut being used.

SPECIAL TOOLS REQUIRED

| Tool No. (Bearing, Part No. 21D68) | Tool No. (Bearing, Part No. 21D101) | Name |
|--|---|---|
| 82932 | 82932 | Wrench, propeller shaft (20 spline) thrust bearing nut lug |
| 82934 | 82934 | Wrench, propeller shaft (30 spline) thrust bearing nut lug |
| | 805055 | Puller, front crankshaft thrust bearing inner race spacer and gear removing |
| | 805056 | Adapter, puller |
| | 805057 | Adapter, puller |
| | 803151 | Clamp, crankshaft thrust bearing nut oil seal ring installing |
| 802198 | | Puller, crankcase front section removing |



WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

WOOD-RIDGE, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: TIMING SERRATIONS—INCREASED DIAMETER OF

Bulletin No. W-18

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: September 4, 1944

This bulletin supercedes Service Bulletin No. 425 dated December 3, 1942, to revise the parts list and change the title.

Early production engines provided a one inch diameter meshing surface of the timing serrations on the starter drive gear and cam drive pinions. Engines of more recent production incorporate a modified starter drive gear and cam drive pinion which increases the meshing surface of the timing serrations to a two inch diameter. This was done to assure more positive engagement of these serrations. It is recommended that service engines that do not incorporate this change have the following parts replaced: starter shaft, starter shaft bolt, starter shaft bolt nut, starter drive gear and cam drive pinion, and cotter pin. The incorporation of a pin having a .116 inch

diameter provides a stronger lock for the nut, but, before this size pin can be installed, the starter shaft bolt nut must be reworked.

REWORK Rework the nut in the following manner:

1. Redrill the cotter pin holes in the starter shaft bolt nut with a .125 inch drill.
2. Chamfer the holes at 45 degrees to a .15 inch diameter.
3. Remove the burrs from the nut threads by running a standard 1/2-20 USF tap through the nut.

PARTS REQUIRED

| Quantity | | Part No. | Part Name |
|----------|-------|----------|---|
| R760E | R975E | 65693 | Starter Shaft |
| 1 | 1 | 48728 | * Starter Drive Gear and Cam Drive Pinion |
| 1 | | 49463 | * Starter Drive Gear and Cam Drive Pinion |
| 1 | 1 | 65694 | Starter Shaft Bolt |
| 1 | 1 | 124D87 | Starter Shaft Bolt Nut |
| 1 | 1 | 59D1 | Cotter Pin |

*Detail parts of the starter drive gear and cam drive pinion will not be supplied separately. These parts must be kept clamped together until assembled to prevent mismatching and to avoid mutilation of the serrations.

WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: ENGINE DRIVEN ROCKER BOX LUBRICATOR—
OPERATION OF

Bulletin No. W-19
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: February 14, 1945

This bulletin reinstates Service Bulletin No. 281, dated December 17, 1936,
since the information is still applicable.

The purpose of this Service Bulletin is to supply information regarding the installation and proper adjustment of the engine driven rocker box lubricator with which some engines are equipped.

The lubricator may be installed to operate satisfactorily in either direction of rotation. If rotation is in the direction indicated by the arrow and 1-1 stamped on the flange of the mounting pad, the housing cover should be installed so that the numbers 1 on the cover and body will index. If, however, rotation is in the opposite direction to that indicated by the arrow, then the housing cover should be installed so that the number 2 indexes with 2 on the housing.

The lubricator should be adjusted to secure an oil flow of from one-quarter to one-half pint per hour at rated engine speed. If a test rig is not available, the flow may be measured with the lubricator on the engine. With the engine thoroughly warmed up, remove the discharge line so that the oil from the lubricator flows into a small graduated measure. Run the engine at rated

speed for ten minutes and note the amount of oil collected. Multiplying the amount by six will give the flow per hour. The rate of flow may be changed by loosening the adjusting screw and altering the position of the adjusting washer with respect to the scale stamped on the cover. Movement of the washer so that its reference line indexes with higher numbers on the scale will increase the rate of oil flow. It should be noted, however, that the numbers on the scale do not denote any specific flow in terms of pints or pounds per hour.

When installing or removing the lubricator tubes, two wrenches should be used on the fittings in order to prevent twisting and damaging the rubber tubing. Some free movement in the fitting which attaches the tube to the rocker hub bolt is permissible since there is a conical seat at the connection which seals the passage.

To ensure an adequate supply of lubricant the rocker boxes should be filled with engine oil whenever the rocker box covers are removed.

WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: BLOCK TESTING OF OVERHAULED ENGINES

Bulletin No. W-20

Page 1 of 2

MODELS AFFECTED: Whirlwind—All

Date: February 8, 1945

This bulletin cancels and supersedes Service Bulletin No. 570 dated April 21, 1943 in order to bring the information up to date.

The information contained in this Service Bulletin is intended to establish standard run-in specifications and various operating limits for overhauled engines.

RUN-IN FOLLOWING TOP OVERHAUL No run-in is necessary on engines which have undergone top overhaul;

that is, the restoration of valves, pistons, piston rings and cylinders to service limits. Ground running to check the installation of the engine in an aircraft should be held to a minimum. Any "slow" time that is desired should be obtained in flight, since prolonged ground running of engines installed in aircraft may result in excessive cylinder barrel temperatures, thus causing piston ring feathering and allied troubles.

RUN-IN FOLLOWING MAJOR OVERHAUL In order to test the operating characteristics of engines which have undergone a major overhaul, test stand equipment should be provided from which the necessary readings of temperatures, pressures, fuel and oil flows and engine speeds may be taken. Specifications and detail drawings of this equipment may be procured from Wright Aeronautical Corporation.

A sufficient number of properly calibrated test propellers should be maintained to compensate for variations in climatic conditions. The test propeller used during the run-in should provide, within plus or minus two percent, a normal rated manifold pressure at a speed within plus or

minus two percent of normal rated RPM. Since values of manifold pressure are taken from propeller load curves, the run-in may be conducted using values of engine speed for the criterion of power output. At rated and take-off powers, manifold pressure and engine speed must both agree with the specified values.

The use of standard or cut-down flight propellers in place of test propellers is not approved unless such propellers are provided with cuffs or fans to provide satisfactory cylinder barrel cooling.

Tests should be conducted with fuel of the grade specified for normal operation of the engines, and the carburetor mixture control should at all times be set at the "Full Rich" position.

During block test operation, the use of power and fuel flow curves is not considered necessary for the determination either of brake horsepower or of brake specific fuel consumption. Since the brake horsepower values computed from the curves are found from MAP and RPM readings, the attainment of the proper manifold pressure and speed may be regarded as the criterion of engine performance, while carburetor acceptance should be based on the flow bench test, and the BSFC may then be calculated, if desired, as a secondary check.

Run-ins in accordance with the following schedule are recommended for all engines after major overhaul.

| Item No. | Duration in Minutes | Operation | % of Normal Rated Speed | Approx. % of Normal Rated Power | Approx. % of Normal Rated MAP |
|----------|--|-------------------|-------------------------|---------------------------------|-------------------------------|
| 1 | 5 | Start and Warm-Up | 45 | | |
| | 5 | Endurance | 58 | 25 | 25 |
| 3 | 10 | Endurance | 68 | 30 | 30 |
| 4 | 10 | Endurance | 74 | 40 | 65 |
| 5 | 45 | Endurance | 84 | 60 | 75 |
| 6 | 60 | Endurance | 95 | 85 | 95 |
| 7 | 30 | Endurance | 100 | 100 | 100 |
| 8 | Idle for 2 minutes; accelerate to take-off RPM and MAP for 1 minute. | | | | |

During operation under Item 5 of the schedule, a magneto check should be conducted. Loss of engine speed while operating on one magneto must not exceed 75 RPM.

When operating under Item 8, it will occasionally be necessary to install another test propeller

in order to obtain RPM and MAP within plus or minus two percent of take-off values.

The following table presents various engine operating limits during block test operation of overhauled engines.

| Engine Model | Main Oil Pressure PSI | Minimum Nose Oil Pressure PSI | Maximum Oil Consumption at Normal Rated Power, Qts/Hr | Maximum Cylinder Head Temperatures—°C at % of Normal Rated Power | | | Maximum Oil Flow at Normal Rated RPM—Lbs/Min. |
|--------------|--------------------------|----------------------------------|---|---|--------|----------|---|
| | | | | 0-70 | 70-100 | Take-off | |
| R760E2 | 60-80 | 25 | 2 | 205 | 232 | 260 | 15 |
| R975E3 | 60-80 | 25 | 3 | 205 | 232 | 260 | 20 |

Oil flow readings should be taken at 185°F (35°C) oil-in temperature.

SERVICE BULLETIN

WRIGHT AERONAUTICAL CORPORATION

TITLE: STARTER DRIVE GEAR BUSHING,
REMOVAL AND INSTALLATION OF

MODELS AFFECTED: Whirlwind—All

Bulletin No. W-21
Page 1 of 4

Date: November 4, 1944

This bulletin supersedes all instructions previously issued on removal and replacement of starter drive gear bushings.

The purpose of this bulletin is to present the most recently established procedure for removal and installation of the starter drive gear bushing.

PROCEDURE 1. With a standard .120 inch punch, drive the lock pin from the diffuser section and starter drive gear bushing. See figure 1.

2. Place the diffuser section on the collar, Tool No. 800556-2, and insert a plug, Tool No. 800556-1, into the bushing. Press out the bushing with an arbor press contacting the plug. See figure 2.

3. Plug all oil passages and channels with beeswax or paraffin.

4. Chamfer and face the starter bushing hole to the dimensions shown in figure 3. Use cutter, Tool No. 800557.

5. Dewax the diffuser section by heating it in a 135°C (275°F) oil bath for 20 minutes. Blow out the holes with hot 49°C (120°F) kerosene at approximately 20 pounds per square inch pressure.

Allow the section to cool before proceeding with the operation.

6. Place the diffuser section on the collar, Tool No. 800556-2 and install a bushing, Part No. 111975, pressing it into place with a plug, Tool No. 800556-1 and arbor press as shown in figure 4. Hold the force on the bushing for a few minutes until it settles in place.

CAUTION

Assemble the bushing so that the oil hole in the bushing is more than 45 degrees away from the pin hole in the diffuser section. See end view, figure 5.




Figure 1




Figure 2




Figure 3

Check with a .0015 inch feeler gage between the bushing flange and the housing. When the bushing is properly installed, the feeler gage will not enter at any point. When the feeler gage does enter at any point, apply additional force to correct this condition.

7. Plug all oil passages or channels with beeswax or paraffin.

8. Clamp the jig, Tool No. 800558, in the bush-

ing and set the assembly at a 45 degree angle as shown in figure 5.

9. Install the drill bushing, Tool No. 800558-2, in the jig and drill through the bushing with drill, Tool No. 800559.

10. Replace the drill bushing with the reamer bushing, Tool No. 800558-3, and ream out the hole with reamer, Tool No. 83794.




Figure 4




Figure 5

Check the finished hole with the plug gage, Tool No. 83795.

11. With a standard .120 inch punch, drive a new lock pin, Part No. 13D42, into the hole so that it extends to within .01 to .03 inch of the inner diameter of the bushing. Peen metal over the outer end of the pin. See figure 6.

12. Assemble the diffuser section to the crankcase rear section.

13. Insert the reamer pilot bushing, Tool No. 83043-2, in the crankcase bushing and ream out the starter shaft bushing with reamer, Tool No. 83043-1. See figure 7.

Check the inside diameter of the bushing with the plug gage, Tool No. 800579.

14. Dewax the diffuser section as described in step 5.

PARTS REQUIRED PER ENGINE

| Quantity | Part No. | Name |
|----------|----------|----------------------------|
| 1 | 111975 | Starter drive gear bushing |
| 1 | 13D42 | Lock pin |

SPECIAL TOOLS REQUIRED

| Tool No. | Name |
|----------|--------|
| 800556-2 | Collar |
| 800556-1 | Plug |
| 800557 | Cutter |




Figure 6

SPECIAL TOOLS REQUIRED

| Tool No. | Name | Tool No. | Name |
|----------|-----------------|----------|-----------------------|
| 800558 | Jig | 83795 | Gage |
| 800558-2 | Bushing, drill | 83043-2 | Bushing, Pilot reamer |
| 800559 | Drill | 83043-1 | Reamer |
| 800558-3 | Bushing, reamer | 800579 | Gage |
| 83794 | Reamer | | |




Figure 7

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: EXCESSIVE ENGINE VIBRATION—PREVENTION OF

Bulletin No. W-22A
Page 1 of 2

MODELS AFFECTED: Whirlwind—All

Date: December 27, 1944

This bulletin supersedes Service Bulletin No. W-22, dated November 7, 1944
to correct the information contained therein.

Occasional cases have been found of excessive-engine vibration caused by mismatching of parts by weight while assembling after overhaul. Since there is a possibility of such occurrences, it is the purpose of this bulletin to give weight combinations which will help the customer to eliminate or correct this condition.

The first chart lists the weight combinations which will, when assembled, effect a balanced engine. For example: a crankshaft requiring a master weight of 26.70 pounds, to be assembled in an R-760 engine, must be assembled with pistons weighing 2.20-2.24 pounds each, piston pins weighing .378 pounds each, articulating rods weighing 1.74 pounds each, and a master rod weighing 7.92 pounds. This chart gives the

possible variance in piston weights. The weight of a piston is stamped on the piston head.

The second chart gives the permissible variation of weights of the piston pins, the articulating rods and the master rod. The articulating rod weight represents the articulating rod assembled with bushings. The master rod weight represents the master rod with its bushing and bearing installed. These parts are not marked with their weight, but must be weighed by the operator.

CAUTION

These charts are a guide against which an assembly may be checked in order to assure balance. They must be used for that purpose only.

CHART No. 1

| Crankshaft Master Weight | Engine | Piston lbs | Piston Pin lbs | Articulating Rod lbs | Master Rod lbs |
|-----------------------------|--------|---------------|-------------------|-------------------------|-------------------|
| 26.70 | R-760 | 2.20-2.24 | .378 | 1.74 | 7.92 |
| 26.82 | R-760 | 2.20-2.24 | .378 | 1.74 | 7.92 |
| 27.33 | R-760 | 2.42-2.46 | .378 | 1.74 | 7.92 |
| 28.49 | R-760 | 2.33-2.37 | .516 | 1.74 | 7.92 |
| 28.80 | R-760 | 2.42-2.46 | .516 | 1.74 | 7.92 |
| 28.90 | R-760 | 2.42-2.46 | .516 | 1.74 | 7.92 |
| 29.64 | R-760 | 2.38-2.42 | .516 | 1.82 | 8.86 |
| 29.92 | R-760 | 2.33-2.37 | .516 | 1.82 | 8.86 |
| 30.00 | R-760 | 2.33-2.37 | .516 | 1.82 | 8.86 |
| 30.82 | R-760 | 2.67-2.71 | .516 | 1.82 | 8.86 |
| 30.87 | R-760 | 2.67-2.71 | .516 | 1.82 | 8.86 |
| 31.10 | R-760 | 2.72-2.76 | .516 | 1.82 | 8.86 |
| 32.55 | R-975 | 2.20-2.24 | .378 | 1.74 | 7.92 |
| 33.15 | R-975 | 2.20-2.24 | .516 | 1.74 | 7.92 |
| 34.24 | R-975 | 2.33-2.37 | .516 | 1.74 | 7.92 |
| 34.87 | R-975 | 2.33-2.37 | .516 | 1.74 | 8.20 |
| 35.07 | R-975 | 2.38-2.42 | .516 | 1.74 | 8.20 |
| 35.19 | R-975 | 2.38-2.42 | .516 | 1.74 | 8.20 |
| 35.32 | R-975 | 2.38-2.42 | .516 | 1.74 | 8.20 |
| 36.21 | R-975 | 2.33-2.37 | .516 | 1.82 | 8.64 |
| 36.38 | R-975 | 2.33-2.37 | .516 | 1.82 | 8.64 |
| 37.62 | R-975 | 2.67-2.71 | .516 | 1.82 | 8.64 |
| 37.90 | R-975 | 2.72-2.76 | .516 | 1.82 | 8.64 |

CHART No. 2
WEIGHT IN POUNDS

| Part | Nominal | Minimum | Maximum |
|------------------|---------|---------|---------|
| Master Rod | 7.92 | 7.855 | 7.985 |
| Master Rod | 8.20 | 8.18 | 8.22 |
| Master Rod | 8.64 | 8.575 | 8.705 |
| Master Rod | 8.86 | 8.795 | 8.925 |
| Articulating Rod | 1.74 | 1.705 | 1.775 |
| Articulating Rod | 1.82 | 1.79 | 1.85 |
| Piston Pin | .378 | .371 | .385 |
| Piston Pin | .516 | .506 | .526 |

There are two possibilities for interchangeability, both of which are listed in the first chart. Any required number of the pistons mentioned below may be used interchangeably:

1. Pistons weighing 2.33-2.37 pounds used on the R-760 or R-975 engines may be used interchangeably with pistons weighing 2.38-2.42 pounds listed for use on the same model engine.

The variance of weights between the pistons concerned is too small to affect the engine balance.

2. Similarly, pistons weighing 2.67-2.71 pounds are interchangeable with pistons weighing 2.72-2.76 pounds provided they are both designed for use on the same model engine.

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: PROPELLER SHAFT THRUST BEARING NUT—
LIMITS FOR REWORKING

Bulletin No. W-23
Page 1 of 1

MODELS AFFECTED: Whirlwinds—All

Date: November 14, 1944

During overhaul inspect the front face of the propeller shaft thrust bearing nut for possible galling. If such a condition exists, correct it by grinding sufficient material from the affected area to clean up the surface. If necessary, material may be removed from the front face of the nut to permit installation of the propeller retaining nut lock ring. In either case the maximum amount of material which may be removed is .015 inch in order that the hardened case is not completely ground off.

To prevent removal of too much material at subsequent overhauls, reworked nuts should be identified by acid- or electric-etching on the outer circumference of the nut the total amount which has been removed from the front face.

Rework all surfaces so that they are parallel, flat, square, and true as applicable within .002 inch full indicator reading.

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: REPLACEMENT OF IGNITION WIRE FERRULES WITH WASHERS

Bulletin No. W-24A

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: January 20, 1945

This bulletin supersedes Service Bulletin No. W-24, dated November 21, 1944 in order to present additional information.

To lessen the possibility of flashover at altitude the distance between the magneto end of the ignition cables and the nearest ground has been increased by replacing the ferrules assembled at this location with a flat washer. When flashover at altitude is suspected in service engines, replace all ferrules with washers.

PROCEDURE (1) Remove sufficient insulation from the magneto end of an ignition cable to expose one-half inch of wire.

(2) Insert and draw the wire through the hole in the center of the washer. See figure 1.

(3) Fan out the ends of the wire and bend the strands back through the slots in the sides of the washer.

(4) Secure the strands of wire between the washer and the cable as shown in figure 1. Perform this operation with special pliers or any suitable tool.

TOOLS REQUIRED

Tool No.
803826 or any
suitable tool


Tool Name
Pliers (See figure 2)

PARTS REQUIRED


Quantity
As required

Part No.
118995*

Name
Washer



Cable with Washer Installed (enlarged)
Figure 1



Tool No. 803828
Figure 2

A complete set of washers each of which is stamped with the number corresponding to its magneto terminal block location, is furnished under Part No. 853990. If this is desired, one of Part No. 118995 is also required for the booster ignition lead.

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U. S. A.

SERVICE BULLETIN

WRIGHT AERONAUTICAL CORPORATION

TITLE: COUNTERWEIGHT STOP—REWORK TO PERMIT
INSTALLATION OF LARGER COUNTERWEIGHT PINS

Bulletin No. W-25A
Page 1 of 1

MODELS AFFECTED: Whirlwind R-975


Date: December 27, 1944

This bulletin supersedes Service Bulletin No. W-25, dated November 27, 1944
in order to incorporate additional information.

Early engines incorporated crankshafts in which the crankpin bore was concentric with the crankpin. These crankshafts use small rear counterweight pins (.874-.876 diameter). More recent models used crankshafts in which the crankpin bore was eccentric to the crankpin. These shafts require large rear counterweight pins (.889-.891 diameter). This situation requires that the operator keep a supply of both large and small counterweight pins on hand for replacement purposes. The necessity for maintaining a stock of both part numbers may be obviated if when assembling concentric crankpin bore engines during overhaul, the rear crankshaft counterweight stop, Part No. 62984, is replaced

with stop, Part No. 112038. This will permit the larger pins, now required for eccentric crankpin bore engines only, to be installed on all engines.

REWORK If it is preferred, counterweight stops, Part No. 62984, provided they are otherwise satisfactory, may be reworked by removing material from the lower edge of the stop to the dimensions shown in the sketch. When performing the rework make certain that the surfaces are kept parallel, flat, square, and true to each other within .002 inch full indicator reading. After the rework is accomplished obliterate the old part number and stamp the part 112038.



WRIGHT AERONAUTICAL CORPORATION
A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PREVENTION OF EXCESSIVE WEAR OF
THE ACCESSORY DRIVE SHAFT SPLINES

Bulletin No. W-26

Page 1 of 1

MODELS AFFECTED Whirlwind—All

Date: November 27, 1944

This bulletin supersedes Bulletin No. 424 dated September 12, 1940.

In some cases corrosion and wear of the accessory drive splines have been experienced. This difficulty is apparently due to a lack of sufficient lubrication at this location. In order to prevent excessive wear caused by the condition, it is recommended that a soft felt plug saturated with engine oil be inserted in

the bottom of the spline hole of the accessory drive shaft prior to the installation of the mating accessory.

Make the felt plug circular, of a diameter equal to the inside diameter of the accessory drive shaft bore, and thick enough so that the space remaining in the drive shaft bore after the accessory is installed will be entirely filled.

WRIGHT AERONAUTICAL CORPORATION

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: UNAUTHORIZED CHANGES IN CARBURETOR SETTINGS

Bulletin No. W-27
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 6, 1944

This bulletin supersedes Service Bulletin No. 443 dated December 31, 1940,
so that it may be included in the new numbering system.

The Wright Aeronautical Corporation continually conducts extensive laboratory and dynamometer tests in order to determine the carburetor settings required for the various models of Wright aircraft engines. A strict adherence to these settings will aid in obtaining optimum performance and increased service life of these engines. When experiments at the factory indicate that a change in carburetor setting is desirable, operators

will be notified. Only changes recommended by the Wright Aeronautical Corporation will be considered authorized changes in carburetor settings.

The Wright Aeronautical Corporation will not be responsible for damage to an engine or for malfunctioning of an engine which may be traced to an unauthorized change of a carburetor setting.

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U. S. A.

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: CLEANING OF MASTER RODS

Bulletin No. W-28

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 6, 1944

This bulletin supersedes Service Bulletin No. 445 dated January 27, 1941,
so that it may be included in the new numbering system.

Investigation has indicated that certain types of cleaning solutions currently used for cleaning engine parts have a tendency to remove lead from the surface of copper-lead master rod bearings. For this reason it is recommended that the bore of the master rod bearing be protected from the solution while the rod is being cleaned.

PROCEDURE (1) Wipe the master rod bearing clean. Use a clean, lintless rag soaked in unleaded fuel. Do not polish, burnish, or attempt to clean bearings by any other means.

(2) Put suitable plugs in the oil holes in the bearing and install protectors, Tool No. 800924, on the master rod at the ends of the bearing. This will prevent the cleaning solution from coming in contact with the bearing.

(3) Degrease and clean the master rod thoroughly by immersing it in a bath of cleaning solution.

(4) After the rod is clean, remove it from the solution, rinse it in hot water, and then in Varsol. This is necessary to assure the complete removal of the cleaning solution.

(5) Remove the rod from the Varsol, remove the protectors and plugs, and rinse the master rod in hot water.

(6) Remove the master rod from the hot water and dry it in a suitable manner.

(7) After the rod is completely dry, coat it with a corrosion preventive conforming to Aeronautical Material Specification No. 3075.

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

A Division of Curtiss-Wright Corporation

PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

**TITLE: VALVE CLEARANCE ADJUSTING SCREW TAPERED-HEAD
LOCK SCREW**

Bulletin No. W-29A
Page 1 of 1

MODELS AFFECTED: Whirlwind 7 and 9

Date: January 10, 1945

This bulletin supersedes Service Bulletin No. W-29,
dated December 15, 1944 to include new information.

To eliminate the possibility of overstressing or insufficiently tightening the valve clearance adjusting screw tapered-head lock screw, the following tightening procedure is recommended:

1. Adjust the valve clearance in the usual manner to the proper value.
2. Tighten the lock screw until the adjusting screw is lightly locked. Test by feel with the standard adjusting screw screwdriver.
3. Mark a convenient point of the hex head of the lock screw with a non-permanent marking and make a corresponding indexing mark on the rocker arm. See figure 1.
4. Tighten the lock screw further by rotating the lock screw 120 degrees as closely as can be approximated using the marks as a guide. See figure 2. The points of the hex are 60 degrees apart.

The correct torque and stretch of the adjusting screw lock screw will thereby be obtained.

Engines not incorporating the tapered-head lock screw may be modified to include this screw, which requires no lock washer, by performing the following rework.

PROCEDURE

Before installing the new screw, cut a taper in the screw hole in the rocker arm:

1. Install the rocker arm in a fixture, tool No. 801415.
2. Countersink the screw hole to the dimensions shown in the figure 3. For this purpose use a countersink, tool No. 801416.
3. Check the operation with a flush pin gage, tool No. 801417.




Figure 1




Figure 2




Figure 3

WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTISS-WRIGHT CORPORATION
PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: PISTON RINGS AND CYLINDER BARRELS—
PRE-LUBRICATION OF

Bulletin No. W-30

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 27, 1944

This bulletin supersedes Service Bulletin No. 580, dated February 23, 1943
so that it may be included in the new numbering system.

It is recommended that castor oil be applied during assembly in place of engine oil as a pre-lubricant for pistons, rings, and cylinder barrels. Engine oil tends to drain away before the engine is ready for operation, leaving the rings and cylinder walls without lubrication when the engine is first started until the regular oil supply becomes available. Castor oil will adhere to the parts much more effectively. It will not be wiped away as easily by the rings when the crankshaft

is turned during subsequent assembly operations, and it will not be washed away by gasoline when the engine is primed.

Before installing the cylinder, coat the side walls of the piston assembly, particularly the rings and lands, and also the lower 3 or 4 inches of the cylinder barrel. Avoid the use of too much oil as any surplus draining into the combustion chamber may cause fouling of the spark plugs.

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PROTECTION OF CYLINDER IDENTIFICATION
NUMBERS

Bulletin No. W-31
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 30, 1944

This bulletin supersedes Service Bulletin No. 523, dated April 10, 1942
so that it may be included in the new numbering system.

Cylinders on which the identification number has become obliterated have occasionally been received at the factory for reconditioning. It is apparent that these numbers, which are stamped on a pad on the intake rocker box, were

effaced when sand blasting the cylinder head.

It is recommended that this pad be protected by a covering of several thicknesses of masking tape or similar material during sand blasting operations.

WRIGHT AERONAUTICAL CORPORATION

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: INSPECTION OF PISTON PINS

Bulletin No. W-32

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 30, 1944

This bulletin supersedes Service Bulletin No. 515, dated March 17, 1942
so that it may be included in the new numbering system.

Cracks in the inner surface of a piston pin may result in progressive fatigue failure of the part if it is installed in an engine.

During overhaul, after the outer surface of a pin has been magnetically inspected, it is recommended that the pin be redipped and that the

inner surface be carefully inspected. Use a dental mirror for this inspection.

If the inspection indicates a questionable surface condition, remove the pin from service and if practicable, return it to the Wright Aeronautical Corporation, Paterson, New Jersey, for further inspection.

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

A Division of Curtiss-Wright Corporation

PATERSON, NEW JERSEY, U. S. A.

PRINTED
ON
COPRA

S E R V I C E B U L L E T I N

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

TITLE: ORDERING OF TOOLS

Bulletin No. W-34

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: December 30, 1944

This bulletin supersedes Service Bulletin No. 532, dated June 17, 1942
so that it may be included in the new numbering system.

Tool orders are occasionally received which list detail tool numbers. A tool consisting of several individual parts should be requested as a unit without reference to detail numbers.

To cite an example, an overhaul manual or service bulletin may describe a rework operation requiring the use of Tools No. 800000-1, 800000-2, 800000-3, and 800000-4. When these tools are requested, the order should list only Tool No. 800000. Parts of a tool, such as Tool No. 800000-2, will not be furnished separately.

Publications incorporate these detail numbers in rework instructions solely to aid in the complete description of each of the several steps of an operation.

In some cases reference is made to a set of tools comprising details having different basic tool numbers, that is, the details are not identified by dash numbers. The tool number of the set of tools is given for ordering purposes, and the tool numbers comprising the set are listed. These tools may be ordered separately since some of them may already be in the possession of the operator.

Because of the present demands on the tool industry, some delay may be experienced in procuring rework tools. However, the necessary drawings for fabricating tools, except for vendors' proprietary items, may be procured from the Wright Aeronautical Corporation in cases of emergency.

W R I G H T A E R O N A U T I C A L C O R P O R A T I O N

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: ELASTIC STOP NUTS

Bulletin No. W-35A
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: March 7, 1945

This bulletin supersedes Service Bulletin No. W-35, dated January 18, 1945,
in order to present additional information.

When using Elastic Stop Nuts, observance of the following recommendations is required:

1. Wright Aeronautical Corporation 2087D and 4040D series Elastic Stop Nuts are the only type that have been approved for use by Wright Aeronautical Corporation.

2. One full thread of the bolt, stud, or cap screw must protrude beyond the end of the fiber insert to insure proper locking. When this can not be accomplished either a thinner washer or some other type of nut must be used.

3. After repeated use, Elastic Stop Nuts tend to lose their locking effectiveness. Nuts which thread on the bolt so easily as to indicate that the self-locking feature is less than full strength must be replaced with satisfactory nuts. Re-use of an Elastic Stop Nut should be governed by the minimum torque required to turn the nut on a bolt, stud, or cap screw before it takes up its normal tightening action. This minimum torque for determining the gripping power of the fiber inserts is tabulated below for fine thread nuts:

| Size | Torque In. Lbs. Minimum |
|---------|-------------------------|
| 10-32 | 0.95 |
| 1/4-28 | 1.8 |
| 5/16-24 | 3.2 |
| 3/8-24 | 5.2 |

| Size | Torque In. Lbs. Minimum |
|---------|-------------------------|
| 7/16-20 | 7.4 |
| 1/2-20 | 10.3 |
| 9/16-18 | 13.5 |
| 5/8-18 | 18.0 |
| 3/4-16 | 27.5 |

4. Elastic Stop Nuts are subject to the following limitations of usage.

They will not be used:

a. On internal engine parts, or where nuts could enter the engine if they became loose.

b. On loose studs, such as fuel pump and tachometer housing attaching studs.

c. On cylinder hold-down studs.

d. When the maximum operating temperature of the stud is over 121°C (250°F).

e. When the threads of the stud are in such condition that tearing of the fiber insert may result. The presence of drilled locking holes in the stud does not prevent the use of Elastic Stop Nuts unless their fiber inserts might be damaged by burrs or rough edges around the locking holes. This condition can be corrected by polishing or filing as necessary.

5. The tightening torque values given for conventional nuts are applicable to Elastic Stop Nuts.

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: IGNITION MANIFOLD DRAIN HOLES—PROVISION OF

Bulletin No. W-36
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: February 2, 1945


This bulletin supersedes Service Bulletin No. 525 dated April 30, 1942,
to correct the information contained therein.

On engines of recent production, ignition manifolds which are neither pressurized nor plastic filled are provided with a 3/32 inch drain hole in each end plate. This hole is located 1/8 inch from the bottom of the plate on its vertical center line and provides drainage for moisture resulting from condensation. To avoid possible moisture damage to the wiring, it is recommended that all ignition manifolds which are not plastic filled or pressurized be provided with similar drain holes.

PROCEDURE Center punch the end plate at the drain hole location, see sketch. Install a stop collar about 1/8 inch from the tip of a No. 42 drill and drill through the end plate at the point marked by the center punch. The stop collar, installed on the drill, prevents the drill from extending too far into the manifold and causing damage to the wires. When drilling, hold the drill at a 90 degree angle to the end

plate. Drill the opposite end plate in a similar manner.

This rework can be performed at any time whether the harness is on or off the engine. If the harness is on the engine, use either a spanner or a strap wrench to loosen the ignition manifold coupling nut. Loosen the brackets which secure one section of the manifold ring to the engine. The end of this section can then be swung out so that the drill can be held at the required 90 degree angle. After performing the rework on this section of the manifold ring, tighten the brackets which secure it to the engine. Repeat this procedure in reworking the other manifold end plate. Secure the manifold coupling nut by drawing it up as tightly as possible without deforming the manifold ring. Tighten the screws holding the manifold brackets to the crankcase front section using the torque value shown in the Table of Limits.



S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CLEANING OF ENGINE PARTS

Bulletin No. W-37
Page 1 of 2

MODELS AFFECTED: Whirlwind—All

Date: February 16, 1945

This bulletin supersedes Service Bulletin No. 437, dated November 26, 1940,
to correct and add to the information contained therein.

CLASSIFICATION OF METHODS

Cleaning methods may be classified under two general headings—chemical cleaning, and mechanical cleaning. Chemical cleaning depends upon various emulsification, reaction, or dissolution principles while mechanical cleaning includes all operations that accomplish the physical removal of foreign matter through the use of abrasives, brushes, or cutting tools. Usually a combination of both methods will be necessary to clean a given part satisfactorily.

CHEMICAL CLEANING

Chemical cleaning, preceding mechanical cleaning, is employed to wash away oil and grease, and to remove or soften hard deposits of foreign material.

Primary Washing—Primary washing should be accomplished with Varsol, or a similar solvent conforming to Aeronautical Material Specification No. 3160, in a ventilated spray booth equipped with a pressure gun. In many cases it is possible to use Varsol salvaged from more critical cleaning operations further along the overhaul sequence.

1. If the engine is exceptionally dirty, wash the exterior before overhaul disassembly.

2. After disassembly, wash the individual parts to prevent unnecessary contamination and weakening of the degreasing and carbon softening compounds used in subsequent cleaning operations.

Vapor Degreasers—Vapor degreasers utilize the condensation principle. Vapors, rising from a tank of trichloroethylene heated to 86°C (188°F), condense on the cooler engine parts suspended over the tank and provide an effective **degreasing** and paint stripping action. This action ceases when the parts reach the temperature of the vapors. A special tank, designed for trichloroethylene degreasing, is necessary and adequate shop ventilation must be provided to protect personnel. Trichloroethylene is not effective on dirt or carbon but is a very satisfactory agent for removing preservative compounds.

1. Suspend the parts over the tank until they are degreased or until the parts reach the temperature of the vapors and the **degreasing** action ceases.

2. If further **degreasing** action is needed, cool the parts and again suspend them in the degreaser.

3. Allow the parts to drain thoroughly before removing them from the unit.

General Cleaning and Carbon Softening—Commercial cleaning agents such as Gunk 70 or Gerlach 77, have been found satisfactory when used in a tank heated to 60°C (140°F) with steam coils. Lower temperatures prolong the cleaning period, while higher temperatures result in uneconomical evaporation.

1. Immerse steel parts in the cleaning tank for two to three hours.

2. Limit the immersion period of aluminum or magnesium parts to 20 to 30 minutes.

3. Immerse all parts completely to prevent slight lines of corrosion at the point where parts project above the surface of the cleaning fluid.

MECHANICAL CLEANING

Mechanical cleaning, following the degreasing and carbon softening procedures, has a twofold purpose. First, it removes carbon deposits and discolorations that did not respond to chemical cleaning. Second, the surfaces of the parts are restored to their original clean and polished condition. Whatever the means of mechanical cleaning used, wash away all traces of dirt and cleaning materials with a Varsol spray or rinse before the parts are assembled.

Gritblasting—During gritblasting operation, adequate protection must be provided for running or mating surfaces such as piston skirts, cylinder barrel interiors, valve stems, and rocker box cover pads. Studs and threaded areas should never be gritblasted.

1. Use only enough air pressure to clean the parts satisfactorily.

2. Gritblast cylinder heads, piston interior surfaces, and valve heads with Alundum 80-90 grit.

Grain Blasting—Blasting with cracked wheat offers an alternate method for cleaning piston ring grooves. If dampness prevents satisfactory blasting, it is recommended that a small steam coil be installed within the wheat hopper.

Machine Cleaning—This type of cleaning is used only for piston ring grooves and must be performed with utmost care. The tool must be accurately shaped and so handled as to avoid any gouging or damage

to the ring lands, the grooves, or the slight radius at the bottom of the groove.

1. Chuck the piston in a lathe.
2. Use a well supported tool to remove all carbon accumulations from the ring grooves. Do not remove any metal.

Wire Brush Cleaning—Brush wheels should be used for polishing and to remove engine varnish or carbon from parts that cannot be grit-blasted.

1. Protect cylinder barrel or other running surfaces from contact with wire brushes.
2. Use a special narrow wire brush to remove carbon from the inner groove of the cylinder barrel to cylinder head joint.

3. Never use a wire brush in such a manner as to leave marks on the surface of the part.

4. Use a ten inch Tampico fiber brush wheel in conjunction with 3M polishing compound for general polishing.

Polishing—Use crocus cloth and Varsol for fine polishing.

Cloth Wiping—This is the only cleaning recommended for master rod bearings which must be protected with plugs or covers to prevent damage from chemical or mechanical cleaning agents.

1. Wipe the bearing gently with a clean soft cloth and Varsol.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CARBURETOR MANUFACTURERS' BULLETINS

Bulletin No. W-38

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: February 23, 1945

This bulletin supersedes Service Bulletin No. 569, dated December 30, 1942 so that it may be included in the new numbering system.

It is recommended that Service Bulletins and instructions of the various carburetor manufacturers be followed as closely as possible in the servicing of their respective products. These bulletins are issued in co-

ordination with the Wright Aeronautical Corporation and bear Wright approval before they are released.

WRIGHT AERONAUTICAL CORPORATION

A Division of Curtiss-Wright Corporation
PATERSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PISTONS—STAMPING FOR IDENTIFICATION

Bulletin No. W-39
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: February 26, 1945

This bulletin supersedes Service Bulletin No. 561, dated December 2, 1942,
so that it may be included in the new numbering system.


GENERAL

Part numbers, engine numbers, and cylinder location numbers stamped on piston domes may become illegible after repeated cleaning of pistons which have been in service for more than one overhaul period. Unnecessary stamping must be avoided, but data which is required should be restamped in accordance with instructions given herein. When it is necessary, the compression ratio may be stamped on the piston dome as shown in the sketch. The weight of a piston is no longer stamped on the piston dome although this was a practice prior to 1939.

PROCEDURE

Locate the numbers about 1/2 inch from the outer edge of the piston, midway between the valve recesses. Use a metal stamp with 1/8 inch numbers. Impress the numbers on the dome just deep enough to be legible. Stamp the data facing the front of the piston, in the order shown in the sketch included in this bulletin. Do not stamp identification numbers on either of the piston pin bosses or in the center of the piston dome.

Clean piston domes carefully so that a minimum of restamping is necessary.



WRIGHT AERONAUTICAL CORPORATION

A Division of Curtiss-Wright Corporation
PATRSON, NEW JERSEY, U. S. A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: VALVE GUIDES—CHANGES IN INSTALLATION OF

Bulletin No. W-40

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: March 5, 1945

It is the purpose of this bulletin to revise the temperature to which a cylinder is heated when installing valve guides, and to establish new limits for checking the seating of valve seat inserts.

Valve guides will be removed and installed in accordance with existing instructions except that cylinders will be heated in an oven or with a torch to 232° to 260°C (450° to 500°F) for the installation operation. When using a torch, keep rotating the cylinder while applying the heat and keep a constant temperature check with a pyrometer fastened to either of the top spring seats. When the pyrometer registers a temperature approaching that required, direct the flame through the valve port and rocker box to apply localized heat to the guide boss.

Immediately after installing a new valve guide, check the seating of the intake and exhaust valve seat inserts. A seat insert that has dropped to the maximum allowed will permit a .002 inch feeler gage to fit snugly at any one location. A seat insert that has dropped to .015 inch must be tapped into place after the cylinder is heated to 260°C (500°F). If the insert has dropped more than .015 inch, install a new insert in accordance with existing instruction.

When a new valve seat insert is to be installed, heat the cylinder for 60 minutes in a 316°C (600° F) oven.

When it is necessary to install both a valve guide and a valve seat insert, heat the cylinder for 60 minutes in a 316°C (600°F) oven.

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: TESTING OF SPARK PLUGS

Bulletin No. W-41

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: March 7, 1945

This bulletin supersedes Service Bulletin No. 384, dated September 22, 1939, so that it may be included in the new numbering system.

Booster magnetos or spark coils should not be used for the bomb testing, core testing, or other electrical testing of mica insulated spark plugs. Booster magnetos will not provide sufficient voltage for continuous sparking at the pressures desired for bomb testing. Spark coils will not give a reliable indication of spark plug condition, and may cause damage to the mica insulation.

It is recommended that an aircraft magneto that is

in good condition be used for testing spark plugs. The magneto should be driven at a speed which will provide approximately 1,000 sparks per minute.

When a magneto is used for testing, all magneto distributor block terminal leads not in use for the test should be connected to one spark gap. This will discharge the potential built up in these leads and will eliminate the possibility of damage to the magneto.

WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTIS-WRIGHT CORPORATION
PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

**TITLE: VALVE TAPPET AND GUIDE—RECONDITIONING
AND INSPECTION OF**

**Bulletin No. W-42
Page 1 of 1**

MODELS AFFECTED: Whirlwind—All

Date: March 24, 1945

This bulletin supersedes Service Bulletin No. 520, dated May 26, 1943,
so that it may be included in the new numbering system.

During inspection and reconditioning of valve tappets and guides, care should be used to avoid conditions that may result in seizure between the two parts.

Inspect the tappets and guides for cracks and for scoring on the mating surfaces. Scored or scratched parts that cannot be cleaned up by light polishing, should be scrapped. Aloxite No. 320 polishing cloth and H41 fine finishing compound, or their equivalents, are recommended as suitable polishing material. These materials may be obtained from the Carborundum Corporation, Niagara Falls, New York.


A draw bar or similar device for holding the tappet in a lathe is recommended for polishing the tappets. Make a hand polishing tool similar to that shown in figure 1. Line this cylindrical inner surface of the tool with polishing cloth and clamp the tool around the tappets as it is rotated in the lathe. The inside

diameter of tappet guides may be polished by mounting a suitable plug in a lathe chuck. Provide a slot in the plug in which to anchor the polishing cloth. After polishing insure that all sharp edges around the roller slot of both tappet and guide are broken.

Do not stone either the tappet or guide to remove scratches or scores. Small flats or irregularities thus formed may cause a seizure of the tappet in the guide.

The outside diameter of the tappet and the inside diameter of the tappet guide should be measured with a telescope gage and a micrometer caliper. When taking these measurements on the tappets check the outside diameter at three different locations rotating the part 90 degrees. Record these measurements. A tappet which is found to be .0005 out-of-round must be replaced.

Consult the Table of Limits for the proper operating clearances for these parts.



**TAPPET
POLISHING TOOL**

Figure 2

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: INTAKE VALVES—INSPECTION OF

Bulletin No. W-43

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: April 13, 1945

This bulletin supersedes Service Bulletin No. 381, dated October 6, 1939,
so that it may be included in the new numbering system.

It is recommended that all intake valves be given a magnetic type inspection before they are installed in an engine. Perform this operation as instructed by the equipment manufacturer.

Recheck the valve for minute cracks. Carefully examine the entire surface. Use a binocular microscope at ten diameters for this purpose. If cracks, no matter how small, are present discard the valve.

WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTISS-WRIGHT CORPORATION
PATERSON, NEW JERSEY, U.S.A.

PRINTED
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CARBURETOR FLOW BENCH LIMIT—DEVIATION IN

Bulletin No. W-44

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: April 30, 1945

GENERAL

Current flow bench limits on all carburetors allow a two percent plus or minus variation. This tolerance is used by the carburetor manufacturer and Wright Aeronautical Corporation in air box testing all carburetors. This close limit is desirable and in most instances can be maintained, but because of deviations occasionally encountered in the field by overhaul shops and repair stations this bulletin is issued to present a comprehensive explanation.

It is occasionally discovered that overhaul and repair depots which are doing an entirely satisfactory job of overhauling, repairing, and flow testing are not able to get all carburetors to stay within the plus or minus two percent flow bench limits at all points. Other cases have been reported from time to time in which an operator will flow bench test a new or repaired carburetor just received from the carburetor manufacturer or WAC, where it had been air box tested. The flow bench calibration of such a carburetor is not always found to be entirely within

the established limits, which may cause the operator to wonder about the validity of the air box test.

REASONS FOR DEVIATION

The discrepancy lies in the fact that the original calibration of the carburetor was not necessarily in the middle of the allowable limits. The flows may have been on the rich side at some points and on the lean side at others. When an attempt is made to hold the carburetor strictly within limits on a flow bench run, the cumulative correlation errors introduced by minor differences between the air box and the flow bench enter the picture and make it impossible to maintain the desired limits of accuracy. This may occur even if all equipment is in the proper mechanical condition and all work has been properly performed. These errors may be brought about by differences in the flow meter calibration, in the gasoline used and/or differences in the adjustment of the carburetor.

The above factors make it possible for a properly calibrated carburetor to show slight deviations when run on a flow bench although such occurrences are not frequent.

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: VALVE TAPPET GUIDE AND ROLLERS—
IDENTIFICATION AND MATCHING OF

Bulletin No. W-45
Page 1 of 2

MODELS AFFECTED: Whirlwind—All

Date: April 10, 1945

This bulletin supersedes Service Bulletin No. 538 dated July 24, 1942,
in order to bring the information given therein up to date.

GENERAL

When valve tappets, guides, and rollers are assembled, every precaution should be taken to insure that they are properly mated and installed in the correct model engine. Failure to assemble and install these parts correctly may result in an engine failure caused

by insufficient lubrication for the valve operating mechanism.

A reference list of parts is included in this bulletin which will help to identify the correct parts for any given engine.

| Engine Model | SUBJECT PART | | | Used In Cylinder No. | MAY BE USED WITH | | | Identification of Subject Part |
|----------------|-----------------|----------------|--------------------------------|---|------------------|----------------|--|--------------------------------|
| | Tappet Part No. | Guide Part No. | Roller Part No. | | Tappet Part No. | Guide Part No. | Roller Part No. | |
| R760E R975E | 66950 | | | Int. and Exh. 1, 2, 3, 8, 9 Int. and Exh. 4, 5, 6, 7 | 66044 29297 | 116447 | 3.66 inches long, 1-.093 inch hole 1.04 inch from top. | |
| | 41770* | | All | | 29297 | 116447 | Ball socket integral with tappet 3.97 inches long. | |
| | | 66044 | Int. and Exh. 1, 2, 3, 8, 9 | 66950 | | 116447 | 3.54 inches long, 2-.125 inch holes .484 inch from outside flange | |
| | | 29297* | Int. and Exh. 4, 5, 6, 7 | 66950 | | 116447 | 3.53 inches long. No oil holes Inside diameter .6873-.6883 inch (.6873-.6878 inch after shrinking into crankcase) | |
| | | 29297* | All | 41770* | | 116447 | 3.53 inches long. No oil holes Inside diameter .6873-.6883 inch (.6873-.6878 inch after shrinking into crankcase) | |
| | | | All | 66950 41770* | 66044 29297* | | 1.25 inch outside diameter .377 inch inside diameter .236 inch width. | |

* Used on engines with external rocker arm lubrication.

WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTIS WRIGHT CORPORATION
PATERSON, NEW JERSEY, U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PROCEDURE IN DETERMINING THE ACCEPTABILITY OF
NEWLY DEVELOPED AND IMPROVED OILS

Bulletin No. W-46A
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: July 10, 1945

This bulletin supersedes Service Bulletin No. W-46 dated April
30, 1945, to correct and add to the information contained therein.

The procedure outlined below is currently being followed in determining the acceptability of new or improved oils which do not conform to Specification No. AN-VV-O-446a and the latest edition of Wright Aeronautical Specification No. 5815. Lubricating oils which meet the requirements of Specification No. AN-VV-O-446a and the latest edition of Wright Aeronautical Specification No. 5815 are now considered acceptable for use in all Wright engines without preliminary acceptance tests. This change in procedure is a departure from the full scale engine testing of oils which was previously carried on at Wright Aeronautical Corporation. An outline of the acceptance procedure follows:

1. An oil company developing a new or improved oil must make application for the Civil Aeronautics Administration to determine the air-worthiness of an oil and arrange with Civil Aeronautics Administration for the flight test.

2. The Civil Aeronautics Administration will notify the manager of the Technical Data Division of Wright Aeronautical Corporation that the oil is considered air-worthy.

3. The refiner is to notify Wright Aeronautical Corporation of plans for flight service tests. Flight tests must be conducted in at least two engines operating for a period not less than the minimum

period of operation between overhauls currently approved by the Civil Aeronautics Administration. Flight tests on any aircraft engines of comparable power will be considered as a satisfactory basis for acceptance or non-acceptance of the oil.

4. During the period of the service test, the refiner should supply Wright Aeronautical Corporation data relative to the progress of the test and submit used oil analyses obtained during the period of the subject test.

5. Upon completion of the test, a Wright Aeronautical Corporation representative will participate in an inspection of the engine in cooperation with representatives of the refiner, airline, and the Civil Aeronautics Administration. Based upon the results of this inspection and upon the review of the data submitted on the oil, a letter of acceptability or non-acceptability will be forwarded to the oil company by Wright Aeronautical Corporation.

6. In the future, no list of approved or acceptable oils will be published. Since the oils which appeared on the previously published approved list have already demonstrated their acceptability, they will be considered acceptable. However, the Wright Aeronautical Corporation assumes no obligation for any brand of oil which may be considered acceptable.

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: ASSEMBLIES, SERVICE—SALVAGING OF
MODELS AFFECTED: Whirlwind—All

Bulletin No. W-47
Page 1 of 1

Date: May 5, 1945

It is occasionally necessary to make detailed part substitutions in assemblies which have been sent back to Wright Aeronautical Corporation for repair. These substitutions are made on assemblies which have been superseded and are out of production resulting in unavailability of parts required in the assembly. Such substitution results in salvaging many useful assemblies which otherwise would have to be scrapped.

Whenever substitutions are considered, odd detail parts are studied carefully in view of the requirements of the assembly. The detail chosen must be satisfactory in every respect.

Before an assembly containing an odd detail part leaves the factory, it is stamped with an assembly number which was compiled to facilitate recording of the rework done on the assembly. The original assembly number is always used. Incorporated with it are a letter signifying a rework on the assembly and additional numbers referring to the authorization of the substitution. The customer, at any time subsequent to the change in an assembly, must use this newly stamped assembly number whenever referring to the assembly, since it will be through this number that the manufacturer can tell its exact status.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PREPARATION OF ENGINES FOR OPERATION
AFTER STORAGE

Bulletin No. W-48
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: May 17, 1945

This bulletin supersedes Service Bulletin No. 572 dated September 24, 1943, so that it may be included in the new numbering system.

All engines which have been slushed for storage or shipment must be prepared for service as described in this bulletin. The removal of the corrosion preventive must be delayed until it is certain that the engine is to be immediately operated. The entire aircraft oil system should be thoroughly cleaned before the engine is installed. Engines stored or shipped in shipping boxes must be removed from the pliofilm envelope, lifted from the box, and installed in the aircraft. Engines stored or shipped in an aircraft must have the engine cover removed.

Current preparations for storage employ adequate lubricants as corrosion preventives, Aeronautical Material Specifications No. 3070 and 3072. These compounds may be sufficiently removed from the engine by draining.

PROCEDURE

Lubricating Compound

Treat engines which have been slushed with compounds conforming to Aeronautical Material Specifications No. 3070 and 3072 in the following manner:

1. Remove all the dehydrator plugs and bags from in and around the cylinders and the sump.
2. Install the spark plugs.
3. Remove all the moisture resistant seals from the exhaust ports and the vents.
4. Remove, clean, inspect, and reinstall the oil filter and the magnetic sump plug.
5. Reinstall all engine parts which have been removed.

6. Before installing, treat the accessories as recommended by their manufacturers.

7. Pre-oil and start the engine in accordance with current instructions.

8. Operate the engine for 15 minutes at 1000 to 1200 rpm. Remove and inspect the oil filter and the magnetic sump plug for foreign material. Drain the oil from the sump and reinstall the oil filter and the magnetic sump plug. Then add enough fresh oil to replenish the oil supply before further operation.

Non-Lubricating Compound

Former instructions for preparation for storage recommended the use of non-lubricating compounds, Wright Aeronautical Corporation Specifications No. 5840 and 5841, which have a tendency to congeal when cool. Treat engines which have been slushed with these compounds in the following manner:

1. Remove by scraping as much corrosion preventive as possible. Pay particular attention to the removal of the compound from the combustion chambers and intake pipes.
2. Flush all passages with hot oil.
3. After all the non-lubricating compound has been removed, pre-oil and start the engine in accordance with current instructions.
4. Run the engine for 15 minutes at 1000 to 1200 rpm and drain the oil from the entire system.
5. Inspect and reinstall the oil filter and magnetic sump plug.
6. Refill the system with new oil before further operation.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

**TITLE: INSTALLATION OF MISCELLANEOUS CLIPS AND
BRACKETS UNDER CYLINDER HOLD-DOWN NUTS—
AVOIDANCE OF**

MODELS AFFECTED: Whirlwind—All

Bulletin No. W-49
Page 1 of 1

Date: June 1, 1945

This bulletin supersedes Service Bulletin No. 441, dated April 30, 1940,
in order that it may be included in the new numbering system.

It has been the practice of some aircraft manufacturers in some instances in the past to install clips, clamps, supports and other miscellaneous parts under cylinder hold-down nuts.

This practice should be discontinued. The only parts that can with safety be installed under cylinder hold-down nuts are those provided with the engine.

Proper tightening of cylinder hold-down nuts is of the utmost importance. The Wright Aeronautical Corporation has established limits of torque to be used when tightening these parts. The use of extraneous attaching parts under cylinder hold-down nuts may change the normal nut seating condition to such an extent that, although the specified torque be observed with the torque wrench when tightening these parts, actually an abnormal tightening condition may be obtained. Loosening or improper pre-stressing of nuts or uneven loading on the cylinder flange may result from this condition.

The Wright Aeronautical Corporation will not be responsible for failure of an engine or of engine parts as a result of the attaching of extraneous parts under cylinder hold-down nuts other than those provided with the engine.

It is suggested that the following alternate attaching points be employed for parts which may have previously been attached under cylinder hold-down nuts. Approved points of attachment for such parts as propeller de-icing fluid line support clips and propeller governor control line support brackets are crankcase front section attaching studs, and supercharger rear housing attaching studs.

Should some problem arise in connection with the installation of these parts and the operator is unable to find a solution, the Service Division of the Wright Aeronautical Corporation will analyze the problem and suggest a solution for that specific installation upon request.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: STARTER SHAFT OIL SEAL AND RETAINER—
REPLACEMENT OF

Bulletin No. W-50
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: June 8, 1945

This bulletin supersedes Service Bulletin No. 502 dated January 28, 1942, so that it may be included in the new numbering system.

GENERAL


A new duprene oil seal, part No. 2083D30, has been designed to replace the cork seal, part No. 23480, which, in a few instances, has caused leakage of oil into the diffuser section. This leakage was the result of a permanent set taken by the cork after a few hours of engine operation.

At next overhaul, install the new oil seal, part No. 2083D30. This cannot be done, however, without replacing the retainer, part No. 23484, with part No. 114732. If it is desired, part No. 23484 may be reworked to the dimensions of part No. 114732 and installed satisfactorily with the new oil seal.

REWORK:

Shorten the flange of part No. 23484 to the dimensions given. See figure 1.

1. Chuck the flange in a lathe.
2. Check run-out with dial indicator. A maximum of .010 inch is permissible.
3. Remove the necessary amount of material from the flange face and maintain the radius specified.
4. Break all sharp edges, and give the part a careful visual inspection when finished.



S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: OIL SEAL, CRANKSHAFT, 8-RING TYPE—
INSTALLATION OF

Bulletin No. W-51
Page 1 of 1

MODELS AFFECTED: Whirlwind R760E and R975E Series
Engines which employ 2-Position
Hydro-Controllable Pitch Propeller
Operating Parts in Governor Drive
Type Crankcase Front Section

Date: June 15, 1945

This bulletin supersedes Service Bulletin No. 407, dated May 14, 1940,
so that it may be included in the new numbering system.

GENERAL

Some of the above models of Whirlwind engines employing 2-position hydro-controllable pitch propeller operating parts in a propeller governor drive type crankcase front section were originally provided with a crankshaft oil seal having seven rings. One

ring of this seal partially obstructs one set of oil distributing holes in the crankcase front section sleeve. In engines where trouble caused by this condition has been experienced, it is recommended that the 7-ring type crankshaft oil seal be replaced with an 8-ring type seal at next overhaul.

| Part Name | Part No. | Quantity Per Engine | |
|--|----------|---------------------|--------|
| | | Install | Remove |
| Adapter, Crankshaft | 65271 | | 1 |
| Gear, Crankshaft Propeller Governor Drive..... | 64332 | 1 | |
| Key, Crankshaft Propeller Governor Drive Gear... | 7-D-17 | 1 | |
| Ring, Crankshaft Oil Seal | 5015-D-6 | 8 | 7 |

The crankshaft propeller governor drive gear, Part No. 64332, is designed for use in propeller governor drive type crankcase front sections employing either a propeller governor or a 2-position

hydro-control. When a propeller governor is used, the crankshaft gear drives the propeller governor drive intermediate gear.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: SLOT-HEADED PLUGS—REMOVAL OF

Bulletin No. W-52
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: June 15, 1945

Some difficulty has been experienced in removing slot-headed plugs because the standard tapered shank screwdriver is not adapted for this purpose.

The tapered shank screwdriver may slip and mutilate the plug. When this happens it will be necessary to employ other means to accomplish the removal. Any standard commercial plug remover of proper size is suitable for this operation.

For satisfactory removal of these subject plugs hol-

low grind the shank of any suitable tapered shank screwdriver as shown in the drawing. This will enable the blade of the screwdriver to grip the bottom of the plug slot, reducing the possibility of slippage when torque is applied.

Rework

Any standard tapered shank screwdriver of suitable size and thickness may be reworked by hollow grinding the shank as shown in the drawing.




Figure 1

WRIGHT AERONAUTICAL CORPORATION

A DIVISION OF CURTISS-WRIGHT CORPORATION

PATERSON, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: TRANSFER OF ENGINES FROM SURPLUS STOCK
TO LICENSED OPERATION

Bulletin No. W-53
Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: June 30, 1945

With the transfer of engines from surplus stock to licensed operation the desirability of incorporating certain design changes recently released is becoming apparent.

In order to insure the most satisfactory operation of these engines, Wright Aeronautical Corporation feels that certain requirements should be met before they are placed in licensed operation. It is recommended that any engines which may be procured from surplus stock for use in licensed aircraft be subjected to a complete overhaul including overhaul of the accessories. The overhaul is recommended for new and used engines and should be performed by a factory approved overhaul shop. Experience has proven this to be necessary as assurance that the in-

ternal parts of the engine are in good condition and also to ensure that they are not affected by corrosion which has a tendency to develop during long periods of inactivity in spite of precautionary preservation measures that may have been taken.

It is further recommended that certain parts which are of latest design be incorporated in these engines during this overhaul. A detailed list of these items is available for the various engine models and can be obtained upon request.

It is therefore recommended that operators who procure any of these engines consult the Wright Aeronautical Corporation for recommendations applicable to the specific engines involved.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

**TITLE: METHOD OF SELECTING OVERSIZE
WEDGE-TYPE PISTON RINGS**

Bulletin No. W-54
Page 1 of 2

MODELS AFFECTED: Whirlwind—All

Date: July 19, 1945

This bulletin supersedes Service Bulletin No. 418, dated August 9, 1943,
in order to include revised piston ring side clearances.

The correct piston ring to be used during assembly is identified through the use of special ring gages. The purpose of this bulletin is to describe the construction of these gages and the method of using them.

Examine all gages now in use to ensure that the width of the ring segment and the oversize indicated on the gage correspond to the values given in the table. This is necessary in order to conform to the latest recommendation on piston ring side clearance.

GAGE CONSTRUCTION

Select the oversize rings listed below. Cut a section that bears no oversize markings from each ring and construct a gage to the dimensions shown in figure 1. Drill two holes in the ring section with a No.

55 drill and solder a 16-gage wire to the ring section for a handle. Fold a piece of metal around the handle as shown in order that each tool may be identified.




Figure 1

PISTON RING

| Part No. | Oversize | Ring Width ±.0003 In. | Stamp Gage Handle |
|-----------|------------------|--------------------------|----------------------|
| 112213Y2 | + .004 in. width | .124 in. | Use std ring |
| 112213Y3 | + .006 in. width | .126 in. | Use +.002 in. ring |
| 112213Y4 | + .008 in. width | .128 in. | Use +.004 in. ring |
| 112213Y5 | + .010 in. width | .130 in. | Use +.006 in. ring |
| 112213Y20 | + .010 in. width | .132 in. | Use +.008 in. ring |
| | + .015 in. OD | | |

It is important that the section of piston rings used as gages be of the exact width mentioned in the tables. This measurement is taken at the widest portion of the ring.

The size of the ring used in making the gage indicates the size of the groove and not the oversize of ring to be selected. Be guided in selecting the ring by the information stamped on the handle of the gage.

PROCEDURE

Select a gage that fits flush or nearly flush with the land and check the width of the No. 1 groove at locations directly under the valve recesses in the head of the piston. Then check at the two additional points

90 degrees from these positions. If the width of the groove varies more than .002 inch, if the gage bottoms in the groove and rocks perpendicularly to it, or if the groove side faces are not parallel to the outer edge of the gage when visually inspected, remachine the groove. Refer to the Service Bulletin on remachining instructions.

If the groove is in good condition or if it has been remachined, select the largest size gage that will fit tightly in the piston groove without projecting beyond the lands, and install the appropriate ring to fit the designated groove. The ring gage will indicate the correct oversize width ring.

If the .008 inch oversize ring gage is a loose fit when flush with the lands as mentioned above and the

groove is not beyond service limits when checked with a snap gage, tool No. 802263, use a .010 inch oversize width ring.

Follow the procedure outlined above and inspect

and measure all the grooves that accommodate wedge-shaped rings. *The outer surface of a ring correctly fitted to the groove fits below the lands and does not protrude beyond them.*

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: PRE-FLIGHT IGNITION CHECK

Bulletin No. W-55

Page 1 of 1

MODELS AFFECTED: Whirlwind—All

Date: July 23, 1945

GENERAL

The ignition system should be checked to insure proper functioning, prior to take-off, as described below.

PROCEDURE

Throttle and Propeller Governor Adjustment—
With the mixture control in the full "RICH" position and the governor control in the full "INCREASE RPM" position, adjust the throttle to give 28 to 30 inch Hg manifold pressure. DO NOT EXCEED 30 inch Hg manifold pressure.

CHECK FOR RPM DROP

Note the rpm as the engine operates with the ignition switch in the "BOTH" position. Then, without changing the throttle setting, operate the engine with the switch in the "LEFT" position just long enough to note the rpm drop (a matter of seconds). Return the ignition switch to the "BOTH" position to permit the engine speed to stabilize. Repeat this procedure for the "RIGHT" position. This check should be made in as short a time as practicable and should not extend over 15 seconds. Atmospheric conditions will influence the readings obtained; however, a drop of 75 rpm or less is considered normal providing no engine roughness is encountered.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: SERVICE LIMITS FOR ANTI-FRICTION BEARINGS

Bulletin No. W-56A
Page 1 of 4

MODELS AFFECTED: Whirlwind 7 and 9

This bulletin supersedes Service Bulletin No. W-56, dated April 5, 1946, to include additional information.

Date: May 20, 1947

The purpose of this bulletin is to establish general limits which may be used for inspection of anti-friction bearing surface conditions during engine overhaul. While it is impossible to establish definite limits of acceptability on these parts, the illustrations and descriptions are guides to help the inspector.

Limits specified herein for ball or roller paths also apply to balls and rollers. Superficial pitting not exceeding $\frac{1}{8}$ inch in length across the track is acceptable on three rollers. Superficial pitting, on three balls, not exceeding $\frac{1}{8}$ inch in any direction is acceptable.




Figure 1—Pitting. The concentration of pitting illustrated on the roller path is acceptable on all surfaces, provided the pits are small in relation to the width of the bearing path.




Figure 2—Pitting. The illustration shows lines of closely spaced pits and some formless stains across the roller path. Because of the lines of pits, this bearing should not be used. Staining as a discoloration only has no effect on bearing performance and can generally be cleaned up by using crocus cloth or equivalent.




Figure 3—Pitting. In this illustration, the band of pits across the ball or roller path prohibits the use of the bearing.




Figure 4—Pitting. This illustration shows many relatively large pits which prohibit the use of this bearing.



Figure 5—Pitting. Two such concentrated pitted areas within the area shown by the illustration shall be considered the limit of acceptability on ball or roller paths. On all other surfaces four such areas shall be considered the limit of acceptability. Pits no larger than shown but dispersed shall be acceptable on any surface.



Figure 6—Pitting. One even larger pit as large as shown by the illustration shall be the limit of acceptability on ball or roller paths. Acceptable as shown on all other surfaces.




Figure 10—Manufacturing Flaws. A race having magnetic or visual indications due to non-metallic inclusions as illustrated shall be rejected if the length of any one indication on the roller path or ball groove exceeds $1/8$ " or if the sum of the lengths of all indications exceeds $3/8$ "; or, if the length of any indication on any other surface of the race exceeds $3/8$ " or if the sum of the lengths of all indications exceeds 1". If more indications than one are present they must be separated by at least 1".



Figure 11—Spalling. The illustration shows bearing races exhibiting spalling in its early stages. Spalling in any stage prohibits the continued use of the bearing.

WRIGHT AERONAUTICAL CORPORATION
 A DIVISION OF CURTIS-WRIGHT CORPORATION
 WOOD-RIDGE, NEW JERSEY, U.S.A.

EX-115
 U.S.



Figure 7—Dents. The large dent is not acceptable on ball or roller paths or on the inside surfaces of roller bearing flanges, and is the limit of acceptability on all other surfaces. The small dent is acceptable on all surfaces.



Figure 8—Dents. Acceptable as a limit with regard to size and concentration on balls, rollers, and ball or roller paths. These dents are caused by metallic particles passing through the bearing.



Figure 9—Polishing Marks. Two scratches twice as long as shown, within the area illustrated, shall be the limit of acceptability on ball or roller paths or on inside faces of roller bearing flanges. Four marks twice as long as shown shall be the limit of acceptability on all other surfaces.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: SPARK PLUGS, INSTALLATION RECOMMENDATIONS

Bulletin No. W-57

Page 1 of 1

MODELS AFFECTED: Whirlwind 760E and 975E

Date: May 7, 1946

Service Bulletin No. 351 which was previously cancelled is hereby reinstated so that these instructions will be available to new operators.

The thickness of solid copper spark plug gaskets and washer type spark plug thermocouples should be within .068 inch minimum and .095 inch maximum. A thinner gasket or thermocouple washer will allow the spark plug to be screwed too far into the cylinder thereby exposing the bottom threads to the gases in the combustion chamber. This will result in overheating of the plug, which may cause detonation, and will make spark plug removal more difficult by allowing carbon to accumulate on the exposed threads.

The Wright Aeronautical Corporation does not

recommend the use of copper-asbestos spark plug gaskets.

Spark plugs shipped from the factory with new or overhauled engines are protected from corrosion with a preservative compound. Before these plugs are tested or installed in an engine it is recommended that they be washed with a good grade of clear gasoline. The plugs should then be dried thoroughly before installation. The use of compressed air for this purpose should be avoided due to the moisture in the air.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: FUEL, USE OF CORRECT OCTANE

Bulletin No. W-58
Page 1 of 1

MODELS AFFECTED: Whirlwind 7 and 9

Date: May 17, 1946

Engines should usually operate on the grade of fuel specified in the engine specification and on the engine data plate. However, if fuel of the recommended octane rating is not available, it is permissible to use a fuel of higher octane. Under no circumstance should a fuel of lower octane rating be used.

Since higher octane fuels are aromatic to a greater

degree and since aromatics have a detrimental effect on rubber and artificial rubber components of a fuel system, caution should be exercised in the use of higher octane fuels than specified until the fuel system has been determined suitable for use with aromatic fuels.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: VALVE TAPPET GUIDE—REWORK OF SLOT

Bulletin No. W-59

Page 1 of 1

MODELS AFFECTED: Whirlwind 7 and 9

Date: May 29, 1946

Service Bulletin No. 547 which was previously cancelled is hereby reinstated so that the rework recommended herein may be incorporated in surplus military engines converted to commercial use, if such rework has not already been accomplished.

To prevent valve tappet seizures, the blend between the roller slot and the inside diameter of the valve tappet guide has been increased to a .030 inch radius. It is recommended that guides which do not incorporate this change be reworked during the next overhaul as described below. Check for sharp edges both visually and by running the fingers over the reworked portions of the guide. The surfaces must be perfectly blended and have no sharp edges.

PROCEDURE

1. Use a 3/8 inch ball type abrasive wheel (Norton 38120 or similar) in a small high speed hand grinder, and with the abrasive wheel inserted in the roller slots, as illustrated in figure 1, break the sharp inside edges of each valve tappet guide slot.




Figure 1




Figure 2

2. When a guide incorporating a flat at the blind end of the slot is being reworked, it will be necessary to break the edge of the flat and the adjacent radius with a strip of No. 240 abrasive cloth used as shown in figure 2.

3. Blend and smooth the surfaces reworked above into the tappet guide bore and slot by using a folded strip of No. 320 abrasive cloth held in a slotted arbor and bent back to create a "butterfly" or pointed grinding surface. The arbor is driven by a high speed hand grinder and used as shown in figure 3. To prevent the valve tappet bore from being damaged by the abrasive cloth during this operation, a soft metal shield should be constructed with an opening approximately 1/16 inch larger than that of the slot being reworked and inserted in the tappet guide bore. Care should be taken in inserting and removing the shield to avoid scratching the guide bore.




Figure 3

4. Polish the inner surfaces of the tappet guide with crocus cloth mounted on a split arbor driven by a high speed lathe as shown in figure 4.




Figure 4

WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTISS-WRIGHT CORPORATION
WOOD-RIDGE, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: RECONDITIONING OF PISTON RING GROOVES

Bulletin No. W-60

Page 1 of 2

MODELS AFFECTED: Whirlwind--R760E and R975E

Date: June 5, 1946

This bulletin supersedes Service Bulletin No. 375, dated September 27, 1943, to incorporate up-to-date information.

GENERAL


Service reports indicate that considerable difficulty exists in the field in reconditioning piston ring grooves, particularly those which are wedge shaped. It is the purpose of this bulletin to establish new reconditioning procedures to alleviate the existing difficulty, thereby increasing the life of both piston and piston rings.

Ring grooves are numbered in consecutive order starting with the groove nearest the dome of the piston as number 1.

During reconditioning, the depth of a ring groove, both wedge and rectangular shape, must never be increased. After reconditioning, a smooth fillet must be formed between the sides and bottom of a groove regardless of its shape.

Special Tools Required

| Name | Tool No. |
|-----------------------------|----------|
| Lathe Fixture | 801830 |
| Limit Gage | 802263 |
| Grooving Tool | 801097 |
| Grooving Tool Checking Gage | 803720 |



WEDGE SHAPED GROOVES

Clean used pistons by a carbon-solvent bath followed by soft grit blasting and by remachining the sides of wedge shaped grooves to the extent necessary to obtain smooth, flat, and true surfaces. Prior to machining, however, a limit gage should be used on the grooves. If the gage passes through the groove, the piston must be replaced.

Clamp the fixture on the lathe face plate, indicating surfaces "A" to run true within .002 inch full indicator reading. The compound rest must be parallel to the lathe fixture as illustrated. Use parallel blocks to elevate the point of the grooving tool to dead center. Use suitable blocks, clamp, and two bolts as shown, to insure tight clamping along the greater length of the tool. Clamp the tool lightly. Place the gage flat against the fixture and, engaging the tool cutting edges accurately, clamp the tool securely. Insert the draw-in rod through the fixture of the lathe face plate. Place the piston on the fixture and insert the correct dummy pin through the piston pin hole and the eye of the draw-in rod. Clamp the piston into the fixture by tightening the nut at the end of the draw-in rod.

Indicate the outside diameter on the ring land between the second and third grooves from the top and also one side of the bottom groove below the piston pin hole to run true within .001 inch full indicator reading. If necessary, use shims between the piston and fixture.

Arrange the spindle speed for 125 to 200 rpm. Use a suitable cutting oil. Centralize the tool in the top ring groove and advance the tool toward the bottom of the groove as close as possible without touching it. At this point, set the micrometer on

the cross feed at zero. This establishes the maximum depth. Move the carriage so that the tool touches the right-hand side of the groove. Back the tool out of the groove and move the carriage approximately .001 inch to the right, using the micrometer carriage stop. Advance the tool into the groove until the zero cross feed is reached. Repeat this operation until the side of the ring groove is cleaned up.

Leave the tool set to its maximum depth. Clean up the opposite side of the groove in the same manner, maintaining the same maximum depth of the grooving tool. After the groove has been cleaned up, check with the correct maximum limit gage. If the gage passes through the groove, the piston is no longer suitable for service use. However, if the gage does not pass through the ring groove, proceed to recondition, if necessary, the second and third groove from the top, checking each with the maximum limit gage.

The grooving tool is to be ground only on the top and not on the sides. Use the checking gage to insure the correct angle on the tool.

RECTANGULAR SHAPED GROOVES

If side clearance limits are exceeded when a .010 inch oversize ring is installed in a rectangular groove, the piston must be replaced.

Rectangular grooves may be machined with standard commercial cutting tools equipped to provide a .030 inch radius at the fillet. Hold the piston in the lathe fixture as described for pistons with wedge shaped grooves.

The final step is to break all sharp corners lightly before the piston is removed from the lathe.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: IDLE MIXTURE SETTING—
ADJUSTMENT OF

Bulletin No. W-61
Page 1 of 1

MODELS AFFECTED: Whirlwind 7 and 9

Date: July 11, 1946

Service Bulletin No. 536 which was previously cancelled is hereby reinstated and changed to present an improved procedure for idle mixture adjustment.

The carburetor idle mixture setting should be adjusted after each engine or carburetor change, whenever changes in airport altitude or atmospheric conditions require it, or whenever poor idling characteristics indicate the need of mixture adjustment.

Adjustment of Idle Mixture Setting:

Adjust the idle mixture setting in the following manner after a thorough warm-up.

1. With the mixture control in the "RICH" position, adjust the carburetor throttle stop so that the engine idles at 400 rpm. Speeds up to 600 rpm are

permissible but 400 rpm is preferred to give a more sensitive adjustment.

2. Set the idle mixture adjustment to give maximum speed or lowest manifold pressure at this setting.

3. Readjust the throttle stop to gain the original rpm setting and again set the idle mixture adjustment to give maximum speed or lowest manifold pressure.

4. Reset the carburetor throttle stop to give the minimum idle speed desired.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CYLINDERS—TESTING FOR CRACKS OR LEAKS IN

Bulletin No. W-62

Page 1 of 1

MODELS AFFECTED: Whirlwind 7 and 9

Date: July 19, 1946

The hydraulic testing and air testing of cylinders at overhaul is no longer recommended in checking cylinder heads for cracks or leaks. Testing of this nature is performed at the factory during manufacture, thereby precluding the need for further testing at overhaul.

All checking of cylinder heads for cracking should be performed by careful visual inspection. If indications exist which to the eye seem doubtful, light acid etching may be employed.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: SPACER, CRANKSHAFT FRONT MAIN BEARING—TIN PLATING OF

Bulletin No. W-63

Page 1 of 1

MODELS AFFECTED: Whirlwind R760E and 975E

Date: July 19, 1946

This bulletin supersedes Service Bulletin No. 453, dated February 26, 1941, to include it in the new numbering system and to incorporate additional information.

It is the purpose of this bulletin to provide instructions for tin plating of crankshaft front main bearing spacers from which the tin plating is worn. Plate only spacers which are in good condition or which may be reconditioned by light polishing.

Tin Plating Instructions

1. Remove all carbon using a carbon removing cleaner or by polishing with pumice.
2. Degrease using Permachlor or a similar commercial solvent.
3. Electric-clean with a standard electric-cleaner using the spacer as the anode. This will also remove any tin which was on the part previously.
4. Rinse in clean hot water.
5. Rinse in clean cold water.
6. Dip in a cold muriatic solution, 15 percent by volume, until all tarnish is removed.
7. Rinse in clean cold water twice.
8. Tin plate in an alkaline stannate bath using 9 to 1.1 amperes current per spacer. Use 4 to 6 volts and allow the spacer to remain in the bath for approximately one-half hour. The exact time required

to plate to .0003 to .0005 inch must be determined by trial.

9. Rinse in clean cold water.
10. Rinse in clean hot water.
11. Dry in a clean air blast.

The alkaline stannate solution must be 63° to 79°C (145° to 175°F) and is composed as follows:

| | |
|---|--------------------|
| Sodium Stannate | 13 ounces |
| Caustic Soda | 1.25 ounces |
| Sodium Acetate | 2 ounces |
| Hydrogen Peroxide (100 percent volume) | 1/16 fluid ounce |
| Water | To make one gallon |

It is recommended that the alkaline stannate solution be procured from a chemical supply company and its strength be maintained in accordance with their instructions.

If tin plating equipment is not available, the spacer may be returned to Wright Aeronautical Corporation for plating, or a new front main bearing spacer which has been tin plated may be procured for replacement.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: CRANKSHAFT—UNDERCUTTING THREADED SECTIONS ON

Bulletin No. W-64
Page 1 of 1

MODELS AFFECTED: Whirlwind—R760E and R975E

Date: October 22, 1946

This bulletin supersedes Service Bulletin No. 544, dated September 30, 1942, in order that it may be included in the new numbering system.


GENERAL.

To avoid excessive stress concentrations at the sharp corners on the last threads, undercuts are machined behind all threaded sections of crankshafts.

Crankshafts not provided with these undercuts should be reworked as shown in the sketch. Rework may be accomplished in a lathe. Cut the grooves only deep enough to remove incomplete threads. Do not cut beyond the diameter specified. Polish to remove all tool marks and subject the part to a magnetic inspection.

Crankshaft Part No.

| Crankshaft Part No. | A | B |
|---------------------|-------|------|
| 22179 | .875 | |
| 23439 | .875 | .88 |
| 63027 | 1.000 | .88 |
| 64365 | 1.500 | .88 |
| 66943 | 1.000 | .88 |
| 68612 | 1.000 | .906 |
| 112016 | 1.500 | .88 |
| 112130 | 1.500 | .88 |
| 112363 | 1.000 | .88 |



WRIGHT AERONAUTICAL CORPORATION
A DIVISION OF CURTISS-WRIGHT CORPORATION
WOODSIDE, NEW JERSEY, U.S.A.

PRINTED
IN
U.S.A.

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: DEFLECTORS, CYLINDER HEAD AIR-CUSHIONED MOUNTING FOR

Bulletin No. W-65
Page 1 of 1

MODELS AFFECTED: Whirlwind—R760E and R975E

Date: October 22, 1946

This bulletin supersedes Service Bulletin No. 533, dated October 22, 1942, to include it in the new numbering system.

On the above engines, cylinder head air deflector brackets are now attached to the cylinder head with neoprene grommet mountings.

To effect this change:

1. Replace the present bracket with the bracket assembly sketched in figure 1. Attach the brackets to the deflector with three 1/8 inch rivets, part No. 66D19, and washers, part No. 27D130.

2. To provide clearance for the new bracket, profile the first cooling fin below the attaching screw boss on the exhaust side as shown in figure 2. Break and blend all sharp edges.

3. Install the deflector on the cylinder head, using screw, part No. 35D7, which is .938 inch overall length, in place of the present screw, part No. 35D13, which is .781 inch overall length. Lockwire securely. No washer is used with the new screw.




Figure 1




Figure 2

S E R V I C E B U L L E T I N

WRIGHT AERONAUTICAL CORPORATION

TITLE: SPARK PLUG APPROVAL PROCEDURE

Bulletin No. W-66

Page 1 of 2

MODELS AFFECTED: Whirlwind R760E and R975E

Date: May 15, 1943

GENERAL

It is considered desirable to have the engine manufacturer approve all spark plugs prior to general use in his engines. This applies not only to newly designed plugs, but also to previously approved plugs in which major changes have been made.

So that the engine manufacturer may lend full cooperation in supplying his approval, he has established a course of action believed to be acceptable to all concerned. The procedure, currently in effect, is outlined in this bulletin.

CONDITIONS

Engine manufacturer's approval of a spark plug must be obtained prior to the release of any publicity concerning the plug.

The number of plugs to be submitted for service testing, the model engines in which the plugs are to operate and the necessary operating time to complete a service test must be determined by the engine manufacturer. After service test, the engine manufacturer reserves the right to destructively examine ten per cent of all plugs tested.

Approval of a plug does not constitute a guarantee of the plug's performance, and the engine manufacturer will not be responsible for engine malfunctioning or failure due to the use of a plug. Approval of a plug may be withdrawn, in whole or in part, at any time, when in the engine manufacturer's opinion, the plug is not performing as it should.

The engine manufacturer also reserves the right to determine when changes in a previously approved plug warrant a re-valuation of its performance.

NEWLY DESIGNED PLUGS

A newly designed plug is submitted to the engine manufacturer for preliminary study prior to contacting any other party. If it is considered to be potentially satisfactory, he requests permission from the Civil Aeronautics Authority to subject the plug to a service test.

When Civil Aeronautics Authority's permission has been granted, the engine manufacturer notifies the spark plug manufacturer that the plug may be released to Commercial Airlines for limited service operation.

NOTE

A minimum of 250 spark plugs must be supplied to any one operator and the total number of plugs released must not exceed 2000.

Before accepting plugs for service testing the operator should contact the engine manufacturer to learn whether or not he has agreed to a test and in what model engine the test should be conducted. The engine manufacturer promptly supplies this information and, if the plug is to be tried, furnishes the operator with forms on which he may report the results of his experience.

While a trial plug is being tested by an operator, the engine manufacturer's Service Representatives follow its progress. At the first regular plug change, they obtain

SERVICE BULLETIN NO. W-66

one average set of plugs for examination by the Wright Aeronautical Corporation.

Meanwhile, operation of the remaining plugs continues, up to approximately 500 hours. At each regular plug change, one representative set of plugs is returned to the engine manufacturer.

At the conclusion of the test, the entire group of plugs is returned to the engine manufacturer, accompanied by the operator's reports on the plug's performance.

After a complete analysis of all obtainable information, the Wright Aeronautical Corporation either approves or rejects the use of the plug in its engines. If approval is given, the plug may be immediately used in any engines of equal or lower specific power rating as compared to the engine in which the test was conducted. If approval is withheld, the spark plug manufacturer, if he so desires, makes any recommended

changes and resubmits the plug for approval. In this event, the plug may or may not be approved without further service testing. When further service testing is required, the entire procedure as outlined above is followed.

CHANGES IN APPROVED PLUGS

If a previously approved spark plug is to be altered in any way, the contemplated change is discussed with the engine manufacturer at the earliest possible time, and, in any event, before co-ordinating the change with anyone else. When the change is of a minor nature, it is immediately approved. However, when it is felt the change may have an unevaluated effect upon the plug, the engine manufacturer withdraws his approval until satisfactory results are obtained through service testing. In this case, the plug is submitted to the same procedure followed in obtaining approval for a newly designed plug.